

12/01/2020

REF: CS/MSG21000341/R1td3

Special Instruction:

ASS. REC. BY:

SURVEY BY: RASUL

ASSIGNMENT (Office)

Merimen

From (Person): JOWYN TAY

of MSIG

Date/Time: 08/01/2021@ 11.14AM

Estimated Cost:

Bill to:

OD ☒ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGQ 8383U

Insured: SKV 8729H

at Workshop m/s

XIN YUN AUTO

Tel: 9839 1555

of 8 Kaki Bukit Avenue 4, #05-23 Premier

Policy No: 30001429294

Claim No: 251811

Sum Insured:

Excess:

D.O.A. 07/01/2021

Make of Veh:

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 11.29AM@08/01/21

Person Contacted:

XI YING

Vehicle ☒ IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SGQ 8383U-X
	SKV 8729H-X