

ACC. REC. BY:

Steve

REF:

AIG

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. 2070176085

Claims No. 4786331505SG


Sum Insured: _____ Excess: 0/-

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Sent: _____ Consistent? : Yes or No

Est. Repairs: 5 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

 Veh No: SMX 1126J Yr Regn: 28/12/20
 Types: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: KIA Sorento c.c. 2799

Colour: White A/C: Insured / Std / NI / N

Sp. Reading 541 T/Radio: Insured / Std / NI / N

Eng/No: _____

C/No: KIA RTH810VM 596376

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 235/65R18

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Continuum

Front Rear

R/Bal. 4 mm R/Bal. 4 mm

L/Bal. 4 mm L/Bal. 4 mm

D.O.A. 6/1/21 D.O.I. 8/1/21

Survey held at Cycle & Carriage

Des. of Damages: Frl / Rear / O/S / N/S / U/C / Rooftop or

Rear RM.

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-148K

08/01/21 @ 5.03pm revert to AIG via Merimen

12/01/21 @ 10.42am Kok Chong informed C/A via Merimen.

12/01/21 @ 4.26pm Informed Kevin C/A & ex: \$0/- by email.

14/04/21 @ 10.10am confirmed with Ms Loi final fig \$5058.80, 5 days. (Red \$2618.40, 34%)

Date/Time, File, Pass to?

☐ : Prel. Report☐ : Final Report

Date/Time, File Return to?

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Days Of Repair: 5

Resurvey No. of Trip: 2

Survey Fee:

Transportation:

\$ + RS, \$

Phone

Others

TOTAL

Approved: MER-OD

Lum Sum / I.E.I. fig 5058.80



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13651/TAN KIAN SIONG (CHEN JIANXIONG) Reg No/Reg Date SMX1126J / 28/12/202 Date In/Mileage / 0 Chassis No KNARH81BVM5066376 Engine No D4HELH262447 Make/Model KIA/SORENTO 2.2 A D SX SR G898 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	08/01/2021/ 09:27	QUK	282 / Kevin Leong	26959		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE REAR RH DOOR, REAR BUMPER LOWER & AFFECTED AREA REPAIR ON REAR BUMPER & REAR RH FENDER				499x1			409 1600.00
E PNT98000 PAINT WORK ON REAR BUMPER, REAR RH FENDER & REAR RH DOOR							1050.00
E PNT98000 PAINT WORK ON REAR BUMPER, REAR RH FENDER & REAR RH DOOR							1050.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST							120.00
M SUNDRY PERFORM RUST PREVENTION							80.00
E PNT88000 TO TRANSFER REAR RH DOOR ATTACHMENT TO NEW PANEL							120.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment							120.00
M SUNDRY TO TRANSFER REAR RH RIM INCLUDING BALANCING							30.00
M SUNDRY SUNRIES							50.00
M COVER-RR BUMPER LWR / CUT				1.00	565.00	20.00	452.00
M GARNISH ASSY-QTR SIDE,RH / CUT				1.00	38.00	20.00	30.40
M GARNISH ASSY-RR DR SIDE,RH / CUT				1.00	210.00	20.00	168.00
M PANEL ASSY-REAR DOOR,RH / 00				1.00	1290.00	20.00	1032.00
M W/STRIP ASSY-RR DR SIDE RH / ?				1.00	76.00	20.00	60.80
M W/STRIP-RR DR BELT I/S RH / ?				1.00	24.00	20.00	19.20
M W/STRIP ASSY-RR DR BELT O/S RH / ?				1.00	88.00	20.00	70.40
M MOULDING ASSY-RR DR FRAME,RH / ?				1.00	38.00	20.00	30.40
M GARNISH ASSY-RR DR RR FRAME,RH / ?				1.00	48.00	20.00	38.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV13651/TAN KIAN SIONG (CHEN JIANXIONG) Reg No/Reg Date SMX1126J / 28/12/202 Date In/Mileage / 0 Chassis No KNARH818VM5066376 Engine No D4HELH262447 Make/Model KIA/SORENTO 2.2 A D SX SR G898 Colour/Trim SWP SNOW WHITE PEAR/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	08/01/2021/ 09:27	QUK	282 / Kevin Leong	26959

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GARNISH ASSY-RR DR FR FRAME,RH	1.00	49.00	20.00	39.20
M WHEEL ASSY-ALUMINIUM / CUT	1.00	799.00	20.00	639.20

Steve CLKK) 00-NM Auth
8/1/21, 12.00pm EXCESS - ?
P/P

Estimate
15 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Confirm & accepted by

	Nett	6,950.00
7% GST on	6950.00	486.50
Total Payable		7,436.50

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	07/01/2021 14:29 (SGT)
Date of Accident	06/01/2021 18:45 (SGT)
Exact Location of Accident	Opp Zhongshan Mall, Singapore
Additional Location Information	BALESTIER RD
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SMX1126J
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	TAN KIAN SIONG
NRIC No	SXXXX588Z
Email Address	SKYTECHET@YAHOO.COM
Mobile Phone No	(Phone) +65-93634042
Alternative Phone No	+65-93634042

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Sorento
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	2070176085
Cover Note Number	-

DRIVER

Name of Driver	TAN KIAN SIONG
NRIC No	SXXXX588Z
Date Of Birth	08/11/1983
Occupation	Outdoor

Date Of Driving Pass

Driving experience

Gender

Mobile Number

Alt. Phone Number

Email Address

Address

Address complement

Postcode

Is the driver the policyholder?

If No, Relationship of the Driver with the Insured

Does Driver Own Other Vehicles?

Vehicle Registration Number of Other Vehicle Owned by Driver

Insurance Company of Other Vehicle Owned by Driver

08/10/2003

17 YEARS AND 3 MONTHS

Male

(Phone) +65-93634042

+65-93634042

SKYTECHIE@YAHOO.COM

BLK 291 CHOA CHU KANG AVENUE 3 #04-214

680291

Yes

No

-

-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident

Weather Conditions

Road Surface

Collision - Head to Rear

Clear

Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?

No

Number of vehicles involved in the accident

2

Was anybody injured in the Accident?

No

Was any injured conveyed to hospital by ambulance?

-

Was any other material or property damaged?

Yes

Number of Passengers (Including Driver)

3

Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?

No

PASSENGER 1

Name

TAN SIN KONG

Gender

Male

PASSENGER 2

Name

LIM BEE TIAN

Gender

Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?

No

Was notice of intended Prosecution given?

No

If yes, against whom?

-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

COLLISION-HEAD TO SIDE

ATTACHMENT(S)

Are accident photos available for attachment?

Yes

Was there any video captured by Car Camera?

Yes

Was there any audio recorded?

No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number

SLF7731D

Vehicle Manufacturer

Honda

Vehicle Model

Vezel

Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name
Nature Of Damage
Details of property damaged in accident
No. Of Passenger (Including Driver)

-
Gray
Private car
LEE KUI LIM
(Phone) +65-90082817
-
-
-
-
-
-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel




Describe Circumstances of the Accident

~~On a clear day~~

On 06/01/21 at 1845hrs, I was driving along Balesier Rd when a Honda Vezel made a turn into Shan Rd from the opposite direction. I had the right of way as I was driving on a straight road and because the driver's view of the Honda Vezel was blocked by a line of other cars, he took the risk to drive but unfortunately, he drove into my vehicle. From the video and photos, my vehicle was hit from the back passenger door all the way to the back bumper and wheel. Clearly, I had driven pass some distance before the driver of the Honda Vezel banged into me.


Declaration

We declare the foregoing particulars are true in every respect.

 07/01/21

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel



COVER NOTE

KIA AUTO PROTECTOR PRIVATE VEHICLE

The following risk described on this Cover Note is hereby HELD COVERED on the terms and conditions of the policy issued to the Policyholder.

Name of Policyholder : TAN KIAN SIONG (CHEN JIANXIONG)
Period of Insurance : 21 Dec 2020 to 20 Dec 2022
Engine No. : D4HELH262447
Chassis No. : KNARH81BVM5066376

Vehicle No. : TBA
Cover Note No. : 2070176085
Endorsement No. :
Issued Date : 21 Dec 2020

ABOUT THE COVER

Make/Model : KIA Sorento 2.2 A D SX
Engine Capacity/Tonnage : 2,151.00 CC
Driver Restriction : NA
Person or Classes of Persons Entitled to Drive* :

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2020
Insuring with COE/PARF : Yes

a) The Policyholder
b) Any other person who is driving on the Policyholder's order or with his/her permission.
This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Inexperienced Driver Excess" ("IDR") if You are or Your Authorised Driver (named or unnamed) has less than 2 years' driving experience.

Mileage Condition : Unlimited Mileage

Age Condition : 35 years old and above

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
This Policy does not cover use for hire or reward, driving tuition, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc
* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$600

Section 2
Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)
TAN KIAN SIONG (CHEN JIANXIONG) - \$600 (Own Damage), \$600 (Flood Cover)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- 1 Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501
 - 2 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
 - 3 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800
 - 4 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
- For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

If you do not receive your Certificate of Insurance and policy documents within 30 days from the inception date stated on this cover note, please contact AIG immediately.
We hereby certify that this Cover Note is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia). For Corporate Policies, this Cover Note is valid for 60 days from the commencement date of the period of insurance.

AIG Asia Pacific Insurance Pte. Ltd.
This computer generated document does not require a signature.

0504671231

CYCLE & CARRIAGE - CINDY
239 ALEXANDRA ROAD
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

Joanne Leung