

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / P / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.


Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Veh No: GSK 3822M Yr Regn: 20/7/20
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or LMMake: Citroen Berlingo C.C. 1499
Colour: white A/C: Insured / Std / NI / NASp. Reading: 19666 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt or delBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F: 205/60R16
R:BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop orThe U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

Preli. Report

1)

☐

Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

19/1/21 2/5 @ 6600 confirmed with Alan

FASTECH AUTO PTE LTD
BLK 1 KAKI BUKIT AVE 6
#01-48, AUTO BAY
SINGAPORE 417883

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Mr: Asher
Not Asher
d/s \$6600
8/1/21
5 days.

VEHICLE No: GBK 3922M

1PC	FRONT BUMPER TOP	Deep cut/turn		\$1,550.00	✓	517
1PC	FRONT BUMPER BOTTOM BLACK	Dis		\$1,200.00	✓	602
1PC	FRONT BUMPER FOG LAMP O/S	Cne	450	\$650.00	✓	
1PC	FRONT BUMPER FOG LAMP GARNISH O/S	mis	222	\$420.00	✓	
1PC	FRONT BUMPER FOG LAMP INNER BRACKET O/S	Cne	205	\$355.00	✓	
1PC	FRONT BUMPER SIDE RETAINER O/S	11		\$68.00	X	
1SET	FRONT BUMPER CLIPS	111	45.00	\$50.00	✓	
1PC	FRONT BUMPER REINFORCEMENT	111		\$685.00	X	
1PC	FRONT BUMPER SPONGE	Torn	105.00	\$320.00	✓	
1PC	FRONT GRILLE	Cne	392.00	\$820.00	✓	
1SET	FRONT GRILLE CLIPS	111	35.00	\$50.00	✓	
1PC	HEADLAMP O/S	Cne	1200	\$2,880.00	✓	
1PC	HEADLAMP LOWER BRACKET O/S	11		\$199.00	X	
1PC	FRONT SUPPORT PANEL	Cne	820	\$1,215.00	✓	
1PC	FRONT FENDER O/S	11		\$885.00	X	
1PC	FRONT FENDER INNER SHIELD O/S	11		\$288.00	X	
1SET	FRONT FENDER INNER SHIELD CLIPS O/S	11		\$50.00	X	
1PC	FRONT INTER COOLER	111/pun	1100	\$2,680.00	✓	
1PC	FRONT INTER COOLER BRACKET TOP	Cne	92.00	\$100.00	✓	
1PC	FRONT INTER COOLER GARNISH HOUSING	Cne	455.00	\$665.00	✓	
1PC	FRONT INTER COOLER AIR BOX	Cne	423.00	\$980.00	✓	
1PC	AIR CON CONDENSER	11		\$1,100.00	X	
1PC	RADIATOR	11		\$1,299.00	X	
1PC	RADIATOR FAN ASSY	11		\$800.00	X	
1PC	FRONT LOWER ARM O/S	11		\$620.00	X	
1PC	FRONT KNUCKLE ARM O/S	But	520	\$755.00	✓	
1PC	FRONT KNUCKLE ARM BEARING O/S	Drye	218	\$350.00	✓	
1PC	FRONT SHOCK ABSORBER O/S	11		\$488.00	X	
1PC	FRONT STEEL RIM O/S	111/But		\$200.00	80	
				\$21,722.00		

(10%)

TO CHECK WIRING	\$50.00	20
TO REFILL AIR CON GAS	\$120.00	100
TO SPRAY RUST PROOFING	\$100.00	X
TO CONDUCT WHEEL ALIGNMENT	\$120.00	80
TO DISMANTLE & REPLACED FRT UNDER CARRIAGE	\$180.00	120
LABOUR FOR PANEL BEATING & REPLACED PARTS	\$1,080.00	600
TO PUTTY & SPRAY PAINTING	\$1,500.00	600
TOTAL	\$24,872	

2481 82529
102
67329