

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Reg. No: 19960/198R GST Reg. No. 19-960/198-R						
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	tef:	CS/AGI21000376/Ktd3q2	
		INSURANCE) U AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	10/02/2021	
			C	ode:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	FBK 2652Z	Veh. Inspected		SMQ 9272D	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C20008355/LA	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		08/01/2021	
2. Vehicle Particulars & Condition						
	Make & Model	CITROEN C5 AIRCROSS (A)	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	VR7A45GFRKL073700	Colour		METALLIC PEARL WHITE	
	Odometer	12334 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	205/55 R19	MICHELIN		9 mm	
	L/H Front Tyre	205/55 R19	MICHELIN		9 mm	
	R/H Rear Tyre	205/55 R19	MICHELIN		9 mm	
	L/H Rear Tyre	205/55 R19	MICHELIN		9 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	14/12/2020	Inspection Date		08/01/2021	
	Survey held at	TONG LUCK AUTO PL	•			
		160 SIN MING DRIVE #07-01/06 SIN MING AUTOCITY SINGAPORE 575722				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	D)III / IOOORDAIN	Estimate Days of Repair				

4 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: