

Surveyor : Steve LKK
 Ins Company : AIG
 DOA : 08/01/2021
 CSE : Coco
 Date of Survey : 08/01/2021

VEHICLE NO : SMA6469H
 MODEL : KIA/ CARENS 1.7 A D SX
 WIP : 27036

Material	:	\$	4,277.60
Labour	:	\$	5,370.00
Sub-Total	:	\$	9,647.60
Less Excess	:	\$	3,000.00
Total	:	\$	6,647.60
GST 7%	:	\$	465.33
Grand Total	:	\$	7,112.93
Finalise By/Date	:	Patrick	14/06/2021

Email :

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 12 WORKING DAYS + 6 Days (3) Weekends
 + 0 Days (0) Public Holiday
 + 1 Survey - 21/05/2021 - Fri
 TOTAL DAYS REPAIR TOOK = 19

☐ TP Claim

☐ Claim GIA / LTA fee

☐ Claim Loss ☐ Use ☐ Rental

☐ Claim Medical Fee / Others

☐ Third Party Report

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 08/01/2021	<table> <tr> <td>Cust No/Name</td><td>/Ng Boon Chye Andrew @ Adhwa Ng</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMA6469H / 26/04/2018</td></tr> <tr> <td>Date In/Mileage</td><td>08/01/2021/ 1615</td></tr> <tr> <td>Chassis/Package</td><td>KNAHU815VJ720541C /FS215N</td></tr> <tr> <td>Engine No</td><td>D4FDJH551779</td></tr> <tr> <td>Make/Model</td><td>KIA/CARENS 1.7 A D SX FL DY6</td></tr> <tr> <td>Colour/Trim</td><td>1D CLEAR WHITE / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Ng Boon Chye Andrew @ Adhwa Ng	Reg No/Reg Date	SMA6469H / 26/04/2018	Date In/Mileage	08/01/2021/ 1615	Chassis/Package	KNAHU815VJ720541C /FS215N	Engine No	D4FDJH551779	Make/Model	KIA/CARENS 1.7 A D SX FL DY6	Colour/Trim	1D CLEAR WHITE / WK SATURN BLACK
Cust No/Name	/Ng Boon Chye Andrew @ Adhwa Ng														
Reg No/Reg Date	SMA6469H / 26/04/2018														
Date In/Mileage	08/01/2021/ 1615														
Chassis/Package	KNAHU815VJ720541C /FS215N														
Engine No	D4FDJH551779														
Make/Model	KIA/CARENS 1.7 A D SX FL DY6														
Colour/Trim	1D CLEAR WHITE / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	14/06/2021/ 15:29	BLC	881 / Jojo Cheng	27036		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER, LHF FENDER, LHF DOOR & LHR DOOR REPAIR LH SIDE SILL							/ 2000.00
E PNT98000 SPRAY PAINT WORK ON FRT BUMPER, LHF FENDER, LHF DOOR, LHR DOOR & LH SIDE SILL							/ 1750.00
E PNT88000 REMOVE & INSTALL FRT DOOR TRIMS AND GLASS							/ 160.00
E PNT88000 REMOVE & INSTALL REAR DOOR TRIMS AND GLASS							/ 160.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION							/ 80.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment							/ 120.00
A 90000001 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							/ 30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							/ 120.00
A 90000001 RENEW FRT UNDERCARRIAGE							/ 400.00
M SUNDRY TRANSFER FRT LEFT TYRE							/ 30.00
M SUNDRY SUNDRIES							/ 20.00
M SUNDRY SUPPLY LH FRONT RIM							? 500.00
X EXC EXCESS FOR OWN DAMAGE CLAIM							-3000.00
X COVER-FR BUMPER				1.00	695.00	20.00	/ 556.00
X EMBLEM-KIA				1.00	76.00	20.00	/ 60.80
X BRACKET-FR BUMPER SIDE,LH				1.00	12.00	20.00	/ 9.60
X PANEL-FENDER,LH				1.00	425.00	20.00	/ 340.00

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 08/01/2021	<table> <tr> <td>Cust No/Name</td><td>/Ng Boon Chye Andrew @ Adhwa Ng</td></tr> <tr> <td>Reg No/Reg Date</td><td>SMA6469H / 26/04/2018</td></tr> <tr> <td>Date In/Mileage</td><td>08/01/2021/ 1615</td></tr> <tr> <td>Chassis/Package</td><td>KNAHU815VJ720541C /FS215N</td></tr> <tr> <td>Engine No</td><td>D4FDJH551779</td></tr> <tr> <td>Make/Model</td><td>KIA/CARENS 1.7 A D SX FL DY6</td></tr> <tr> <td>Colour/Trim</td><td>1D CLEAR WHITE / WK SATURN BLACK</td></tr> </table>	Cust No/Name	/Ng Boon Chye Andrew @ Adhwa Ng	Reg No/Reg Date	SMA6469H / 26/04/2018	Date In/Mileage	08/01/2021/ 1615	Chassis/Package	KNAHU815VJ720541C /FS215N	Engine No	D4FDJH551779	Make/Model	KIA/CARENS 1.7 A D SX FL DY6	Colour/Trim	1D CLEAR WHITE / WK SATURN BLACK
Cust No/Name	/Ng Boon Chye Andrew @ Adhwa Ng														
Reg No/Reg Date	SMA6469H / 26/04/2018														
Date In/Mileage	08/01/2021/ 1615														
Chassis/Package	KNAHU815VJ720541C /FS215N														
Engine No	D4FDJH551779														
Make/Model	KIA/CARENS 1.7 A D SX FL DY6														
Colour/Trim	1D CLEAR WHITE / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LAX00000	Credit	14/06/2021/ 15:29	BLC	881 / Jojo Cheng	27036		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
X	PANEL ASSY-FRONT DOOR,LH			1.00	1097.00	20.00	/ 877.60
X	PANEL ASSY-REAR DOOR,LH			1.00	977.00	20.00	/ 781.60
X	BLACK TAPE-FRT DOOR FRAME UPR,			1.00	13.00	20.00	/ 10.40
X	TAPE-FR DR BLACK FRAME RR LH			1.00	14.00	20.00	/ 11.20
X	TAPE-RR DR BLACK FRAME FR,LH			1.00	11.00	20.00	/ 8.80
X	TAPE-RR DR BLACK FRAME UPR,LH			1.00	12.00	20.00	/ 9.60
X	TAPE-RR DR BLACK RR,LH			1.00	9.00	20.00	/ 7.20
X	ARM COMPLETE-FR LWR,LH			1.00	429.00	20.00	/ 343.20
X	BEARING-FRONT WHEEL HUB			1.00	251.00	20.00	/ 200.80
X	KNUCKLE-FRONT AXLE,LH			1.00	344.00	20.00	/ 275.20
X	STRUT ASSY-FR,LH			1.00	335.00	20.00	/ 268.00
X	BUMPER-RUBBER			1.00	42.00	20.00	/ 33.60
X	BEARING-STRUT			1.00	53.00	20.00	/ 42.40
X	END ASSY-TIE ROD,LH - SUPP			1.00	61.00	20.00	48.80
X	SENSOR ASSY-ABS FRONT WHEEL ,L - SUPP			1.00	137.00	20.00	109.60
X	LINK ASSY-FRONT STABILIZER,LH			1.00	94.00	20.00	? 75.20
X	INSULATOR ASSY-STRUT			1.00	104.00	20.00	? 83.20
X	HOLDER-PARKING ASSIST SYSTEM N			1.00	17.00	20.00	13.60
X	HOLDER-PARKING ASSIST SYSTEM N			1.00	17.00	20.00	13.60
X	HOLDER-PARKING ASSIST SYSTEM N			1.00	17.00	20.00	13.60
X	HOLDER-PARKING ASSIST SYSTEM N			1.00	17.00	20.00	13.60
X	FILM-ANTI CHIPPG LH			1.00	13.00	20.00	10.40
X	GUARD ASSY-FRONT WHEEL,LH			1.00	75.00	20.00	? 60.00

Pro Forma

SUPP

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	4,277.60	Nett	6,647.60
Labour	4,740.00	7% GST on	465.33
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	7,112.93
Sundry/Others	-2,370.00		
Total(w/o GST)	6,647.60		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.

SUPPLEMENTARY

INSURANCE CO : AIG ASIA PACIFIC INSURANCE PTE LTD

REGISTRATION NO : SMA6469H

S/N	Description	Qty	Unit Price	Disc%	Amount
PARTS					
1	END ASSY-TIE ROD, LH	1.00	61.00	20.00	48.80
2	SENSOR ASSY-ABS FRONT WHEEL, L	1.00	137.00	20.00	109.60
3	HOLDER-PARKING ASSIST SYSTEM	4.00	17.00	20.00	54.40
4	FILM-ANTI CHIPPG LH	1.00	13.00	20.00	10.40
Total					223.20
7 % GST					15.62
Grand Total					238.82

Thank You.

Yours faithfully

CYCLE & CARRIAGE KIA PTE LTD

Patrick Lee

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Link Assy - FR Stabilizer LH	? / SUPP		- BT	
2	Grat Assy Steering Tie Rod end LH	? / SUPP		- BT	} Steve 13/11/21
3	LH Front wheel ABS Sensor	? / SUPP		- TN	
4	Shut Insulator Fwd RH	? / SUPP		-	
5	Knuckle arm Fwd LH	? / SUPP		-	
6	" " heavy LH LH	? / SUPP		-	} Steve 13/11/21
7		? / SUPP			
8	LHF inside Fender Garnish	? / SUPP			
9	LHR sill panel Sticker	? / SUPP		- HR TN	
10	Cilp 15	? / SUPP		- NC	
11	FT Bumper Sensor bracket RH - 14	? / SUPP		- NC	} Steve 19/11/21
12	FT Bumper Sensor bracket 14 LH	? / SUPP		- N	
13	FT Bumper Sensor bracket Center (2)	? / SUPP		- N	
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

PHOTO BEFORE PAINT	DATE	TAKEN BY
PHOTO AFTER PAINT	10 Nov 19/11	Steve
PHOTO OF MOUNT TO CELLETTE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

MODEL: carens k1A

SURVEYOR: Steve

HOME Online  CARENS/RONDO../2018/D 1.7 TCI.. VCI  

 **Fault Code Searching**

Rescan Erase All DTC Go to DTC Save

 **AIRCON**  **AIRBAG**  **ESP**

5/5

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ESP	No Current DTC	Good
AIRBAG	No Current DTC	Good
AIRCON	No Current DTC	Good

System	DTC	Description	State
No Current DTC			

S/W Ver.	M-E-K-01-00-0237	VCI Ver.	02.49
ECU Ver.	M-E-K-01-00-0178	OS Ver.	Android 10

Work Order: R001311
 License: sma 6469 h
 Technician: 810119
 Mileage: 57784
 Date: 14.1.21 18:34

Kia : Carens IV / Rondo (2014-19 RP) : with 16", 17" Wheel

Front : Left

Actual	Before	Specified Range
-0°36'	-0°31'	-1°00' 0°00'
3°50'	3°50'	3°44' 4°44'
0°00'	-0°19'*	-0°06' 0°06'
12°54'	12°49'	
12°19'	12°19'	

Camber
 Caster
 Toe
 SAI
 Included Angle
 Turning Angle Diff.

Front : Right

Actual	Before	Specified Range
-0°28'	-0°29'	-1°00' 0°00'
5°21'*	5°21'*	3°44' 4°44'
0°01'	-0°22'*	-0°06' 0°06'
13°10'	13°11'	
12°42'	12°42'	

Front

Cross Camber
 Cross Caster
 Cross SAI
 Total Toe
 Cross Turn Diff.

Actual	Before	Specified Range
-0°08'	-0°02'	
-1°32'	-1°32'	
-0°16'	-0°22'	
0°00'	-0°41'*	-0°12' 0°12'

Rear : Left

Actual	Before	Specified Range
-1°29'	-1°27'	-2°00' -1°00'
0°11'	0°09'	-0°09' 0°18'

Camber
 Toe

Rear : Right

Actual	Before	Specified Range
-1°26'	-1°28'	-2°00' -1°00'
0°03'	0°05'	-0°09' 0°18'

Rear

Cross Camber
 Total Toe
 Thrust Angle

Actual	Before	Specified Range
-0°03'	0°02'	
0°14'	0°14'	-0°18' 0°36'
0°04'	0°02'	

* This value is not within specification. Tire wear, handling and safety problems may result.