

ASS. REC. BY: SteveREF: 1

AIG CS/AIG21000439/Eqd3

ASSIGNMENT

From: _____ Date: _____
Estimated Cost: _____
QD/LTP/WS/LTP RES/LOD RES/EVA/INV/LMY
To Inspect Vehicle No: _____
at Workshop m/s _____
of _____
Insured: _____
Policy No. 1900156670
Claims No. 7535058293SG
Sum Insured: _____ Excess: 0/-
(Client's Record)
Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 7 days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMA 9507T Yr Regn: 2/9/19
Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
Truck / Trailer or
Make: KIA Stonic c.c. 998
Colour: Grey A/C: Insured / Std / NI / N
Sp. Rending: 19286 T/Radio: Insured / Std / NI / N
Eng/No: _____
C/No: KNA06811 VK629469
Gen. Cond: Good / Fair / Poor / Burnt
Steering: In order / Jammed / Leaked / Burnt or
Brake: In order / Jammed / Leaked / Burnt or
Modl: Nil / S/Rim / STD A/Rim or
Tyre Size: F: 185/65R15
R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or Kumho

Front		Rear	
R/Bal. <u>4</u>	mm	R/Bal. <u>4</u>	mm
L/Bal. <u>4</u>	mm	L/Bal. <u>4</u>	mm
D.O.A. <u>11/1/21</u>		D.O.I. <u>11/1/21</u>	

Survey held at Cycle & Callap
Des. of Damages: Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

MV-77K

11/01/21@5.40pm revert to AIG via Merimen

12/01/21@2.46pm Kok Chong informed C/A via Merimen

12/01/21@3.53pm Informed Coco C/A & ex \$0/- by email

22/01/21@11.13am Confirmed Ms. Loi final fig \$7,897.20, 7 repair days. (Red \$8306, 51%)

Date/Time, File, Pass to?

☐ : Prel. Report☐ : Final ReportDays Of Repair: 7Resurvey No. of Trip: 2

Survey Fee:

Transportation:

Date/Time, File Return to?

Add Fee: ☐ : Site Insp (\$ _____) S + RS, SI☐ : Interview (\$ _____) Photos☐ : Tech. Invs (%) Others☐ : Weigh and (kg) TOTAL

3/20/2021

MER-OD

http://www.aig.com

7897.20



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAY CHEE YONG (ZHENG ZHIYONG)	Cust No/Name	LCV11001/TAY CHEE YONG (ZHENG ZHIYONG)
3 FERNVALE CLOSE	Reg No/Reg Date	SMN9507T*ECB1/ 02/09/201
#02-08	Date In/Mileage	/ 0
SINGAPORE 797486	Chassis No	KNAD6811VK6297469
Contact No	Engine No	G3LCKP027889
	Make/Model	KIA/STONIC 1.0 A BET
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
LCV11001	CRDVCH	11/01/2021/ 11:08	BLC	442 / CocoLu	27152		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW FRT BUMPER				490			800.00
E PNT98000 SPRAY PAINT FOR FRT BUMPER				350			700.00
M SUNDRY FRT NUMBER PLATE WITH FRAME							50.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM							30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							120.00
E PNT88000 RENEW REAR BUMPER, REAR END PANEL, REPAIR TAILGATE				490			1600.00
E PNT88000 REMOVE & INSTALL PARKING SENSOR							60.00
E PNT98000 SPRAY PAINT FOR REAR BUMPER, REAR END PANEL, BOOLTID				700			1600.00
E PNT88000 REMOVE & INSTALL REAR COMPARTMENT TRIMS				1			300.00
A 90000001 RENEW REAR EXHASUT SYSTEM							400.00
A 90000001 RENEW REAR CAMERA							300.00
M SUNDRY APPLY SEALANT FOR ACCIDENT PORTION							40.00
M SUNDRY SUPPLY REAR NUMBER PLATE							50.00
M SUNDRY C&C LOGO							40.00
M SUNDRY Sundry							20.00
M COVER-FR BUMPER UPR				1.00	476.00	00.00	476.00
M COVER-FR BUMPER, LWR				1.00	367.00	00.00	367.00

Estimate

(phb)

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
TAY CHEE YONG (ZHENG ZHIYONG)	Cust No/Name	LCV11001/TAY CHEE YONG (ZHENG ZHIYONG)
3 FERNVALE CLOSE	Reg No/Reg Date	SMN9507T*ECB1/ 02/09/201
#02-08	Date In/Mileage	/ 0
SINGAPORE 797486	Chassis No	KNAD6811VK6297469
Contact No	Engine No	G3LCKP027889
	Make/Model	KIA/STONIC 1.0 A BET
	Colour/Trim	ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV11001	CRDVCH	11/01/2021/ 11:08	BLC	442 / Cocolu	27152			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	GRILLE-FRONT BUMPER				1.00	96.00	00.00	96.00
M	SKID PLATE-FR BUMPER X				1.00	55.00	00.00	55.00
M	GRILLE ASSY-RADIATOR				1.00	324.00	00.00	324.00
M	MOULDING-FRONT BUMPER A/INTAKE				1.00	61.00	00.00	61.00
M	ABSORBER-FRONT BUMPER ENERGY				1.00	98.00	00.00	98.00
M	STIFFNER-FR BPR LWR X				1.00	123.00	00.00	123.00
M	BRACKET-FR BUMPER SIDE, RH				1.00	13.00	00.00	13.00
M	BRACKET-FR BUMPER SIDE, LH				1.00	13.00	00.00	13.00
M	BEAM COMPLETE-FR BUMPER				1.00	544.00	00.00	544.00
M	ORNAMENT-KIA NO.115 X				1.00	32.00	00.00	32.00
M	LOGO ASSY-KIA SUB				1.00	51.00	00.00	51.00
M	EMBLEM-STONIC				1.00	26.00	00.00	26.00
M	EMBLEM-TURBO G.D.I				1.00	38.00	00.00	38.00
M	LAMP ASSY-HEAD, RH				1.00	1845.00	00.00	1845.00
M	LAMP ASSY-HEAD, LH				1.00	1845.00	00.00	1845.00
M	COVER-RR BUMPER LWR				1.00	366.00	00.00	366.00
M	SKID PLATE-RR BUMPER				1.00	122.00	00.00	122.00
M	MOULDING ASSY-RR BUMPER SIDE, R				1.00	152.00	00.00	152.00
M	MOULDING ASSY-RR BUMPER SIDE, L				1.00	152.00	00.00	152.00
M	LAMP ASSY-REAR FOG & R/REFL, RH				1.00	111.00	00.00	111.00
M	LAMP ASSY-REAR FOG & R/REFL, LH				1.00	111.00	00.00	111.00
M	COVER-RR BUMPER SIDE UNDER				1.00	62.00	00.00	62.00
M	WIRING HARNESS-BWS EXT				1.00	245.00	00.00	245.00
M	BRACKET-RR BEAM UPR MTG				2.00	7.00	00.00	14.00
M	BRACKET-RR BEAM LWR MTG, RH				1.00	5.00	00.00	5.00
M	BRACKET-RR BEAM LWR MTG, LH				1.00	7.00	00.00	7.00
M	ANTENNA ASSY-SMARTKEY				1.00	32.00	00.00	32.00
M	STAY-RR BUMPER RH				1.00	55.00	00.00	55.00
M	STAY-RR BUMPER LH				1.00	55.00	00.00	55.00
M	BEAM-RR BUMPER				1.00	419.00	00.00	419.00
P	ULTRASONIC SENSOR ASSY-BWS				2.00	189.00	00.00	378.00
P	ULTRASONIC SENSOR ASSY-BWS				2.00	189.00	00.00	378.00
M	PANEL ASSY-BACK				1.00	345.00	00.00	345.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

Invoice Name & Address	Owner Name & Vehicle Info
TAY CHEE YONG (ZHENG ZHIYONG)	Cust No/Name LCV11001/TAY CHEE YONG (ZHENG ZHIYONG)
3 FERNVALE CLOSE	Reg No/Reg Date SMN9507T*ECB1/ 02/09/201
#02-08	Date In/Mileage / 0
SINGAPORE 797486	Chassis No KNAD6811VK6297469
Contact No	Engine No G3LCKP027889
	Make/Model KIA/STONIC 1.0 A BET
	Colour/Trim ABT PLATINUM GRAPHI/ WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LCV11001	CRDVCH	11/01/2021/ 11:08	BLC	442 / CocoLu	27152			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M MUFFLER ASSY-REAR					1.00	665.00	00.00	665.00
M MUFFLER ASSY-CENTER					1.00	362.00	00.00	362.00
M RR CAMERA & TRUNK LID HDL ASSY					1.00	758.00	00.00	758.00

Estimate

Steve CLKK) 00- NM AL
 11/1/21, 1.00pm Excers - ?
 P/P
 My Bel spy
 7 days

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Confirm & accepted by
Signature:
Date:

	Nett	16,911.00
7% GST on	16911.00	1183.77
Total Payable		18,094.77

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreens in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreens.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission 11/01/2021 13:18 (SGT)
Date of Accident 11/01/2021 07:45 (SGT)
Exact Location of Accident KJE, Singapore
Additional Location Information KJE AFTER EXIT 5 TOWARDS PIE
Country/State of Loss Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number SMN9507T

INSURED/POLICYHOLDER

Is company? No
Name Of Registered Owner TAY CHEE YONG
NRIC No SXXXX924G
Email Address TAYCHEEYONG@GMAIL.COM
Mobile Phone No (Phone) +65-91867185
Alternative Phone No +65-91867185

VEHICLE PARTICULARS

Manufacturer Kia
Model Stonic
Variant -
Exact purpose for which vehicle was being used at time of accident -
Are you claiming under your own insurance policy for repair to your vehicle? Yes
Vehicle Category Private car

INSURANCE COMPANY

Name of Insurance Company AIG
Type of Coverage Comprehensive
Fleet Policy No
Policy Number 1900156670
Cover Note Number -

DRIVER

Name of Driver TAY CHEE YONG
NRIC No SXXXX924G
Date Of Birth 04/03/1981
Occupation Indoor

Valid Driving Pass	29/03/2007
Driving experience	13 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91867185
Alt. Phone Number	+65-91867185
Email Address	TAYCHEEYONG@GMAIL.COM
Address	3 FERNVALE CLOSE #02-08
Address complement	-
Postcode	797486
Is the driver the policyholder?	Yes
If No, Relationship of the Driver with the Insured	-
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Chain Collision
Weather Conditions	-
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	3
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	Yes

PASSENGER 1

Name	SOH CHAI YEN
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	Yes
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJR7438L
Vehicle Manufacturer	Honda
Vehicle Model	Fit
Vehicle Variant	-
Vehicle Colour	Red
Vehicle Category	Private car
Name of Driver	PRIYA D/O MUHINDHRAN
Contact Number	(Phone) +65-92375445

Address complement
 Postcode
 Insurance Company Name
 Nature Of Damage
 Details of property damaged in accident
 No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 2:

Vehicle Registration Number	SLD8803J
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	SOO ZHEN YU
Contact Number	(Phone) +65-81236348
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.


(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


 11/1/21
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

Sketch Plan




Circumstances of the Accident


was ~~being~~ driving at KJE first lane.
car in front came to a stop.
I slow down and came to a complete stop.
the car behind hit onto me and I hit onto the car in front.

Declaration

We declare the foregoing particulars are true in every respect.


Policyholder's Signature / Date & Time
11/1/21

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

KIA AUTO PROTECTOR PRIVATE VEHICLE
Name of Policyholder : TAY CHEE YONG (ZHENG ZHIYONG)
Period of Insurance : 02 Sep 2019 To 01 Sep 2021
Engine No. : G3LCKP027889
Chassis No. : KNAD6811VK6297469

Vehicle No. : SMN9507T
Policy No. : 1900156670
Endorsement No. :
Issued Date : 06 Sep 2019

ABOUT THE COVER

Make/Model : KIA Stonic
Engine Capacity/Tonnage : 998.00 CC
Driver Restriction : NA

Sum Insured : Market Value
Off Peak Car : No

First Year of Registration : 2019
Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

TAY CHEE YONG (ZHENG ZHIYONG) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS-RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000

2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800

4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1989 (Malaysia).

0504622242

CYCLE & CARRIAGE-ERNEST
239 ALEXANDRA ROAD
SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCNMD

1002554148/AC/Decal