**MESSAGES** 

**CLAIMS** 



General & Workshop Deta	ils Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
General Details			Workshop De	tails		
Involving	TPVD NISSAN (GBJ5354U)		Total Rebate Am	nount 19190	)	
Date of Loss	8 January 2021		Nett Loss Amou	nt \$30,810	0.00	
Time of Loss	9.14		Assigned Works	hop LKK AL	ITO CONSULTANTS	FPTE LTD (TP)
Loss Description	FBN209T (INSD) C/W GBJ5354U		Days of work completion *	20		
Comment			completion			

**MESSAGES** 

**CLAIMS** 



General & Workshop	Details Vehicl	e & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & L	abour	Miscellaneous	Summa	ry
Vehicle & Driver De	etails								
Vehicle Registration#	GBJ5354U			Purchase Date		dd/mm/y	уууу		
Registration State	SINGAPOR	E		Registration Date	*	22/05/2	019		
Mileage	34094			Age of Vehicle		1			
CATEGORY	POLICY INFORMATION	ASSESSMENT INF	ORMATION	Driver Details					
Manufacturing		2019		CATEGORY	FN: INF	OL FORMATION		T SURVEY DRMATION	
Year				Driver Name	SIN	M WEE KIA	Т		
Make	TPVD	NISSAN							44
				Date of Birth			do	I/mm/yyyy	

Model CATEGORY	NUSSAN INFORMATION	NV200 DX 1.6 AUTO	<b>CATEGORY</b> Age	fnol (nformation	POST SURVEY INFORMATION
Туре		•	Occupation	Unknown	
Type of Paint			Education Qualification	Other	
Chassis No		VM20135181	Driving Experience	0	
Engine No		HR16147226D	Driver License #		
Engine Capacity		1597	License Type		
Sum Insured		0	License Issue Date		dd/mm/yyyy

License

**Expiration Date** 

dd/mm/yyyy

50000

Market Value

CATEGORY Address	FNOL INFORMATION Singapore	POST SURVEY
Address type	Personal Correspondence	•
Gender	Unknown	•
Marital status	Unknown	•
Identification #	TBC	

**MESSAGES** 

**CLAIMS** 



General & Workshop Deta	ils Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labo	our	Miscellaneous	Summary	
Detailed Assessment			Condition of Vehicle at time of survey					
Inspection Date *	ate * 12/01/2021		General condition		Good			~
Total Loss	Yes No		Steering (Service	eable)	Yes	No		
Towing Charges	0		Footbrake (Servi	ceable)	Yes	No		
Voluntary Excess  Compulsory Excess	0		Handbrake (Serviceable)		Yes	No		
Young/Inexperienced/ Unnamed Driver Excess	0		Engine Modifica	tion	Yes	No		
			Pre-accident cor	ndition	Good			~

Other Excess		Tyre Condition	
Age of Tyres		Spare wheel	
Front Tyre Size	175/70R14	Rear Tyre Size	175/70R14
Front left side	BRIDGESTONE6mm	Rear left side	BRIDGESTONE6mm
Front right side	BRIDGESTONE6mm	Rear right side	BRIDGESTONE6mm

**MESSAGES** 

**CLAIMS** 



General & Workshop Details	Vehicle & Driver Details	Vehicle Conditi	on Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Tax Eligibility & Additiona	al Deduction for Parts					
Depr./Bttr%			Salvage%			
Discount%	10		Settlement%	100		
Paint Labour/Material Ra	tio					
Paint Labour Ratio	20		Paint Material R	atio 80		
Cash Loss		<b>Y</b> es N	o			
Part Supplied by AXA		Yes N	o			

MESSAGES

CLAIMS

Gener	al & Works	hop Details	Vehicle	& Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary						
Parts															
Add	Approve	Deny	Submit	All											
	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
		0	1		FRONT BUMPER	Cut	0	653	No		10			587.7	Reviewin <sub>į</sub>
	Ø	0	1		FRONT BUMPER SIDE HOLDER RH	Cracked	0	34.8	No		10			31.32	Reviewinį
	D	0	1		FRONT BUMPER SIDE HOLDER LH	Serviceable	0	0	No		10			0	Deny
	D	0	1		FRONT BUMPER REINFORCEMENT	Serviceable	0	0	No		10			0	Deny
	Ø	0	1		FRONT GRILLE	Serviceable	0	0	No		10			0	Deny
	Ø	0	1		FRONT GRILLE LOGO	Serviceable	0	0	No		10			0	Deny
	Ø	0	1		HEADLAMP RH	Cut	0	648	No		10			583.2	Reviewinį
	Ø	0	1		HEADLAMP LOWER APRON RH	Deformed	0	374.6	No		10			337.14	Reviewinį

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
	Ø	0	1		FRONT RH FENDER	Repair	0	0	No		10			0	Deny
Labour															
Add	Approve	Deny	Submit A	JI .											
	EDIT	SR NO	REPAI (LABC	R/REPLACE DUR)	PART NAME		ESTIMATE LABOUR AMOUNT	ADJUSTED LA		ESTIMATE PAINT AMOUNT		DJUSTED PAINT MOUNT	ACT (LAB	OUR)	COMMENT
		0			PANEL BEATING, F AND REFIT PARTS		0	300		0	0		Rev	iewing	
	Ø	0			SPRAY PAINTING AFFECTED AREA	то	0	300		0	0		Rev	iewing	
	Ø	0			WIRING CHECK		0	30		0	0		Rev	iewing	

**MESSAGES** 

CLAIMS



Genera	ıl & Worksho	p Details	Vehicle & Dri	ver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaned .	)US
Add	Approve	Deny	Submit All						
	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE	
	Ø	0	DAYS OF REPAIR : 3 DAYS	Reviewing		0		<b>d</b>	
	D	0	SET FRONT BUMPER CLIPS	Reviewing		30	NECESSARY	ш	
	ø	0	SET FRONT GRILLE CLIPS	Deny		0	NOT NECESSARY	ш	

**MESSAGES** 

**CLAIMS** 



## **Assessment Details**

Details •	Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
\$0.00	)		Adjusted Claim Amount	\$2,199.36		
	ESTIMATE	ADJUSTED				
	\$0.00	\$1,539.36				
	\$0.00	\$630.00				
	\$0.00	\$30.00				
		\$0.00  ESTIMATE  \$0.00  \$0.00	\$0.00  ESTIMATE ADJUSTED  \$0.00 \$1,539.36  \$0.00 \$630.00	\$0.00 Adjusted Claim Amount  ESTIMATE ADJUSTED  \$0.00 \$1,539.36  \$0.00 \$630.00	\$0.00 Adjusted Claim Amount \$2,199.3  ESTIMATE ADJUSTED  \$0.00 \$1,539.36  \$0.00 \$630.00	\$0.00 Adjusted Claim Amount \$2,199.36  ESTIMATE ADJUSTED  \$0.00 \$1,539.36  \$0.00 \$630.00

Submit for Review