

ASS. REC. BY:

Steve

REF:

CS/AIG 21000497/Eqd3

## ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

1800115338

Claims No.

6556128009SG

Sum Insured:

Excess:

500

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

8

days

Res.:

Yes or No

Lum Sum:

%

3 Val.:

Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SME 8137G

Yr Regn:

18/19/18

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Mitsubishi Attrage

c.c

1193

Colour:

Red

A/C:

Insured / Std / NI / N

Sp. Reading

35532

T/Radio: Insured / Std / NI / N

Eng/No:

C/No:

MMB STA 13AJH 003678

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

185/55R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal.

4

mm

R/Bal.

4

mm

L/Bal.

4

mm

L/Bal.

4

mm

D.O.A.

8/1/21

D.O.I.

11/1/21

Survey held at

Cycle &amp; Carriage

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

Fnt RH

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time

Action / Instruction

MV-54K

12/01/21 @ 4.16pm revert to AIG via Merimen.

14/01/21 @ 9.59am Kok Chong informed C/A via Merimen.

14/01/21 @ 10.30am Informed kevin C/A &amp; ex: \$500 by email.

09/02/21 @ 9.44am confirmed with Ms Loi final fig \$9413.15, 8 days. (Red \$2797.98, 23%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

Days Of Repair:

8

Resurvey No. of Trip:

2

Survey Fee:

Transportation:

S + RS \$

Photos

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (%)

☐

: Weekend (%)

Rep. Format:

MER-OD

Final Sum. P.E.I. /

9413.15



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI  
MOTORS

Reg No : 1977014696

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CHANG SENG KEONG (CHENG XINQIAN) Reg No/Reg Date SME8137G / 18/10/201 Date In/Mileage 09/01/2021/ 0 Chassis No MMBSTA13AJH003678 Engine No 3A92UHH5714 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	11/01/2021/ 12:18	QUK	282 / Kevin Leong	61680			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE FRT BUMPER, BONNET, FRT RH FENDER, FRT RH DOOR & AFFECTED AREA REPAIR ON FRT RH WHEEL HOUSING, FRT RH A-PILLAR					5 X 450			2700.00 2250
E PNT98000 PAINT WORK ON FRT BUMPER, BONNET, FRT RH FENDER, FRT RH DOOR & FRT RH WHEEL HOUSING								1750.00
M SUNDRY PERFORM RUST PREVENTION								47 80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
A 15900099 TO REPLACE ENGINE ATTACHMENTS								? 450.00
A WHEELALIGNMENTBP To Conduct Computerize Full Wheel Alignment								120.00
M SUNDRY SUNDRIES								20 50.00
M HEADLAMP ASSY, RH	✓	BR?			1.00	660.00	23.00	508.20
M LAMP ASSY, FOG, FR LH					1.00	303.00	23.00	233.31
M FACE, FR BUMPER	✓	BR			1.00	703.00	23.00	541.31
M COVER, HEADLAMP SUPT PANEL	X				1.00	62.00	23.00	47.74
M GRILLE, FR UNDER	X				1.00	165.00	23.00	127.05
M AIR DAM, SIDE, FR RH	✓	mis			1.00	18.00	23.00	13.86
M GARNISH, FR BUMPER, RH		(fig kyp m) / cut			1.00	127.00	23.00	97.79
M BRACKET, FR BUMPER, RH					1.00	13.00	23.00	10.01
M GRILLE, RADIATOR	X				1.00	554.00	23.00	426.58
M HOOD	✓	OP			1.00	734.00	23.00	565.18
M HINGE, HOOD, RH	X				1.00	56.00	23.00	43.12
M LATCH, HOOD	X				1.00	69.00	23.00	53.13
M DAM, HOOD	X				1.00	20.00	23.00	15.40
M FENDER, FR RH	✓	OD			1.00	497.00	23.00	382.69

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CHANG SENG KEONG (CHENG XINQIAN) Reg No/Reg Date SME8137G / 18/10/201 Date In/Mileage 09/01/2021/ 0 Chassis No MMBSTA13AJH003678 Engine No 3A92UHH5714 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P57 WINE RED PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	11/01/2021/ 12:18	QUK	282 / Kevin Leong	61680			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	REINFORCEMENT,FR BUMPER	✓ UU			1.00	466.00	23.00	358.82
M	COVER,ENG ROOM UNDER,FR	✓			1.00	99.00	23.00	76.23
M	SHIELD,FR WHEELHOUSE,RH	✓ TN			1.00	98.00	23.00	75.46
M	PANEL ASSY,FR DOOR,RH	X R			1.00	996.00	23.00	766.92
M	RUNCHAN,F/DR WDO GLA,RR RH	X			1.00	20.00	23.00	15.40
M	GLASS,FR DOOR WINDOW,RH	X			1.00	233.00	23.00	179.41
M	RUNCHANNEL,F/DR WDO GLA,RH	X			1.00	120.00	23.00	92.40
M	MLDG,F/DR WDO BELT LINE,RH	X			1.00	75.00	23.00	57.75
M	TAPE,FR DOOR SASH,RH	X			1.00	29.00	23.00	22.33
M	GARNISH,FR FENDER	X			1.00	65.00	23.00	50.05
M	TANK ASSY,RADIATOR COND	X <del>GRV</del>			1.00	42.00	23.00	32.34
M	TANK,WINDSHIELD WASHER	✓ GRV			1.00	74.00	23.00	56.98
M	CAP,WASHER TANK FILLER	X			1.00	7.00	23.00	5.39

Steve CLKK)  
11/1/21, 5.00pm

DD-NM Aul  
Excess - ?  
P/P  
By BIL sy  
8 dly

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Confirmed & accepted by  
Acknowledged by Repairer  
Signature:  
Date:

Nett 10,154.85  
7% GST on 10154.85 710.84  
Total Payable 10,865.69

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission	09/01/2021 11:05 (SGT)
Date of Accident	08/01/2021 18:30 (SGT)
Exact Location of Accident	404 Pasir Panjang Rd, Singapore 118741
Additional Location Information	PASIR PANJANG ROAD NEAR NEO PECK TECK LANE
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SME8137G
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	CHANG SENG KEONG
NRIC No	SXXXX284D
Email Address	CHANGSK_WORK@HOTMAIL.COM
Mobile Phone No	(Phone) +65-97832134
Alternative Phone No	+65-97832134

### VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Attrage
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

### INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1800115338
Cover Note Number	-

### DRIVER

Name of Driver	CHANG SENG KEONG
NRIC No	SXXXX284D
Date Of Birth	22/11/1974
Occupation	Indoor

Date Of Driving Pass  
Driving experience  
Gender  
Mobile Number  
Alt. Phone Number  
Email Address  
Address  
Address complement  
Postcode  
Is the driver the policyholder?  
If No, Relationship of the Driver with the Insured  
Does Driver Own Other Vehicles?  
Vehicle Registration Number of Other Vehicle Owned by Driver  
Insurance Company of Other Vehicle Owned by Driver

24/09/2018  
2 YEARS AND 4 MONTHS  
Male  
(Phone) +65-97832134  
+65-97832134  
CHANGSK\_WORK@HOTMAIL.COM  
3 FERNVALE CLOSE #03-07  
-  
797486  
Yes  
-  
No  
-  
-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident  
Weather Conditions  
Road Surface

Collision - Head to Rear  
Clear  
Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident? No  
Number of vehicles involved in the accident 2  
Was anybody injured in the Accident? No  
Was any injured conveyed to hospital by ambulance? -  
Was any other material or property damaged? Yes  
Number of Passengers (Including Driver) 2  
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

#### PASSENGER 1

Name DAVID HEE  
Gender Male

#### DETAILS OF POLICE ACTION

Was the accident reported to the police? No  
Was notice of intended Prosecution given? No  
If yes, against whom? -

#### CIRCUMSTANCES OF ACCIDENT

#### REFER TO ATTACHMENT

#### ATTACHMENT(S)

Are accident photos available for attachment? Yes  
Was there any video captured by Car Camera? Yes  
Was there any audio recorded? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SCP7079H  
Vehicle Manufacturer Toyota  
Vehicle Model -  
Vehicle Variant -  
Vehicle Colour -  
Vehicle Category Private car  
Name of Driver DEXTER CHENG WEI JIE  
Contact Number (Phone) +65-90884358

address

address complement

postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident

No. Of Passenger (Including Driver)

## SKETCH PLAN

### URGENT NOTICE

Report correctly the details of the accident to speed up the claims process.  
The Form must be completed by the Policyholder and/or the Authorised Driver.  
Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may  
insurance companies to repudiate policy liability.  
The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance  
companies.

Any false reporting may be referred to the Police for investigation.

The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association  
of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.

By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the  
report being made available aforesaid.

Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose  
and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or  
possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s)  
who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be  
collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant  
government agency/authority (such as the police), for the purpose(s) of:

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to  
the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve  
disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail  
packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect,  
use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents  
(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date &  
Time

Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date  
& Time

Witnessed by Reporting Centre  
Personnel

