

ASS. REC. BY:

REF:

C72/ 21000 516/kg

Kenneth

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s AT

of \_\_\_\_\_

Insured: \_\_\_\_\_


Policy No. DMPCSNW00167492003Claims No. SNM21D200149C02

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.Bal. or Market Value: 854K

IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No

Est. Repairs: 4-5 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S10 1751X Yr Regn: 06/16Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Vezel c.c. 1496Colour: M-Black A/C: Insured / Std / NI / NASp. Reading: 68143 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: R41 1117163Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: NII / S/Rlm / STD A/Rlm orTyre Size: F: 215/60R16

R: \_\_\_\_\_

BS/ DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 4 mm R/Bal. 3 mmL/Bal. 4 mm L/Bal. 3 mmD.O.A. 8/1/21 D.O.I. 12/1/2021

Survey held at: \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

21/01/21@5.40pm revised to Irene Tay via Merimen.

Date/Time, File Pass to?

☐ : Prell. Report

Days Of Repair: \_\_\_\_\_

1)

☐ : Final Report

Resurvey No. of Trip: \_\_\_\_\_

Date/Time, File Return to?

Survey Fee: \_\_\_\_\_

2)

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

Transportation: \_\_\_\_\_

☐ : Interview (\$ \_\_\_\_\_)

S - RS. SI

☐ : Tech Invs (\$ \_\_\_\_\_)

F. Repairs

☐ : Weekend (\$ \_\_\_\_\_)

Others

Report Format :

Lump Sum / I.B.I: (\$ \_\_\_\_\_)

TOTAL



# A T AUTO CONSULTANT

Blk 113 Teck Whye Lane #05-650 Singapore 680113

HP: 8386 8989

Co. Reg. No. : 53368526E

Date of Estimate: 11.01.2021

Vehicle No: SLD1751X

Owner: PRAVEAN GANESH

Date of Accident: 08.01.2021

Make & Model: Honda Vezel

Chassis No : RU11117163

Not Authorized  
11 Rm B  
Purvey After Pain  
4-5 days

## ESTIMATE FOR ACCIDENT VEHICLE NO SLD1751X

### PARTS

1	1	Tailgate
2	1	Tailgate moulding
3	1	Tailgate reflector RH
4	1	Tailgate lock
5	1	Tailgate striker
6	1	Tailgate inner trim
7	1	Tailgate windscreen seal
8	1	Tailgate weatherstrip
9	1	Tailgate emblem "VEZEL"
10	1	Rear corner apron garnish RH
11	1	Rear bumper
12	2	Rear bumper side retainer LH/RH
13	1	Rear bumper reflector RH
14	1	Rear end panel
15	1	Rear end panel top garnish
16	1	Taillamp RH
17	1	Remote key buzzer
18	1	Remote key buzzer bracket
19	1	Exhaust system

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

@ \$48

1	\$1,098.00	✓
2	\$269.00	✓
3	\$386.00	X
4	\$238.00	✓
5	\$85.00	X
6	\$299.00	X?
7	\$85.00	✓
8	\$286.00	?
9	\$58.00	✓
10	\$276.00	?
11	\$986.00	✓
12	\$96.00	X
13	\$151.00	✓
14	\$588.00	?
15	\$252.00	?
16	\$586.00	X
17	\$88.00	?
18	\$18.00	?
19	\$960.00	X
<b>SUB TOTAL</b>		<b>\$6,805.00</b>
<b>LESS 20 %</b>		<b>\$1,007.07</b>
<b>DISCOUNTED SUB TOTAL</b>		<b>\$5,797.93</b>

### S. NETT ITEM

1	1set	Rear bumper clips
2	3pcs	Rear end panel top garnish clips
3	1set	Reverse sensor
4	1set	Reverse camera

@ \$5.00

**SUB TOTAL**  
**LESS 0 %**  
**DISCOUNTED SUB TOTAL**

1	\$50.00	✓
2	\$15.00	?
3	\$320.00	2000
4	\$350.00	X
<b>SUB TOTAL</b>		<b>\$735.00</b>
<b>LESS 0 %</b>		<b>\$0.00</b>
<b>DISCOUNTED SUB TOTAL</b>		<b>\$735.00</b>

### LABOUR

1	Panel beating for replace and repair affected parts
2	Spray painting on accident areas
3	Wiring charges
4	Remove/refix reverse sensor
5	Remove/refix reverse camera
6	Transfer tailgate glass
7	Transfer tailgate component
8	Apply undercoating to above affected areas

**SUB TOTAL (LABOUR)**

**SUB TOTAL (S.NETT ITEM)**

Page 1 of 2

\$1,000.00	7
\$800.00	450
\$100.00	150
\$100.00	50
nn \$100.00	x
\$180.00	120
\$150.00	60
\$120.00	30
<u>\$2,550.00</u>	

**\$735.00**





## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission ..... 09/01/2021 12:12 (SGT)  
Date of Accident ..... 08/01/2021 18:00 (SGT)  
Exact Location of Accident ..... AYE, Singapore  
Additional Location Information ..... AYE Near Alexander Exit  
Country/State of Loss ..... Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number ..... SLD1751X

#### INSURED/POLICYHOLDER

Is company? ..... No  
Name Of Registered Owner ..... Pravean Ganesh S/O Elanthiraiyan  
NRIC No ..... SXXXX529J  
Email Address ..... vjromeo24@yahoo.com.sg  
Mobile Phone No ..... (Phone) +65-91895855  
Alternative Phone No ..... +65-91895855

#### VEHICLE PARTICULARS

Manufacturer ..... Honda  
Model ..... Vezel  
Variant ..... -  
Exact purpose for which vehicle was being used at time of accident ..... Private use  
Are you claiming under your own insurance policy for repair to your vehicle? ..... No - Claiming third party  
Vehicle Category ..... Private car

#### INSURANCE COMPANY

Name of Insurance Company ..... China Taiping Insurance  
Type of Coverage ..... Comprehensive  
Fleet Policy ..... No  
Policy Number ..... -  
Cover Note Number ..... -

#### DRIVER

Name of Driver ..... Aravind S/O Elanthiraiyan  
NRIC No ..... SXXXX547J  
Date Of Birth ..... 07/10/1993  
Occupation ..... Outdoor



Date of Driving License	22/12/2010
Driving experience	4 YEARS AND 1 MONTH
Gender	Male
Mobile Number	(Phone) +65-81395301
Alt. Phone Number	-
Email Address	aravind77.ap@gmail.com
Address	Blk 143 Jalan Bukit Merah #10-1140
Address complement	-
Postcode	160143
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Sibling
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

#### GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

#### OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

#### DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

#### CIRCUMSTANCES OF ACCIDENT

Please refer to sketch plan.

#### ATTACHMENT(S)


Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SJZ5061K
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	-



## SKETCH PLAN



A-SLD1751X

B-SJZ5061K

Date 08/07/2021

Time 1800

AYE Towards City.  
Near Alexandra Exit.

## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On mentioned date and time, I was driving AYE towards City near Alexandra exit on Lane 2.

The traffic was heavy. As I drove, the front vehicle slowed and stopped so I followed. Suddenly I felt an impact from the rear. It was vehicle B that collided onto my rear.

I felt discomfort after the accident.

## DECLARATION

I/We declare the foregoing particulars are true in every respect.

X

Policyholder's Signature

Date &amp; Time

09 JAN 2021

Driver's Signature

If signature is not the policyholder's

09 JAN 2021

Reporting Centre Personnel's Signature

Name