

ASS. REC. BY:

REF: CS3/ASM21000521/R1vf3

Special Instruction:

Surveyor: RASUL ASSIGNMENT (Office)From (Person): YU Dominic Yishan of AXA Date/Time: 12/1/2021 12:38 PM

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SMM 1191C Insured: SHC 3680Gat Workshop m/s Alpha Performance Singapore Pte Ltd. Tel: 6472568of 48 Toh Guan Road East #04 - 126 Enterprise HubPolicy No: _____ Claim No: S1M0305E

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 06-JAN-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP" H.O.D. Endorsement: _____

Date/Time: 12-01-2021 1.36P.M Person Contacted: NICOLE Vehicle ☒ IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	SMM 1191C ☒
	SHC 3680G- CC6/FCI20003595/Uda3q2 DOA :03/03/2020
13/1/21	Send IA via Smart Claim
13/1/21	Submit PRS, repair range \$3,000-\$4,000 (5 days)