



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623		Ref: CS/SMO21000547/R1Ktf3q2 Date: 25/02/2021 Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SLH 7372X	Veh. Inspected	SLM 8784H
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD2100124/THE	Excess (\$)	0.00
Assign From	GRACE TEO	Assign Date	12/01/2021
2. Vehicle Particulars & Condition			
Make & Model	KIA CERATO FORTE K3 1.6A	c.c	1591
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	KNAFJ411MH5714284	Colour	BROWN
Odometer	120504 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	07/01/2021	Inspection Date	13/01/2021
Survey held at	BLK 1002 BUKIT MERAH LANE 3 #01-73		
Repairer	3A AUTOMOBILE PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	