

AES. REC. BY: Pasul

REF: CS/SM02100547/R1K13

2760

**ASSIGNMENT**

From: \_\_\_\_\_ Date: \_\_\_\_\_  
 Estimated Cost: \_\_\_\_\_  
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV  
 To Inspect Vehicle No: SLM 8784H  
 at Workshop m/s 3A AUTOMOBILE  
 of 1002, BUKIT MERAH LN 3 #01-73  
 Insured: SMO  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_  
 (Client's Record)  
 Make of Veh: \_\_\_\_\_

Veh No: SLM 8784H Yr Regn: 2017, APR  
 Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /  
 Truck / Trailer or \_\_\_\_\_  
 Make: KIA CERATO FORTE K31-6A c.c. 1591  
 Colour: BROWN A/C: Insured / Std / NI / NA  
 Sp. Reading: 120504 T/Radlo: Insured / Std / NI / NA  
 Eng/No: \_\_\_\_\_  
 C/No: KNAF J411M H5714284  
 Gen. Cond: Good / Fair / Poor / Burnt  
 Steering: In order / Jaimmed / Leaked / Burnt or \_\_\_\_\_  
 Brake: In order / Jammed / Leaked / Burnt or \_\_\_\_\_  
 Modi: Nil / Rim / STD A/Rim or \_\_\_\_\_  
 Tyre Size: F: 195/65R15  
 R: \_\_\_\_\_  
 BS / DUN / EXNOVA / GY / FS / LIZA / NIC / OHTSU / PIR / SUMI /  
 TOYO / OKO or \_\_\_\_\_

(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 58k  
 IDAC Accident Rpt: \_\_\_\_\_ Consistent?: Yes or No  
 GIA / PR Seen: \_\_\_\_\_ Consistent?: Yes or No  
 Est. Repairs: \_\_\_\_\_ days Res.: Yes or No  
 Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No  
 CA / REV / REP. / 24 HRS  
 Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_ Vehicle: IN / OUT

Front Rear  
 R/Bal. 6 mm R/Bal. 6 mm  
 L/Bal. 6 mm L/Bal. 6 mm  
 D.O.A. 07/01/2021 D.O.I. 13/01/2021  
 Survey held at 3A AUTOMOBILE  
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or  
REAR O/S  
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair limit - 17K</u>
	<u>Finalised amount is \$ 800 / 2 days of lump sum repair</u>
	<u>RED: 845.6:51%</u>

Date/Time, File Pass to?  : Prel. Report  
 : Final Report  
 Date/Time, File Return to?  
 2) \_\_\_\_\_  
 Repair Format: \_\_\_\_\_  
 Lump Sum / L.S.K. (\$) \_\_\_\_\_

Days Of Repair: 2  
 Resurvey No. of Trip: \_\_\_\_\_  
 Add Fee:  : Site Insp (\$ \_\_\_\_\_)  
 : Interview (\$ \_\_\_\_\_)  
 : Tech. Invs (\$ \_\_\_\_\_)  
 : Weekend (\$ \_\_\_\_\_)

Survey Fee:	
Transportation:	
\$ + RS. \$	
Photos	
Others	
TOTAL	