

REF: CS/SM021000547/RIK#3 12760
 A&S. REC. BY: Pasul

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SLM 8784H
 at Workshop m/s 3A AUTOMOBILE
 of 1002, BUKIT MERAH LN 3 #01-73
 Insured: SMD
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SLM 8784H Yr Regn: 2017 / APR
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: KIA CERATO FORTE KS1-6A c.c. 1591
 Colour: BROWN A/C: Insured / Std / NI / NA
 Sp. Reading: 120504 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: KMFJ411MHS714280
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: Order / Janned / Leaked / Burnt or _____
 Brake: Order / Janned / Leaked / Burnt or _____
 Modi: Nil / Rim / STD A/Rim or _____
 Tyre Size: F: 195/65R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 58k
 IDAC Accident Report: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Front Rear
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 07/01/2021 D.O.I. 13/01/2021
 Survey held at 3A AUTOMOBILE
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
REAR O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Repair Limit - 17K</u>

Date/Time, File Pass to? : Prel. Report
 : Final Report
 Date/Time, File Return to? _____
 Days Of Repair: _____
 Resurvey No. of Trip: _____
 Survey Fee: _____
 Transportation: _____ \$ + RS. _____ \$
 Photos _____
 Others _____
 TOTAL _____

Add Fee: : Site Insp (\$ _____)
 : Interview (\$ _____)
 : Tech. Invs (\$ _____)
 : Weekend (\$ _____)

Report Format: _____
 Lump Sum / I.B.H. (\$ _____)



3A Automobile Pte Ltd

Office Address : No 120 Lower Delta Road #02-15 Singapore 169208 Tel: 6223 1122 Fax: 6738 6666

Estimate Report

To : Sompo Insurance Singapore Pte Ltd

Vehicle Number: SLM 8784 H

Make and Model: KIA FORTE

Tel :

Date Of Accident: 7/1/2021

Fax :

Time Accident: 2000HRS

Attn: Claim Department

Unit	List Items	Unit Price	Prices
1 pc	REAR BUMPER repair <i>Scr ✓</i>	\$ 688.00	\$ 688.00
1 pc	BUMPER REFLECTOR RHS <i>X</i>	\$ 95.00	\$ 95.00
8 pcs	REAR BUMPER CLIPS <i>✓</i>	\$ 3.00	\$ 24.00

S/Total		\$ 807.00
Less -20%		\$ (161.40)
		\$ 645.60

	To Provide Skill Labour & Material to do Surface Treatment / Epoxy Treatment and to Respray with 2K Paint on the Affected Areas & Components with Oven Spray Booth Facilities	\$ 600.00	\$ 600.00 <i>200</i>
	To Remove & Replace the Damaged Parts as Listed Above, including Reinstatements of necessary Attachments & Fittings to Facilitate Repairs; Jack, Panel Beat & Reshape the Affected Parts & Components, Correct & Realign the Necessary Parts	\$ 400.00	\$ 400.00 <i>200</i>

Total

\$ 1,645.60

Regards,

Yours faithfully,

3A Automobile Pte Ltd

Person to contact : Alwin / Enjo

Mobilephone : 9786 8677 / 6738 7777

Rasul
Hp 970 10568
2 days
4/3

13/01/2021 01420

Reply after repair

email: rasul@lkkauto.com

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Insured / Std / NI / NA
 A/C:
 BLACK
 Colours
 Car Oil

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	08/01/2021 17:59 (SGT)
Date of Accident	07/01/2021 20:00 (SGT)
Exact Location of Accident	701 Woodlands Drive 40, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLM8784H
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	Yes
Name Of Registered Owner	BKW RENT A CAR PTE LTD
Company Reg No	2XXXXX276D
Email Address	KENNETH.TAN@BKW.SG
Mobile Phone No	(Phone) +65-97898888
Alternative Phone No	(Office) +65-67387777

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Forte
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	Yes
Policy Number	999993729
Cover Note Number	-

DRIVER

Name of Driver	EU TEIK LEONG
NRIC No	SXXXX039B
Date Of Birth	09/01/1952
Occupation	Indoor

Date Of Driving Pass	16/03/1985
Driving experience	35 YEARS AND 10 MONTHS
Gender	Male
Mobile Number	(Phone) +65-97868677
Alt. Phone Number	-
Email Address	ALWIN.NG@BKW.SG
Address	120 LOWER DELTA ROAD #02-15 CENDEX CENTRE SINGAPORE
Address complement	-
Postcode	169208
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Hirer
Does Driver Own Other Vehicles?	Yes
Vehicle Registration Number of Other Vehicle Owned by Driver	SKU3418T
Insurance Company of Other Vehicle Owned by Driver	AIG

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Clear
Road Surface	Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	2
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No

PASSENGER 1

Name	OOI LAY HOON
Gender	Female

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

PLEASE REFER TO ATTACHED

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No
Was there any audio recorded?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLH7372X
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-

Contact Number	-
Address	-
Address complement	-
Postcode	-
Insurance Company Name	Sompo
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;


(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 
 Policyholder's Signature / Date & Time


 Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



Describe Circumstances of the Accident

On 7/1/2021, at approximately 8pm, I was waiting stationary for traffic to clear on 701 Woodlands Drive 210 before turning left into Woodlands Drive 40. The night was dry and clear weather. Suddenly, I felt another vehicle (SLH7372X) had ~~the~~ crashed into the right bumper back of the car I was driving (SLM8784H). No one was injured.

Declaration

We declare the foregoing particulars are true in every respect.

 
Policyholder's Signature / Date & Time


Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID:	276D
Vehicle No.:	SLM8784H
Vehicle to be Exported:	No
Intended Deregistration Date:	13 Jan 2021
Vehicle Make:	KIA
Vehicle Model:	FORTE K3 1.6A
Primary Colour:	Brown
Manufacturing Year:	2017
Engine No.:	G4FGGH647462
Chassis No.:	KNAFJ411MH5714284
Maximum Power Output:	95.3 kW (127 bhp)
Open Market Value:	\$12,082.00
Original Registration Date:	17 Apr 2017
First Registration Date:	17 Apr 2017
Transfer Count:	1
Actual ARF Paid:	\$12,082.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	16 Apr 2027
PARF Rebate Amount:	\$9,061.00
COE Expiry Date:	16 Apr 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$50,101.00
COE Rebate Amount:	\$31,354.00
Total Rebate Amount:	\$40,415.00

The information contained herein is correct as at 13 Jan 2021

OK

Brown





Merimen e-Claims



Used 2017 Kia Cerato K3 1.6A for



Singapore Parali

gcar mart.com/used_cars/info.php?ID=958767&DL=1053

► Kia Cerato K3 1.6A

Overview

Financial

Accessories

Similar

Research

Photos

Map

AUTOMOBILE

CARTIMES



An Award-Winning Premier Automotive House



Price \$58,800

Depreciation \$8,420 /yr
[View models with similar depre](#)

Reg Date 17-Apr-2017
(6yrs 3mths 3days COE left)

Mileage N.A.

Manufactured 2017

Road Tax \$738 /yr

Transmission Auto

Dereg Value \$40,487 as of today (change)

OMV \$12,181

COE \$50,101

ARF \$12,181

Engine Cap 1,591 cc

Power 95.3 kW (127 bhp)

Curb Weight 1,295 kg

No. of Owners 2

Type of Vehicle Mid-Sized Sedan

Features

Reliable 1.6L 4 Cylinders 16 Valves, DOHC Dual CVT Engine, 127Bhp, 6 Speed Auto Transmission, ABS And SRS Airbags. [View specs of the Kia Cerato K3 \(2013-2018\)](#)



62

e.

57.5