



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI21000548/Ktd3n2	Date: 24/03/2021
			Code: AGI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SGX 4897T	Veh. Inspected	SDJ 303B	
Policy No.		Coverage (\$)	0.00	
Claim No.	C10008636/CH	Excess (\$)	0.00	
Assign From	IVY RATILLA	Assign Date	12/01/2021	
2. Vehicle Particulars & Condition				
Make & Model	MERCEDES C200 (A)	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	WDD2050772R519148	Colour	WHITE	
Odometer	22663 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	225/45 R18	BRIDGESTONE	8 mm	
L/H Front Tyre	225/45 R18	BRIDGESTONE	8 mm	
R/H Rear Tyre	245/40 R18	BRIDGESTONE	8 mm	
L/H Rear Tyre	245/40 R18	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S REAR BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	08/01/2021	Inspection Date	13/01/2021	
Survey held at	BLK 10 AMK IND.PARK 2A# 01-05			
Repairer	OPTIMA WERKZ PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	