



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 10.01.2021
Emailed : 22/01.2021, 3.30pm
Date Survey : 12.01.2021 *11.30am*

VEHICLE NO : SMV 1950 G
MODEL : KIA NIRO 1.6 A SX
WIP : 27218

Material	:	\$	<u>2,154.40</u>
Labour	:	\$	<u>920.00</u>
Sub-Total	:	\$	<u>3,074.40</u>
REPAIR LIMIT	:	\$	<u>-</u>
Less Excess	:	\$	<u>600.00</u>
Total	:	\$	<u>2,474.40</u>
GST 7%	:	\$	<u>173.21</u>
Grand Total	:	\$	<u>2,647.61</u>
Finalise By/Date	:		<u>LOI / 19/01/2021</u>

2,154.40

1,050.00

3,204.40

600.00

2,604.40

182.31

2,786.71

Re-finalised 22/1/21.

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
+ 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name /LEW YIP KEONG LAWRENCE Reg No/Reg Date SMV1950G / 21/09/2020 Date In/Mileage 12/01/2021/ 4567 Chassis/Package KNACC81CVL536106C /# Engine No G4LEKS600328 Make/Model KIA/NIRO 1.6 A SX SR ASY PE Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK
12/01/2021	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	22/01/2021/ 11:11	BLC	260 / AiTing	27218			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE FRONT BUMPER LOWER PANEL, FRONT BUMPER, FRONT SKID PLATE, REPAIR ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 400.00
E PNT98000 RESPRAY ON FRONT BUMPER, SKID PLATE, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 480.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY SUNDRIES								✓ 20.00
X EXC EXCESS FOR OWN DAMAGE								-600.00
X COVER-FR BUMPER UPR					1.00	✓ 637.00	20.00	509.60
X LOGO ASSY-KIA SUB					1.00	✓ 51.00	20.00	40.80
X COVER-FR BUMPER,LWR					1.00	✓ 373.00	20.00	298.40
X SKID PLATE-FR BUMPER					1.00	✓ 60.00	20.00	48.00
X GRILLE ASSY-RADIATOR					1.00	✓ 441.00	20.00	352.80
X LAMP ASSY-FRONT FOG,LH					1.00	? 223.00	20.00	178.40
X GRILLE-FRONT BUMPER					1.00	✓ 131.00	20.00	104.80
X STIFFNER-FR BPR LWR					1.00	? 116.00	20.00	92.80
X BEAM COMPLETE-FR BUMPER					1.00	? 661.00	20.00	528.80
Z TEXT AIG OD CLAIM DOA : 10.01.21 SURVEYOR STEVE LKK 12.01.21 POLICY NO: 2070136307, REPAIR 03 DAYS								
Guarantee Your Warranty, Maintain with Cycle & Carriage!								

Parts	2,154.40	Nett	2,604.40
Labour	1,030.00	7% GST on	182.31
Standard Menu	0.00		
Specialist Job	0.00		
Diagnostics Job	0.00	Total Payable	2,786.71
Sundry/Others	-580.00		
Total(w/o GST)	2,604.40		

This is not an official tax invoice.
 This is a computer generated document, no signature is required.