



Exceptional Journeys

Surveyor : STEVE LKK
Claim : AIG OD
DOA : 12.02.2021
Emailed : 05.07.2021, 2.20pm
Date Survey : 12.01.2021

VEHICLE NO : SLX 1885 M
MODEL : KIA FORTE K3 1.6 A L
WIP : 27293

Table with 2 columns: Description and Amount. Rows include Material (\$2,379.20), Labour (\$2,300.00), Sub-Total (\$4,679.20), Less Excess (\$-), Total (\$4,679.20), GST 7% (\$327.54), Grand Total (\$5,006.74), and Finalise By/Date (LOI / 05/07/2021).

[X] REVERT BACK WITHIN 7 DAYS, OTHERWISE WILL PROCEED WITH INVOICING

[] SURVEYOR'S REPORT REQUIRED

[] REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends + 0 Days (0) Public Holiday
TOTAL DAYS REPAIR TOOK = 0

[] TP claim

[] Claim GIA / LTA fee

[] Claim Loss of Use / Rental

[] Claim Medical Fee / Others

[] Third Party Report



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**PRO-FORMA INVOICE**

Co Reg No : 199405410K

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000 15/01/2021	Cust No/Name	/Khoo Seng Tat
	Reg No/Reg Date	SLX1885M / 20/03/2018
	Date In/Mileage	15/01/2021/ 59951
	Chassis/Package	KNAFJ411MJ5762074 /#
	Engine No	G4FGHH692349
	Make/Model	KIA/FORTE K3 1.6 A L 189
	Colour/Trim	B4U GRAVITY BLUE / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	05/07/2021/ 14:14	BLK	260 / AiTing	27293

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE RH FRONT DOOR, RH REAR DOOR, REPAIR RH ROCKER PANEL, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME				✓ 800.00
E PNT98000 RESPRAY ON RH FRONT DOOR, RH REAR DOOR, RH ROCKER PANEL AND ALL OTHER AFFECTED AREAS TO THE SAME				✓ 1050.00
E PNT88000 TRANSFER RH FORNT DOOR ATTACHMENTS TO NEW PANEL				✓ 120.00
E PNT88000 TRANSFER RH REAR DOOR ATTACHMENTS TO NEW PANEL				✓ 120.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS				✓ 40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM				✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE				✓ 120.00
M SUNDRY SUNDRIES				✓ 20.00
X PANEL ASSY-FRONT DOOR,RH	1.00	✓ 1542.00	20.00	1233.60
X PANEL ASSY-REAR DOOR,RH	1.00	✓ 1361.00	20.00	1088.80
X BLACK TAPE-FR DR RR,RH	1.00	✓ 12.00	20.00	9.60
X TAPE-RR DR FRAME BLACK RR,RH	1.00	✓ 8.00	20.00	6.40
X BLACK TAPE-FR DR FRAME UPR,RH	1.00	13.00	20.00	10.40
X BLACK TAPE-RR DR FRAME UPR,RH	1.00	11.00	20.00	8.80
X FILM-ANTI CHIPPG RH	1.00	27.00	20.00	21.60
Z TEXT AIG OD CLAIM. DOA : 12.01.21 SURVEYOR STEVE LKK 12.01.21 POLICY NO : 1800025612-01				

Guarantee Your Warranty, Maintain with Cycle & Carriage!

Parts	2,379.20		Nett	4,679.20
Labour	2,240.00	7% GST on	4679.20	327.54
Standard Menu	0.00			
Specialist Job	0.00		Total Payable	5,006.74
Diagnostics Job	0.00			
Sundry/Others	60.00			
Total(w/o GST)	4,679.20			

This is not an official tax invoice.
This is a computer generated document, no signature is required.



Exceptional Journeys

INSURANCE CO. : AIG

Supplementary Parts For Registration No.: SLX 1885 M

	<u>Materials</u>	<u>Cost (\$)</u>
1	Black tape-Fr dr frame upr, RH	13.00 / nec
2	Black tape-Rr dr frame upr, RH	11.00 / nec
3	Film-anti chippg RH	27.00 / nec
	Total	51.00
	Less 20% discount	10.20
	Total after discount	40.80
	7% GST	2.86
	Grand total	<u>43.66</u>

Thank You.

Yours faithfully

LOI AI TING
SENIOR OFFICER - ADMIN
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240



Fault Code Searching

Rescan

Save



8/8

System	Status	Result
ENGINE	No Current DTC	Good
AT	No Current DTC	Good
ABSESC	No Current DTC	Good
AIRBAG	No Current DTC	Good
EPS	No Current DTC	Good
SJB	No Current DTC	Good

System	DTC	Description	State
	No Current DTC		

S/W Ver. M-E-K-01-00-0237

VCI Ver. 02.49

ECU Ver. M-E-K-01-00-0178

OS Ver. Android 10