

ASS. REC. BY:

REF: CS3/ASM21000594/Gvf3

Special Instruction:

Surveyor: GQASSIGNMENT (Office)From (Person): Chan Kian Chuan of AXA Date/Time: 13/1/2021 10:01 AM

Estimated Cost: _____ Bill to: _____

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: GBJ 4009Z Insured: SHD 6960Uat Workshop m/s GARAGE 13 Tel: 6385 1171of 8 kaki bukit ave 4 #03-46 Premier@KBPolicy No: _____ Claim No: S1M030DD

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 6.1.2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 13-01-2021 10.16A.M Person Contacted: IRENE Vehicle IN/OUT

Date/Time	Action/Instruction (☒) Estimate
	GBJ 4009Z - NA/EQI21000370/r3 DOA : 06/01/2021
	SHD 6960U- NA/EQI21000370/r3 DOA :06/01/2021
14/1/21	Send IA via Smart Claim
14/1/21	Submit PRS,repair range \$7,000-\$8,000 (8 days) ,MV\$49,000