

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/198R GS1 Reg. No. 19-900/198-R					
		Affiliated to Federation Internation	nale Des Experts En	Automo	bile	
	AUTO & GENERA	L INSURANCE (S) PL		Ref:	CS/AGI21000612/Dvd3e2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE		Date:	05/03/2021	
				Code:	AGI	
1.	1. Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJF 3152A	Veh. Inspected		SGY 9819G	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	C10008620/CH	Excess (\$)		0.00	
	Assign From	IVY RATILLA	Assign Date		13/01/2021	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA WISH	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2015	
	Chassis No.	JTDGG20W50J002783	Colour		BEIGE	
	Odometer	106784 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	3. Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	TOYO		5 mm	
	L/H Front Tyre	195/65 R15	TOYO		5 mm	
	R/H Rear Tyre	195/65 R15	TOYO		5 mm	
	L/H Rear Tyre	195/65 R15	TOYO		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT AND REAR PORTION.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	06/01/2021	Inspection Date	•	13/01/2021	
	Survey held at JWG INTERNATIONAL PTE LTD					
	10 ANG MO KIO INDUSTRIAL PARK 2A #03-08 AMK AUTOPOINT SINGAPORE 568047					
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					

12 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: