

Surveyor: Bryan

REF: CS1/LPC21000626/Dqd3

Special Instruction:

From (Person): ONG LI LI of LPC ASSIGNMENT (Office) Date/Time: 12/01/2021
Estimated Cost: Bill to:

18300.30

Third Parties:

Claimant:

Surveyor:

Workshop: PREMIUM AUTO

OD/TP Re-inspection / Evaluation

To Inspect Vehicle No: SLA 1587A Insured: YN 4504S
at Workshop m/s PREMIUM AUTO Tel: 6366 2323
of 55 UBI ROAD 1

Policy No: Claim No: 21916

Sum Insured: Excess:

Make of Veh: D.O.A. 08/06/2019
(Client's Record)

H.O.D. Endorsement/Date:

Date/Time: Person Contacted: Vehicle IN / OUT

Date/Time: Confirmed with Final Fig days (Red \$ / %; Original 12 days)

Date/Time: 21/01/21 Submit Final Fig \$15404, 12 days (Red \$2896.30/ 16 %; Original 12 days)

Date/Time	Action/Instruction
	SLA 1587A-X
	YN 4504S-X
01/12/21	re-open ref. for amend report to final fig \$18300.30, 12 days (Red \$0/-, 0%) as last time, LPC did not provide us supplementary list. <i>Celine 01.12.2021</i>

Para(1) : Parts found not replaced (To highlight R or UB, LR, Etc)

Para(2) : Comments on consistency of damages (Parts Not Consistent : NC)

Para(3) : Nett Value

Market Value :

Salvage Value :

Nett Value :

Inspected/
Evaluated by:

Fee Charged:

Basic & Add
Transport
Photos
Others
Total

Date:

1) Date/Time 01/12/21 File Pass to Typist

2) Date/Time File Return to

3) Date/Time File Pass to

4) Date/Time File Return to

5) Date/Time File Pass to

6) Date/Time File Return to