

ASS. REC. BY:

REF: CS3/ASM21000635/Qvf3

Special Instruction:

Surveyor: SUN PIN

ASSIGNMENT (Office)

From (Person): Tan Jun Hong of AXA Date/Time: 13/1/2021 4:31 PM

Estimated Cost: Bill to:

OD-TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: FBK 3258Y Insured: SHA 353G

at Workshop m/s Lian Chin Heng Motor & Carriage Pte Ltd Tel: 6758 6609 / 8200 8888

of BLK 22 WOODLANDS LINK #01-35 SINGAPORE 738734

Policy No: Claim No: S1M0300T

Sum Insured: Excess:

Make of Veh: D.O.A. 06/01/2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement:

Date/Time: 13-01-2021 4.41P.M Person Contacted: JASON Vehicle IN/OUT

Date/Time	Action/Instruction (X) Estimate
	FBK 3258Y-X
	SHA 353G- CS/FCI18008549/Utn2 DOA :09/05/2018
25/2/21	Send IA via Smart Claim
25/2/21	Submit PRS, repair range \$1,000-\$1,5000 (2 days)