

(ADDITIONAL PARTS CH

	DATE	TAKEN BY
SILENCE 5 FLOOR		
PUMPER - 7/6A113 OVERSLAM		
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		

STEIN

MODEL: STONIC

Car No: SMN 3878L WIP 21336

ADDITIONAL PARTS CHANGE

S/No	Parts Name	? /Supp	CSA Sign	Photo Taken	Remarks
1	Replace floor panel	2/Supp		/	
2	Replace End panel	3/Supp		/	
3	RXI fuel tank	3/Supp		/	
4	RXI Exhaust Muffler	3/Supp		/	
5	Fit Reinforcement bar	3/Supp		/	
6	Painting floor panel	3/Supp		/	
7	Painting End panel	3/Supp		/	
8	Painting RH rear fender	3/Supp		/	
9	Replace both rear lamp housing	3/Supp		/	
10	Painting both rear lamp housing	3/Supp		/	
11		3/Supp			
12	Add 09 day - Total 19 day	3/Supp			
13		3/Supp			
14	Masker tank	3/Supp		/	CRN
15		3/Supp			
16		3/Supp			
17		3/Supp			
18		3/Supp			
19		3/Supp			
20		3/Supp			

DATE

TAKEN BY

Model:

Stone

Surveyor:

Steve - Mkl

PHOTO BEFORE PAINT
PHOTO AFTER PAINT
PHOTO OF DAMAGED PARTS (DPS)
PHOTO OF COMPLETE BENCH