

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 13 Jan 2021)
 Parts: 192 HYUNDAI IONIQ HYBRID 1.6 GLS DCT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: ComfortDelGro Engineering Pte Ltd/SHB2887P/13/01/2021 09:05
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT FENDER BLUE-DRIVE LH	20.00	0.00	*26.60 FL
F=Franchise part. L=ListItemDisc.						
Sub Total (\$\$)						26.60 <i>nee</i>
- List Item Discount on L Items (\$\$)						5.32
Total Parts (\$\$)						21.28 ✓

ComfortDelGro Engineering Pte Ltd/SHB2887P/13/01/2021 09:05. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Lim Tien Siong

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			✓ 11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	PANEL BEATING - FRT FENDER LH	New	350 400.00
2	SPRAY PAINTING - FRT BUMPER	New	500 600.00 850
Gross Labour Cost (S\$)			1,000.00

ComfortDelGro Engineering Pte Ltd/SHB2887P/13/01/2021 09:05. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Tauhin 97495749
'WP' 13/1/21 @ 5pm
2 days
P/S Resurvey after repair.
Tanjoh @ 1/1/21.
21.28
11
850
882.28
2 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: