

IMMEDIATE ADVICE

To: AXA Insurance Pte Ltd DATE: 15/1/2021

Survey details

Date of loss	6/1/2021
Date of appointment	13/1/20201
Date of survey	14/1/2021
Location of survey	V-TECH AUTO SERVICE

Vehicle Details:

Claim Type:	THIRD PARTY	
Vehicle number	SLG 8819Z	
Make and Model	SUBARU LEVORG 1.6GT-S AWD CVT	
Date of registration	18/10/2016	
Excess		
Market Value	\$77,000.00	
Parf Rebate	\$53,599.00	
Nett Loss	\$23,401.00	

Repair details

Initial Estimate	

Proposed/Revised repair cost:

Parts		
"Check items (Estimated)		
Labour		
Total		
Lump Sum (Estimated)		
Number of days of repair	8 days (est)	

Remarks:

The estimated repair cost of the damaged vehicle is in the region of \$5,000.00-\$6,000.00