

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD		Ref:	CS3/ASM21000679/R1vf3e2	
	8 SHENTON WAY TOWERSINGAPO			Date:	27/01/2021	
	ATTN : JOHNNY Y	ONG		Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SLE 5276U	Veh. Inspected		SLG 8819Z	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	S1M030IV	Excess (\$)		0.00	
	Assign From	JOHNNY YONG	Assign Date		14/01/2021	
2.	Vehicle Particulars & Condition					
	Make & Model	SUBARU LEVORG 1.6GT-S	c.c		1600	
	Engine No.	HIDDEN	Year of Reg.		2016	
	Chassis No.	JF1VM4K55GG002581	Colour		BLACK	
	Odometer	78038 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	225/45 R18	GOODYEAR		6 mm	
	L/H Front Tyre	225/45 R18	GOODYEAR		6 mm	
	R/H Rear Tyre	225/45 R18	GOODYEAR		6 mm	
	L/H Rear Tyre	225/45 R18	GOODYEAR		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	E SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	13/01/2021	Inspect Date / 1	Гіте	14/01/2021 (05:17 PM)	
	Survey held at	Survey held at V-TECH AUTO SERVICE				
		No.1 SOON LEE STREET #06-04/05/06/07 PIONEER CENTRE SINGAPORE 627605				
5a.	. Remarks					
	B) THE REPAIR ES THE REPAIRER W C) ENCLOSED PL	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000				
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 8 Working Days					

Report Ref No. CS3/ASM21000679/R1vf3e2

Inspected By

Automotive Assessor

MOHAMMED RASUL BIN MOHD YUNUS

K.K.LAU CPT(RET)

PEOP Auto Occupion OAF Licensed Association

REGD Auto Consultant-SAE, Licensed Appraiser

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$