

ASS. REC. BY:

REF: CS3/ASM21000679/R1vf3

Special Instruction:

Surveyor: RASULASSIGNMENT (Office)From (Person): YONG Johnny of AXA Date/Time: 14/1/2021 11:42 AM

Estimated Cost: _____ Bill to: _____

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLG 8819Z Insured: SLE 5276Uat Workshop m/s V-Tech Auto Service Tel: 6264 6222of 1 Soon Lee Street #06-04/05 Pioneer CentrePolicy No: _____ Claim No: S1M030IV

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13-1-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

"WP"

H.O.D. Endorsement: _____

Date/Time: 14-01-2021 2.21P.M Person Contacted: MEE KEY Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SLG 8819Z- ☒
	SLE 5276U- ☒
15/1/21	Send IA via Smart Claim
15/1/21	Submit PRS, repair range \$5,000-\$6,000 (8 days)