

ASS. REC. BY:

REF: CS/AGI21000690/Gvf3

Special Instruction:

Surveyor: GQ

ASSIGNMENT (Office)

From (Person): IVY RATILLA of AGI Date/Time: 14/1/2021 3:14 PM

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMQ 6728B Insured: SLN 8821D

at Workshop m/s HUAT HOCK MOTOR WORKSHOP Tel: 8161 6988

of Blk 3012 Bedok North Ave 4 # 01-2054

Policy No: Claim No: C10008671/ST

Sum Insured: Excess:

Make of Veh: D.O.A. 13-01-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 14-01-2021 3.39P.M Person Contacted: DAVID Vehicle ☒ IN OUT

Date/Time	Action/Instruction (☒) Estimate
	SMQ 6728B- X
	SLN 8821D- X