ASS. REC. BY: CASIL REF: CC3 A1421	ovo 699 R129 1 1489
ASS	GNMENT
From: Date:	Veh No: SMS 5149T Yr Regn: 2020/PG/
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD ITPI WS ITP RES I OD RES I EVA I INV I MIV	Truck / Trailer or
To Inspect Vehicle No: SMS 5(49T	Make: SKODA OCTAVIA RS2-0,751 C.C 1984
at Workshop m/s Volksnagen	Colour WHITE A/C: Insured / Std / NI / NA
of 17 purs prof 6	Sp.Reading 22 198 T/Radio: Insured / Std / NI / NA
Insured: Plh	Eng/No:
Pollcy No.	CINO: TMBBU7NE9LOUS3813
Claims No.	Gen. Cond: Good I Fair Poor I Burnt
Sum Insured: Excess:	Steering: Norde / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Inforder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / 8/Rim / STD A/Rim or
	Tyre Size: F: 225 35 R19
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	-11551551
repair at the time of inspection.	TOYO/YOKO or
Bal. or Market Value: 127K	Front Rear
IDAC Accident Rport: Consistent? ; Yes or No	R/Bal. mm R/Bal. mm
GIA / PR Seen: Consistent?: Yes or No	UBal. 6 mm UBal. 6 . mm D.O.I. 14012021
Est Repairs: days Res.: Yes or No	17/01/001
Lum Sum: % · 3 Val.: Yes or No	Survey held at Volkswarran
CA / REV / REP. / 24 HRS	Des. of Damages. Fit Rear O/S N/S U/C Rooftop or
Vehicle: IN /	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
from (init - 74K	
:	
<u> </u>	•
Dale/Time, File Pass to? Prell. Report	Days Of Repair:
; Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
₂₎ Ad	d Fee:: Site Insp (\$)s + RSsi
•	· Interview (\$) Photos
Reput Forniel:	:Tech, Invs (\$) Others
Lucrap State / L.B.A: (%)	: Weel and (\$
-	TOTAL

. ;••

w.

26 Leng Kee Rd Singapore 159104 Biz. Reg. No.: 199101494Z GST No.: M200985052







Quotation

Non binding - Preview

Company AIG ASIA PACIFIC INSURANCE P/L 78 Shenton Way #07-16 AIG Building Singapore 079120 Customer Details: Mr CHUA WEE KUAN BLK 671B JURONG WEST ST 65 #14-106 SINGAPORE 642671

1/4 Page Document no. 14-01-2021 Document date 5211043795 Customer no. 201009404M Customer GST-ID Dealer 30001 Job order number 2021001779/1 13-01-2021 Job order date TIOW CHUAN CHEE Service Advisor

License plate SMS5149T Model code SMS5149T First registration 28-02-2020 VIN TMBBU7NE9L0053813 Model Octavia RS 2.0 I TSI 180kW w/o WC MY20 22,198

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	i	pcs.	480.00	#1	480.00	513.60
	R&R REAR EXHAUST	1	pcs.	840.00	#1	840.004	20 898.80
	R&R REAR SUB FRAME	4	pcs.	840.00	#1	3,360.00	3,595.20
	R&R ROOFLINING	3	pcs.	840.00	#1	2,520.00	2,696.40
	R&R FUEL TANK	3	pcs.	840.00	#1	2,520.00	2,696.40
	CHANGE LINE ASSIST SYSTEM CALIBRATION	1	pcs.	840.00	#1	840.00	898.80
5E0807221AA	Cover For 1 rani	1	pcs.	1,539.67	#1	1,539.67	1,647.45
5E0919485H	Sensor Bra	1	pcs.	13.05	#1	13.05	13.96
5E0919486H	Sensor Bra	1	pcs.	13.05	#1	13.05	13.96
5E0807248E	Buffer 7 7 FRT BUMPER FOAM 7 -	1	pcs.	49.49	#1	49.49	52.95
5E5827023E	Rear Trunk St	1	pcs.	3,255.00	#1	3,255.00	3,482.85
5E5845049AANVB	Rear Windo REAR W/SCREEN The photo	1	pcs.	811.06	#1	811.06	867.83
D 169300M2	1k Window Adhesive	2	pcs.	51.11	#1	102.22	109.38
D 00940104	All Purpose Cleaner	1	pcs.	94.03	#1	94.03	100.61
D 00920002	Primer M	1	pcs.	27.39	#1	27.39	29.31
D 181802M1	Activator For Precoated W Nec	1	pcs.	25.14	#1	25.14	26.90
D 00950025	Applicator No	2	pcs.	10.12	#1	20.24	21.66
5E5860523 9B9	Strip 3RD BRAKE LIGHT STRIP	1	pcs.	20.54	#1	20.54	21.98
5E5827705J	Decklid We REAR BOOT WETHERSTRIP	1	pcs.	130.64	#1	130.64	139.78
WHT007341	Rivetted Cap Nut	2	pcs.	2.28	#1	4,56	4.88
3V0853621A FOD	Skoda Embl re	1	pcs.	64.32	#1	64.32	68.82
5JA853687 2ZZ	Inscriptio EMBLEM - SKODA 7 100 /	1	pcs.	73.51	#1	73.51	78.66
5E0853687 2ZZ	Inscriptio EMBLEM - OCTAVIA	1	pcs.	82.45	#1	82.45	88.22
5E0853687R NTA	Inscriptio EMBLEM - RS	1	pcs.	82.45	#1	82.45	88.22
5E5807421B	REAR BUMPER 2006	1	pcs.	1,371.14	#1	1,371.14	1,467.12
5E5807521F 9B9	Spoiler de/	. 1	pcs.	178.34	#1	178.34	190.82
5E5807441A GRU	Cover For REAR BUMPER TOWING COVER Bracket	1	pcs.	7.25	#1	7.25	7.76
5E5807364A	Bracket EXHAUST PIPE CHROM BRACKET RIETAL. Tail P	zen/	pcs.	20.41	#1	20.41	21.84
5E0253682H	EXH PIPE CHROM RH 7 27		pcs.	466.09	#1	466.09	498.72
5E5807305B	Reinforcem 77	1	pcs.	448.02	#1	448.02	479.38

26 Leng Kee Rd Singapore 159104

Biz. Reg. No.: 199101494Z GST No.: M200985052







Quotation

Non binding - Preview

Company AIG ASIA PACIFIC INSURANCE P/L 78 Shenton Way #07-16 AIG Building Singapore 079120

Customer Details: Mr CHUA WEE KUAN BLK 671B JURONG WEST ST 65 #14-106 SINGAPORE 642671

2/4 Page Document no. 14-01-2021 Document date 5211043795 Customer no. 201009404M Customer GST-ID 30001 Dealer 2021001779/1 Job order number 13-01-2021 Job order date TIOW CHUAN CHEE Service Advisor

License plate	Model code	First registration 28-02-2020	VIN	Model	Mileage
SMS5149T	5E36UDR3		TMBBU7NE9L0053813	Octavia RS 2.0 I TSI 180kW w/o WC MY20	22,198

5E0807838B 9B9 5E5807863 5E5807864 5E5807393 5E5807394 WHT003737 N 10621301 5E5919485C 5E5919485C 5E5919486C 5E5919485B 5Q0919275B GRU 5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Connecting BUMPER END TRIM LH Connecting BUMPER END TRIM RH Retaining BUMPER CTR BRACKET LH Retaining BUMPER SIDE BRACKET LH Guide Piec BUMPER SIDE BRACKET LH Guide Piec BUMPER SIDE BRACKET RH The sum of the s	1 1 1 1 1 1 6 10 1 1 2 2 2	pcs. pcs. pcs. pcs. pcs. pcs. pcs. pcs.	28.48 28.48 65.74 65.74 20.46 20.46 0.19 1.80 11.63 11.63 11.63 164.62 1.28	#1 #1 #1 #1 #1 #1 #1 #1 #1	28.48 28.48 65.74 65.74 20.46 20.46 1.14 18.00 11.63 11.63 23.26 329.24	30.47 70.34 70.34 21.89 21.89 1.22 19.26 12.44 12.44 24.89 352.29
5E0807838B 9B9 5E5807863 5E5807864 5E5807393 5E5807394 WHT003737 N 10621301 5E5919485C 5E5919486C 5E5919485B 5Q0919275B GRU 5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Connecting BUMPER END TRIM RH Retaining BUMPER CTR BRACKET LH Retaining BUMPER CTR BRACKET RH RUMPER SIDE BRACKET RH Guide Piec BUMPER SIDE BRACKET RH RUMPER SI	1 1 1 1 6 10 1 1 2 2 2	pcs. pcs. pcs. pcs. pcs. pcs. pcs. pcs.	65.74 65.74 20.46 20.46 0.19 1.80 11.63 11.63 11.63 164.62	#1 #1 #1 #1 #1 #1 #1 #1	65.74 65.74 20.46 20.46 1.14 18.00 11.63 11.63 23.26	70.34 70.34 21.89 21.89 1.22 19.26 12.44 12.44 24.89 352.29
5E5807863 5E5807864 5E5807393 5E5807394 WHT003737 N 10621301 5E5919485C 5E5919486C 5E5919485B 5Q0919275B GRU 5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Retaining BUMPER CTR BRACKET LH? Retaining BUMPER CTR BRACKET RH? Guide Piec BUMPER SIDE BRACKET LH? Guide Piec BUMPER SIDE BRACKET RH? Unbekannt? WUT Expanding Nut Sensor Bra Au Senso	1 1 1 6 10 1 1 2 2 2	pcs. pcs. pcs. pcs. pcs. pcs. pcs. pcs.	65.74 20.46 20.46 0.19 1.80 11.63 11.63 11.63 164.62	#1 #1 #1 #1 #1 #1 #1 #1	65.74 20.46 20.46 1.14 18.00 11.63 11.63 23.26	70.34 21.89 21.89 1.22 19.26 12.44 12.44 24.89 352.29
5E5807864 F 5E5807393 G 5E5807394 G WHT003737 N 10621301 5E5919485C 5E5919486C 5E5919485B 5Q0919275B GRU 5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Retaining BUMPER CTR BRACKET RH? Guide Piec BUMPER SIDE BRACKET LH? Guide Piec BUMPER SIDE BRACKET RH? Junction of the piec BUMPER SIDE BRACKET RH? Junction of the piec Bumper Side Bracket RH? Junction of the piece of the	1 1 6 10 1 1 2 2 2 1	pcs. pcs. pcs. pcs. pcs. pcs. pcs. pcs.	20.46 20.46 0.19 1.80 11.63 11.63 11.63 164.62	#1 #1 #1 #1 #1 #1 #1	20.46 20.46 1.14 18.00 11.63 11.63 23.26	21.89 21.89 1.22 19.26 12.44 12.44 24.89 352.29
5E5807393 5E5807394 WHT003737 N 10621301 5E5919485C 5E5919486C 5E5919485B 5Q0919275B GRU 5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Guide Piec BUMPER SIDE BRACKET LH? Guide Piec BUMPER SIDE BRACKET RH? Unbekannt? WUT Expanding Nut Sensor Bra Sensor Bra Sensor Bra Sensor Bra Sensor Primed Seal Ring Satin Black Bonding Agent For Plastic	1 6 10 1 1 2 2 2	pcs. pcs. pcs. pcs. pcs. pcs. pcs. pcs.	20.46 0.19 1.80 11.63 11.63 11.63 164.62	#1 #1 #1 #1 #1 #1	20.46 1.14 18.00 11.63 11.63 23.26	21.89 1.22 19.26 12.44 12.44 24.89 352.29
5E5807394 WHT003737 N 10621301 5E5919485C 5E5919486C 5E5919485B 5Q0919275B GRU 5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Guide Piec BUMPER SIDE BRACKET RH Jubekannt NUT Expanding Nut Sensor Bra Sensor Bra Sensor Bra Sensor Primed Seal Ring Satin Black Bonding Agent For Plastic	6 10 1 1 2 2 2	pcs. pcs. pcs. pcs. pcs. pcs. pcs.	0.19 1.80 11.63 11.63 11.63 164.62	#1 #1 #1 #1 #1	1.14 18.00 11.63 11.63 23.26	1.22 19.26 12.44 12.44 24.89 352.29
N 10621301 5E5919485C 5E5919486C 5E5919485B 5Q0919275B GRU 5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Sensor Bra Mules Sensor Bra Mules Sensor Bra Mules Sensor Bra Mules Sensor Primed Mules Seal Ring Satin Black Bonding Agent For Plastic	10 1 1 2 2 2	pcs. pcs. pcs. pcs. pcs.	1.80 11.63 11.63 11.63 164.62	#1 #1 #1 #1	18.00 11.63 11.63 23.26	19.26 12.44 12.44 24.89 352.29
N 10621301 5E5919485C 5E5919486C 5E5919485B 5Q0919275B GRU 5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B	Expanding Nut We Sensor Bra Me Sensor Bra Me Sensor Bra Me Sensor Primed Me Seal Ring Satin Black Me Sending Agent For Plastic Me	1 1 2 2 2 1	pcs. pcs. pcs. pcs.	11.63 11.63 11.63 164.62	#1 #1 #1 #1	11.63 11.63 23.26	12.44 12.44 24.89 352.29
5E5919485C 5E5919486C 5E5919485B 5Q0919275B GRU 5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Sensor Bra Auguster Sensor Bra Auguster Sensor Bra Auguster Sensor Primed Auguster Seal Ring Satin Black Auguster Seal Ring Satin Black Auguster Seal Ring Agent For Plastic Auguster Sensor Bonding Agent For Plastic Augus	1 1 2 2 2 1	pcs. pcs. pcs. pcs.	11.63 11.63 11.63 164.62	#1 #1 #1 #1	11.63 23.26	12.44 24.89 352.29
5E5919486C 5E5919485B 5Q0919275B GRU 5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Sensor Bra Mussesser Bra Mussesser Bra Mussesser Primed Mussesser Primed Mussesser Branch Black Mussesser Bonding Agent For Plastic Mussesser Bonding Bond	1 2 2 2 1	pcs. pcs. pcs.	11.63 11.63 164.62	#1 #1 #1	11.63 23.26	24.89 352.29
5E5919485B 5Q0919275B GRU 5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Sensor Bra Municipal Sensor Primed Municipal Seal Ring Satin Black Research Bonding Agent For Plastic Punicipal Search Research Res	2 2 2 1	pcs.	11.63 164.62	#1 #1	23.26	24.89 352.29
5Q0919275B GRU 5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B	Sensor Primed MAASSESSESSESSESSESSESSESSESSESSESSESSESS	2 2 1	pcs.	164.62	#1		352.29
5Q0919133 9B9 D 822150A1 D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Seal Ring Satin Black Resident Seal Ring Seating Black Resident For Plastic Resident Seating Resident	2 1				323.24	
D 822150A1 D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Bonding Agent For Plastic	1	pcs.		#1	2.56	2.74
D 180KU2A1 5E5945712A 5E0945106B 5E0945104B	Bonding Agent For Plastic Particle Plastic Adhesive Action	-	200	62.81	#1	62.81	67.21
5E5945712A 5E0945106B 5E0945104B	2k-Plastic Adhesive /	1	pcs.	78.91	#1	78.91	84.43
5E0945106B 5E0945104B			pcs.			691.81	740.24
5E0945104B	Taillight You /	1	pcs.	691.81	#1		
5E0945104B	Reflector REFLECTOR RH	1	pcs.	35.76	. #1	35.76	38.26
	Reflector REFLECTOR CTR	1	pcs.	54.64	#1	54.64	58.46
	Rear Panel 34/	. 1	pcs.	581.29	#1	581.29	621.98
5E5813309	End Plate END PANEL OUTER 344	1	pcs.	120.67	#1	120.67	129.12
D 007500A2	Zinc Spray New 2	1	pcs.	62.88	#1	62.88	67.28
D 180003M2	2k-Body Adhesive	1	pcs.	428.72	#1	428.72	458.73
D 476KD1M2	Sealant Can Be Sprayed M	i	pcs.	64.15	#1	64.15	68.64
5E0810970E	Wheelhouse RHR FENDER LINER	1	pcs.	120.88	#1	120.88	129.34
	Floor Pan Pepon	1	pcs.	522.30	#1	522,30	558,86
5Q0803274B	Retainer SPARE WHEEL BOLT BRACKET	1	pcs.	44.66	#1	44.66	47.79
5G0803899	Bolt For Spare Wheel Moun	1	pcs.	19.75	#1	19.75	21,13
5Q0907686C	Control Unit For Blind Sp	1	pcs.	864.09	#1	864.09	924.58
5E5907456A	Bracket CONTROL UNIT BLIND SPOT BRACKE	791	pcs.	22.66	#1	22.66	24.25
5E0253181CF	Middle Exh 7 7 REAR SILENCER	1	pcs.	4,124.43	#1	4,124.43	4,413.14
1K0253141AA	Dual Clamp 7	1	pcs.	62.04	#1	62.04	66.38

26 Leng Kee Rd Singapore 159104

Biz. Reg. No.: 199101494Z GST No.: M200985052



3/4





Quotation

Page

Non binding - Preview

Company AIG ASIA PACIFIC INSURANCE P/L 78 Shenton Way #07-16 AIG Building Singapore 079120 Customer Details: Mr CHUA WEE KUAN BLK 671B JURONG WEST ST 65 #14-106

SINGAPORE 642671

 Document no.
 14-01-2021

 Customer no.
 5211043795

 Customer GST-ID
 201009404M

 Dealer
 30001

 Job order number
 2021001779/1

 Job order date
 13-01-2021

 Service Advisor
 TIOW CHUAN CHEE

leat Shield For Exhaust M Strong assistance - AWP inwall	1 1	pcs.	excl. GST 112.50	#1	112.50	120.38
owing assistance - AWP inwill ABOUR FRT	1	pcs.	112.00			120.30
ABOUR FRT	1		195.00	#1	195.00	208.65
	2	pcs.	840.00			2,696.40
SDD AV DA INIT EDT	3	pcs.	800.00			1,712.00
SPRAY PAINT FRT ABOUR REAR	12	pcs.	840.00		/ -	0,785.60
	_	pcs.		60% 5%	10	7,704.00
	1	•			0	898.80
	1					
	1	•				898.80
	1					898.80
	4					1,605.00
	1					160.50
	1	•				85.60
	i	•			,	428.00
		ρω.	400.00		400.00	420.00
N. 7 (1. July 24) In 1965 (1. July 24)						
VLII. GOLGIGOD						
	PRAY PAINT REAR RANSFER BOOT LID MECHANISM REAR ELAR LUGGAGE TRIM REHICLE ON BENCH - CELETTE REAR WATER LEAK TEST RT NUMBER PLATE REAR W/SCREEN SOLAR FILM RIG DIRECT SETTLEMENT RIGO : 13/01/2021 P VEH: SGL6155B	PRAY PAINT REAR 9 8.8 R REAR W/SCREEN 1 RANSFER BOOT LID MECHANISM 1 8.8 R REAR LUGGAGE TRIM 1 8.8 R REAR SEAT 1 1/EHICLE ON BENCH - CELETTE 1 8.2 EAR WATER LEAK TEST 1 RT NUMBER PLATE 1 8.4 REAR W/SCREEN SOLAR FILM 1 8.6 DIRECT SETTLEMENT 1 8.7 (13/01/2021	PRAY PAINT REAR 9 pcs.	PRAY PAINT REAR 9 pcs. 800.00 8.8 R REAR W/SCREEN 1 pcs. 840.00 RANSFER BOOT LID MECHANISM 1 pcs. 840.00 8.8 R REAR LUGGAGE TRIM 1 pcs. 840.00 8.8 R REAR SEAT 1 pcs. 840.00 7 EHICLE ON BENCH - CELETTE 1 pcs. 1,500.00 8 RT NUMBER PLATE 1 pcs. 150.00 8 RT NUMBER PLATE 1 pcs. 80.00 8 RT NUMBER PLATE 1 pcs. 80.00 8 RT NUMBER PLATE 1 pcs. 400.00	PRAY PAINT REAR 9 pcs. 800.00 #1 Pcs. 840.00 #1 Pcs	PRAY PAINT REAR 9 pcs. 800.00 #1 \$40.00 \$20.

Quotation valid till 20-01-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	10,840.00	44,686.83	7%	3,886.88	55,526.83	59,413.71
is (e)follo	10.840 00 columb	44 686 85		3 886 88	gym = 12 - 150,526,63° (2)	59,41874

Customer	Service Advisor

26 Leng Kee Rd Singapore 159104

Biz. Reg. No.: 199101494Z GST No.: M200985052



4/4





Quotation

Non binding - Preview

Company AIG ASIA PACIFIC INSURANCE P/L 78 Shenton Way #07-16 AIG Building Singapore 079120

Customer Details: Mr CHUA WEE KUAN BLK 671B JURONG WEST ST 65

#14-106 SINGAPORE 642671 Document no. Document date Customer no. Customer GST-ID Dealer

Page

14-01-2021 5211043795 201009404M 30001 2021001779/1

Job order number Job order date Service Advisor

13-01-2021 TIOW CHUAN CHEE

License plate SMS5149T

Model code 5E36UDR3

First registration 28-02-2020

TMBBU7NE9L0053813

Octavia RS 2.0 I TSI 180kW w/o WC MY20

Mileage

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resury be fore paint

1	
of Driving Pass	
ing experience	04/10/2017
ander	3 YEARS AND 3 MONTHS
abile Number	Male
II. Phone Number	(Phone) +65-96969147
n add	(Home) +65-96969147
A Land	JC_ROMANTIC@YAHOO.COM.SG
ddress	BLK 671B JURONG WEST STREET 65
ddress complement	#14-106
ostcode	642671
the driver the policyholder?	Yes
No, Relationship of the Driver with the Insured	-
Ooes Driver Own Other Vehicles?	No
/ehicle Registration Number of Other Vehicle Owned by Driver	
nsurance Company of Other Vehicle Owned by Driver	-
	-
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident	Chain Collision
Weather Conditions	Clear
Road Surface	Wet
Thou Garlage	Wet
OTHER INFORMATION	
Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	5
Was anybody injured in the Accident?	Yes
Was any injured conveyed to hospital by ambulance?	No
Was any other material or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s)	
soliciting/offering accident claims assistance?	No
DETAILS OF POLICE ACTION	
Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	1
CIRCUMSTANCES OF ACCIDENT	
REFER TO SKETCH PLAN	
ATTACHMENT(S)	
Are accident photos available for attachment?	Ves
Was there any video captured by Car Camera?	Yes Yes
Was there any audio recorded?	No
DETAILS OF OTHER	R.VEHICLE PROPERTY 1
Vehicle Registration Number Vehicle Manufacturer	SGL6155B
Vehicle Model	Mercedes

Name of Driver Contact Number

Vehicle Model

Vehicle Variant Vehicle Colour Vehicle Category

Address

Junkorulo.....

Private car

Address complement Poetcode

_{a Of} Damage gis of property damaged in accident Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 23

Vehicle Registration Number SML9687S Vehicle Manufacturer Toyota Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

TDETAILS OF OTHER VEHICLE PROPERTY 3指

Vehicle Registration Number SKJ1859A Vehicle Manufacturer Volvo Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Private car Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

DETAILS OF OTHER VEHICLE PROPERTY 4

Vehicle Registration Number FBP3528S Vehicle Manufacturer Vehicle Model Vehicle Variant Vehicle Colour Vehicle Category Motorcycle Name of Driver Contact Number Address Address complement Postcode Insurance Company Name Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

JINJURED PERSONS DETAILS

Code
Code
Coximate Age Years Old
Coximate Age

TOH PLAN

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
 - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
 - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
 - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
 - (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

X

Policyholder's Signature

Date & Time:

Driver's Signature


(If driver is not the policyholder)

Steven Chee Insurance Advisor I: 6305 7299 Ext: 511

HP: 8511 2203 Fax: 6285 8620

Reporting Centre Personnel's Signature

Name:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT


01	13	JAN	202	1,0	700	H A1	ONG	PIE	TOWARDS	To	A
YAS	'6H ,								-BRAKE,		
A	Нπ		• D							١.	
C					017	ro B.					
									4		-
						d					
			100								
										2	
					en l'						
					l l va L _k a						
						,					
									1		
	ARATION declare the		g particular	s are true i	n every re	espect.			Stever Insurance Tel: 6305 72	Advis	sor
	(2							HP: 851 Fax: 628	1 2203	3

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Dwner ID Type: Owner ID:	Singapore NRIC
	148G
Vehicle No.:	SMS5149T
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2021
Vehicle Make:	SKODA
Vehicle Model:	OCTAVIA RS 2.0 TSI AIDISPLAY
Primary Colour:	Grey
Manufacturing Year:	2019
Engine No.:	DLB032457
Chassis No.:	TMBBU7NE9L0053813
Maximum Power Output:	180.0 kW (241 bhp)
Open Market Value:	\$27,446.00
Original Registration Date:	28 Feb 2020
First Registration Date:	28 Feb 2020
Transfer Count:	0
Actual ARF Paid:	\$30,425.00
वर्षत्रस्य संस्थानसम्बद्धाः । स्थानस्य स्थानस्य कृति स्थानस्य स्थानस्य सम्बद्धाः	BERNYARINAN NYANYARIANA BERNYARIA KAMBUNIN MUNIKANYA MANDANIN'I KAMBUNIN MANDANINA NYANYA MANDANINA MANDANINA
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Feb 2030
PARF Rebate Amount:	\$22.818.00
क्षिस्याक्ष्यक्षिण्यस्यक्षिक्षात्रस्य ग्रह्मान् व्यवस्थानस्य	asus silvasa aa aanan kinista aa aanan ka
COE Expiry Date:	27 Feb 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$32,889.00
COE Rebate Amount:	\$29,991.00
Total Rebate Amount:	\$52,809.00

ОК



Features

The Octavia RS Truly Leads The Pack Within Its Segment. The Sports Sedan Offers A Dynamic Appearance That Reinforce With Its Imposing Performance. View specs of the SKODA Octavia (2018)







