

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page

1/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Company
REEL LOCO PRODUCTIONS PTE LTD
162 BUKIT MERAH CENTRAL
#06-3555
Singapore 150162

Document no.
Document date
Customer no.
Customer GST-ID
Dealer
Job order number
Job order date
Service Advisor

07-01-2021
5211001170
200208384E
30001
2021000837/ 1
07-01-2021
TIOU CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SGK1008G	7N24MYH2	25-09-2020	WVWZZZ7NZLV015505	Sharan Highline 2.0 TSI 162kW DSG Toulon	50

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount excl. GST	Total amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
D 169300M2	1k Window Adhesive	2	pcs.	51.11	#1	102.22	109.38
D 00940104	All Purpose Cleaner	1	pcs.	94.03	#1	94.03	100.61
D 00920002	Primer	1	pcs.	27.39	#1	27.39	29.31
D 181802M1	Activator For Precoated W	1	pcs.	25.14	#1	25.14	26.90
D 00950025	Applicator	2	pcs.	10.12	#1	20.24	21.66
7N0827025H	Rear Trunk Lid	1	pcs.	2,838.71	#1	2,838.71	3,037.42
8D0853419D	Packing Adhesive	1	pcs.	29.20	#1	29.20	31.24
	RR NUMBER PLATE PACKING						
WHT007341	Rivetted Cap Nut	4	pcs.	2.28	#1	9.12	9.76
7N0827705F	Decklid Weatherstrip	1	pcs.	330.55	#1	330.55	353.69
3CN945087	Additional Brake Light W/ 3RD BRAKELIGHT	1	pcs.	221.63	#1	221.63	237.14
7P6853630D FOD	Vw Sign Black High Gloss/	1	pcs.	126.61	#1	126.61	135.47
7N0853687 739	Inscription Chrome	1	pcs.	86.79	#1	86.79	92.87
	NAME PLATE (SHARAN)						
7N0807417E GRU	Cover For Bumper Primed	1	pcs.	1,378.97	#1	1,378.97	1,475.50
	REAR BUMPER						
7N0807521C 9B9	Spoiler Satin Black	1	pcs.	286.09	#1	286.09	306.12
7N0807251A	Foam Insert	1	pcs.	134.37	#1	134.37	143.78
7N0807305A	Bumper Bracket	1	pcs.	755.04	#1	755.04	807.89
	REINFORCEMENT						
7N0807863	Attachment Strip	1	pcs.	189.14	#1	189.14	202.38
	BUMPER CTR BRACKET						
7N0807375	Guide Piece	1	pcs.	81.62	#1	81.62	87.33
	BUMPER SIDE BRACKET LH						
7N0807376	Guide Piece	1	pcs.	81.62	#1	81.62	87.33
	BUMPER SIDE BRACKET RH						
N 10621301	Expanding Nut	6	pcs.	1.80	#1	10.80	11.56
1S0919275C GRU	Sensor Primed	2	pcs.	174.15	#1	348.30	372.68
1T0919133C 9B9	Seal Ring Satin Black	2	pcs.	0.76	#1	1.52	1.63
7N0945105B	Reflector	1	pcs.	67.42	#1	67.42	72.14
	LH						
	LABOUR	4	pcs.	840.00	#1	3,360.00	3,595.20
	SPRAY PAINT	4	pcs.	800.00	#1	3,200.00	3,424.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00	#1	840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	REAR NUMBER PLATE	1	pcs.	80.00	#1	80.00	85.60
	CHINA TAIPING DIRECT SETTLEMENT						
	DOA : 07/01/2021						
	TP VEH : SLZ3228L						
	SURVEY BY :						

VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road
Singapore 159934
Biz. Reg. No.: 199101494Z
GST No.: M200985052



Quotation

Non binding - Preview

Page 2/2

Company
CHINA TAIPING INSURANCE (S) PL
3 ANSON ROAD
#18-00 SPRINGLEAF TOWER
Singapore 079909

Customer Details:
Company
REEL LOCO PRODUCTIONS PTE LTD
162 BUKIT MERAH CENTRAL
#06-3555
Singapore 150162

Document no.
Document date 07-01-2021
Customer no. 5211001170
Customer GST-ID 200208384E
Dealer 30001
Job order number 2021000837/ 1
Job order date 07-01-2021
Service Advisor TIOW CHUAN CHEE

License plate	Model code	First registration	VIN	Model	Mileage
SGK1008G	7N24MYH2	25-09-2020	WVWZZZ7NZLV015505	Sharan Highline 2.0 TSI 162kW DSG Toulon	50

Quotation valid till 14-01-2021

Tax Code	Labour	Material	GST %	GST	Total amount excl. GST	Total amount incl. GST
#1	760.00	15,716.52	7%	1,153.36	16,476.52	17,629.88
Total	760.00	15,716.52		1,153.36	16,476.52	17,629.88

Customer

Service Advisor

—VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).—

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Handwritten:
Done
Hp 90010068
5 days + 2 = 7 days
18/01/2021 @ 1145
Resy before paint