

ASS. REC. BY:

REF: CS/CTI21000717/R1vf3

Special Instruction:

Surveyor: RASUL

ASSIGNMENT (Office)

From (Person): IRENE TAY of CTI Date/Time: 15/1/2021 7:51 AM

Estimated Cost: Bill to:

OD ☒ TP WS/ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SGK 1008G Insured: SLZ 3228L

at Workshop m/s Volkswagen Group Singapore Pte Ltd Tel: 6305 7176

of 247 Alexandra Road

Policy No: DMPCSNW00177712001 Claim No: SNM21D200087/C02/IRENE

Sum Insured: Excess:

Make of Veh: D.O.A. 6.1.2021
(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 15-01-2021 9.20A.M Person Contacted: STEVEN Vehicle IN ☒ OUT

Date/Time	Action/Instruction (☒) Estimate
	SGK 1008G - CS/CTI18005401/R1vd3q2 DOA : 13/03/2018
	SLZ 3228L - CS3/ASM18019401/Gsd3e2-1 DOA : 23/10/2018
2/3/21	Final fig \$13,139.40 confirmed by email (Red 3337.12, 20%)
5/3/21	Send IA via merimen