SES. REC. BY: Com CS CTI 2100	v7i7/Rivf3 1 826#
	GNMENT
From: Date:	Veh No: Shk 1008h Yr Regn: 2020 1889
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxl / Prime Mover /
OD / PI WS I TP RES / OD RES / EVA / INV / MIV	Truck / Trailer or
To Inspect Vehicle No: SAK 15864	Make: Volksnapien Staran 20731 c.c 1984
at Workshop m/s Volysuppen	Colour BLUE A/C: Insured / Std / NI / NA
of 247, Meansta co	Sp.Reading 5765 T/Radio: Insured / Std / NI / NA
Insured: CT1	Eng/No:
Policy No.	C/No: WY W222 1N2 L VU   5505 .
Claims No.	Gen. Cond: Good (Fa) / Poor / Burnt
Sum Insured: Excess:	Steering: Inorder/ Jammed / Leaked / Burnt or
(Client's Record)	Brake: (norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil / SRim / STD A/Rim or
11.30	Tyre Size: F: 225 45R18
(Policy Condition) our miles	R:
Remark: The veh had commenced its . N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / NIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYOTYOKO Or. CONTINGUAM
Bal. or Market Value: 151K	_ Fron! Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. R/Bal. mm , R/Bal. m
GIA / PR Seen: Consistent? : Yes or No	UBal. UBal
Est. Repairs: days Res.: Yes or No	D.O.A. 86 01 221 D.O.I. 18/01/2021 _
Lum Sum: % · 3 Val.: Yes or No	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
CA / REV / REP. / 24 HRS  Vehicle: IN / OU	0600 0110
Date:Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collis
Date / Time Action / Instruction	π
figure 1 mit - 8/K	.m.
· · · · ·	
	sion.
Dale/Time, File Pass to? Pre B. Report	Days Of Repair: 7
i) : Final Report	Resurvey No. of Trip: 1 Survey Fee:
Date/Time, File Return to?	. Transportation;
2) 5/3/21-Typist Add F	
Marine an	: Interview (\$ ) Photos
Representation Merimen	:Tech, Invs (\$ ) Others
Lump Sum/LEA (\$\\\ \$13,139.40\)	:Weeliend (%)
	TOTAL
to See a	₩ <del></del>

## **ÓL**KSWAGEN CENTRE SINGAPORE

47 Alexandra Road Singapore 159934

Biz. Reg. No.: 199101494Z GST No.: M200985052







Quotation

Non binding - Preview

Company CHINA TAIPING INSURANCE (S) PL 3 ANSON ROAD #18-00 SPRINGLEAF TOWER Singapore 079909

TP VEH: SLZ3228L SURVEY BY:

Customer Details: Company REEL LOCO PRODUCTIONS PTE LTD 162 BUKIT MERAH CENTRAL #06-3555 Singapore 150162

1/2 Page Document no. 07-01-2021 Document date 5211001170 Customer no. Customer GST-ID 200208384E 30001 Dealer 2021000837/1 Job order number 07-01-2021 Job order date TIOW CHUAN CHEE Service Advisor

-	License plate	Model code	First registration	VIN	Model	Mileage
-	SGK1008G	7N24MYH2	25-09-2020	WVWZZZ7NZLV015505	Sharan Highline 2.0 TSI 162kW DSG	50
					Toulon	

Position no.	Description	Quantity	Unit	Unit price excl. GST	Tax code	Total amount T excl. GST	otal amount incl. GST
	Check Short Circuit / Harness Repair	1	pcs.	280.00	#1	280.00	299.60
	Diagnostic and Programming	1	pcs.	480.00	#1	480.00	513.60
D 169300M2	1k Window Adhesive	2	pcs.	51.11	#1	102.22	109.38
D 00940104	All Purpose Cleaner New /	1	pcs.	94.03	#1	94.03	100.61
D 00920002	Primer Ne /	1	pcs.	27.39	#1	27.39	29.31
D 181802M1	Activator For Precoated W / /	1	pcs.	25.14	#1	25.14	26.90
D 00950025	Applicator ~ /	2	pcs.	10.12	#1	20.24	21.66
7N0827025H	Rear Trunk Lid 🛂 /	1	pcs.	2,838.71	#1	2,838.71	3,037.42
8D0853419D	Packing Adhesive RR NUMBER PLATE PACKING	1	pcs.	29.20	#1	29.20	31.24
WHT007341	Rivetted Cap Nut M	4	pcs.	2.28	#1	9.12	9.76
7N0827705F	Decklid Weatherstrip	1	pcs.	330.55	#1	330.55	353.69
3CN945087	Additional Brake Light Wing Area / July 3RD BRAKELIGHT	1	pcs.	221.63	#1	221.63	237.14
7P6853630D FOD	Vw Sign Black High Gloss/ / /	1	pcs.	126.61	#1	126.61	135.47
7N0853687 739	Inscription Chrome NAME PLATE (SHARAN)	1	pcs.	86.79	#1	86.79	92.87
7N0807417E GRU	Cover For Bumper Primed) REAR BUMPER	1	pcs.	1,378.97	#1	1,378.97	1,475.50
7N0807521C 9B9	Spoiler Satin Black '-	1	pcs.	286.09	#1	286.09	306.12
7N0807251A	Foam Insert 7	1	pcs.	134.37	#1	134.37	143.78
7N0807305A	Bumper Bracket 7 7 REINFORCEMENT	1	pcs.	755.04	#1	755.04	807.89
7N0807863	Attachment Strip 77 BUMPER CTR BRACKET -	1	pcs.	189.14	#1	189.14	202.38
7N0807375	Guide Piece  BUMPER SIDE BRACKET LH  7	1	pcs.	81.62	#1	81.62	87.33
7N0807376	Guide Piece BUMPER SIDE BRACKET RH	1	pcs.	81.62	#1	81.62	87.33
N 10621301	Expanding Nut /	6	pcs.	1.80	#1	10.80	11.56
1S0919275C GRU	Sensor Primed 2	2	pcs.	174.15	#1	348.30	372.68
1T0919133C 9B9	Seal Ring Satin Black 7	2	pcs.	0.76	#1	1.52	1.63
7N0945105B	Reflector 37	1	pcs.	67.42	#1	67.42	72.14
	LABOUR	4	pcs.	840.00	#1 ((	3300.00	3,595.20
	SPRAY PAINT	4	pcs.	800.00	#1 /	600 3,200.00	3,424.00
	R&R REAR W/SCREEN	1	pcs.	840.00	#1	840.00	898.80
	TRANSFER BOOT LID MECHANISM	1	pcs.	840.00		420 840.00	898.80
	REAR WATER LEAK TEST	1	pcs.	150.00	#1	150.00	160.50
	REAR NUMBER PLATE CHINA TAIPING DIRECT SETTLEMENT DOA: 07/01/2021	1	pcs.	80.00	#1	7 80.00	85.60

### OI KSWAGEN CENTRE SINGAPORE

47 Alexandra Road Singapore 159934

Biz. Reg. No.: 199101494Z GST No.: M200985052







## Quotation

Page

Non binding - Preview

Company CHINA TAIPING INSURANCE (S) PL 3 ANSON ROAD #18-00 SPRINGLEAF TOWER Singapore 079909 Customer Details: Company REEL LOCO PRODUCTIONS PTE LTD 162 BUKIT MERAH CENTRAL #06-3555

Singapore 150162

 Document no.
 07-01-2021

 Customer no.
 5211001170

 Customer GST-ID
 200208384E

 Dealer
 30001

 Job order number
 2021000837/1

 Job order date
 07-01-2021

 Service Advisor
 TIOW CHUAN CHEE

2/2

License plate | Model code | First registration | VIN | Model | SGK1008G | 7N24MYH2 | 25-09-2020 | WVWZZZ7NZLV015505 | Sharan Highline 2.0 TSI 162kW DSG | Toulon | 50

#### Quotation valid till 14-01-2021

Tax	Labour	Material	GST %	GST	Total amount	Total amount
Code					excl. GST	incl. GST
#1	760.00	15,716.52	7%	1,153.36	16,476.52	17,629.88
g-terminal and the						

	Customer	Service Advisor
•		
VISI	T OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for acceptable)	ditional services, products

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

He rootoviss

5 class
18/01/2021 @ 1144

Roey be fore print

N21170003 / Volkswagen Group Singapore Pte Lid NRY DATE & TIME: 07/01/2021 10:51 (SGT) IBMITTED BY: Steven Chee ERSION: 1 (07/01/2021 10:51 (SGT))



## SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver
- 2. Information provided must be as truthful and accurate as possible. Any wiful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

#### anemena centera

Date of Submission07/01/2021 10:51 (SGT)Date of Accident06/01/2021 09:26 (SGT)Exact Location of AccidentYio Chu Kang, SingaporeAdditional Location InformationCTE EXIT TO YIO CHU KANGCountry/State of LossSingapore

#### DETAILS OF OWN VEHICLE

Vehicle Registration Number SGK1008G

#### INSURED/POLICYHOLDER

Is company? Yes

Name Of Registered Owner REEL LOCO PRODUCTION PTE LTD

Company Reg No 2XXXX826H

Email Address joey@reelloco.com

Mobile Phone No (Phone) +65-97430710

Alternative Phone No (Home) +65-97430710

#### VEHICLE PARTICULARS

Manufacturer Volkswagen

Model Sharan

Variant 
Exact purpose for which vehicle was being used at time of accident Private use

Are you claiming under your own insurance policy for repair to your vehicle?

Vehicle Category

No - Claiming third party

Private car

#### INSURANCE COMPANY

DRIVER

Name of Driver
NRIC No

CHAN HUAN SUAN SXXXX822D

Of Driving Pass 08/08/2001 ying experience 19 YEARS AND 5 MONTHS nder Female <sub>lobile</sub> Number (Phone) +65-97430710 r<sub>Alt.</sub> Phone Number <sub>Email</sub> Address joey@reelloco.com Address **BLK 97 MARINE PARADE** Address complement #09-02 Postcode 449273 Is the driver the policyholder? No If No, Relationship of the Driver with the Insured Other Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No **DETAILS OF POLICE ACTION** Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO SKETCH PLAN ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes Was there any audio recorded? No IDETAILS OF OTHER VEHICLE PROPERTY (I

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
NRIC No
Contact Number
Address

Address complement

SLZ3228L Subaru

\_

White Private car

DON LEE KOON HONG

SXXXX034D

-

rance Company Name ure Of Damage rails of property damaged in accident of Passenger (Including Driver)

## China Taiping Insurance

\_

\_

#### SKETCH PLAN

#### **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
  - (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
  - (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
  - (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
  - (e) the information so collected under (d) above may be shared / disclosed:
    - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or

(ii) for complying with requirements under any regulations, laws or court orders.

Steven Chee
Insurance Advisor
Tel: 6305 7299 Ext: 511

HP: 8511 2203 Fax: 6285 8620

Reporting Centre Personnel's Signature Name:


Policyholder's Signature

Date & Time:

(16 driver is not the policybolder)

(If driver is not the policyholder)

YIO CHU KANTO.



#### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

DATE: 6 JANUARY 2020
TIME: 9:26 AM
VEHICLE WAS STATIONERY WAITING TO EXIT FROM
CTE FILTER LANG AT YIO CHU KANG EXTT.
VEHICLE BEHND SLZ 3228L BUMPED INTO REAP
AT CAR SAKIODER WHEN BOTH ATTEMPTED TO
EXT FROM FILTER LANE TO YIO CHU KANG ROAD-
A: SGK 1008 G
B: SLZ 3228L
DECLARATION Steven Chee
I/We declare the foregoing particulars are true in every respect.  I/Insurance Advisor  Fel: 6305 7299 Ext: 511  HP: 8511 2203  Fax: 6285 8620
$\mathcal{O}$

## > Back to OneMotoring

# Enquire PARF/COE Rebate for Registered Vehicle

Owner ID:	Company 826H
Vehicle No:	56K1008G
Vehicle to be Exported:	Paranananananananananananananananananana
Intended Deregistration Date:	18 Jan 2021
Vehicle Make:	
Vehicle Model:	VOLKSWAGEN
Primary Colour:	SHARAN 2.0 TSI
Manufacturing Year:	Blue
Engine No.:	2020
Chassis No.:	DED035903
Maximum Power Output:	WWZZZ7NZLV015505
Open Market Value:	162.0 kW (217 bhp)
Original Registration Date:	\$34,049.00
First Registration Date:	25 Sep 2020
Transfer Count:	25 Sep 2020
Actual ARF Paid:	Ο
invalori, egiri egiri (april) appril (appendantanta	\$39,669.00
PARF Eligibility:	erranen en en 1966 betaka 1961 betaka 1961 betaka 1962 betaka 1962 betaka 1962 betaka 1962 betaka 1962 betaka Pes
PARF Eligibility Expiry Date:	
PARF Rebate Amount:	24 Sep 2030 \$29.751.00
\$\$\$《元·17·4·12·4·11 年中) 20 (4-17·1-1-14-14 日) (2) 4-11 ( 146-14-14-14-14-14-14-14-14-14-14-14-14-14-	527./51.00
COE Expiry Date:	24 Sep 2030
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10 10 1000CE BY 97RW (130Bhp)
QP Paid:	\$40.989.00
COE Rebate Amount:	\$39.691.00
Total Rebate Amount:	\$69,442.00

ОК

