

## **National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H

**AUTOMOBILE INSPECTION REPORT** 



AUTOMOBILE INSPECTION REPORT						
NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC21000724/Qvd3e2						
73 BRAS BASAH ROAD #05-01 NTUC TRADE UNION HOUSESINGAPORE 189556			Date:	19-05-2021 INC4		
1. Policy Particulars :- THIRD PARTY CLAIM						
••	Insured Veh.					
	Policy No.	5118655098	Cover	·	0.00	
	Claim No.	MT/1116967-002	Exces		0.00	
	Assign From		Assign		14/01/2021	
2.						
	Make & Model	MAN NL320F	c.c		10518	
	Engine No.	HIDDEN	Year o	f Reg.	2013	
	Chassis No.	WMAA22ZZ4D7001938	Colou	<u> </u>	MULTI COLOUR	
	Odometer	599884	Steerii	ng	IN ORDER	
	Brakes	IN ORDER	Modifi	cation	SPORTS RIM	
	General	FAIR				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	275/70 R22.5	FALKE	N	6 mm	
	L/H Front Tyre	275/70 R22.5	FALKE		6 mm	
	R/H Rear Tyre	275/70 R22.5 (D)	FALKE		6/6 mm	
	L/H Rear Tyre	275/70 R22.5 (D)	FALKE		6/6 mm	
4.						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	08/01/2021		tion Date	14/01/2021	
	Survey held at	•				
-	60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705					
5a.	Remarks  A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair						
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					