

ASS. REC. BY: Sun Pin

REF:


NTUC

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: _____
 at Workshop m/s _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.



Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SMB1394D Yr Regn: 01/11/2013
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or _____
 Make: MAN NL 320 F C.C. 10518
 Colour: Multicolour A/C: Insured / Std / NI / NA
 Sp. Reading: 599884 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: WM/AA22224D7001938
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 275/70 R22.5
 R: 275/70 R22.5
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or Falken
 Front _____ Rear _____
 R/Bal. 6 mm R/Bal. 6 mm
 L/Bal. 6 mm L/Bal. 6 mm
 D.O.A. _____ D.O.I. 14/01/2020
 Survey held at SMRT
 Des. of Damages: Frt / Rear / O/S / NI / U/C / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* GZA Not Ready yet

Date/Time, File Pass to?

☐ : Preli. Report
☐ : Final Report

1) _____
 Date/Time, File Return to?

2) _____

Rep. Form: _____

Lump Sum / LB. J. ()

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)
☐ : Interview (\$ _____)
☐ : Tech. Invs (\$ _____)
☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS \$ _____

Photos

Others

TOTAL



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672


Date Generated : 14/01/2021

User ID : GohKK2

Section A - Accident Details

Registration Number	SMB1399D
Case Reference Number	BUS/01/21/7014
Registration Date	1/11/2013
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN NL320F(A22)
Name of Driver	Saw Chiang Chue
Type of Accident	Side Swipe
Accident Date and Time	8/1/2021 4:03 PM
Accident Reported Date and Time	8/1/2021 5:15 PM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	
Special Instruction to ARC, if any	SMB1399D - LEFT FRONT PORTION AND RIGHT FRONT PORTION GBG5718U (TP) - INSURED WITH NTUC
Prepared Date and Time	14/1/2021 7:48 AM
Chassis Number	WMAA22ZZ4D7001938
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$3,710.00	\$0.00
Total Spray Cost	\$1,126.00	\$0.00
Total Spare Part Cost	\$13,043.47	\$0.00
Total Other Cost	\$520.00	\$0.00
TOTAL COST	\$18,399.47	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	
Prepared / Adjusted By	Kok Khoon Goh	
ARC / Surveyor Sign Off Date	14/01/2021 8:10 AM	
Signature		<input checked="" type="checkbox"/>
Remarks		

Section C - Quotation and Accident Invoice Details

Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/01/2021

User ID : GohKK2

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REMOVE & INSTALL ALL ABOVE ITEMS AND REPAIR OTHERS DAMAGED AFFECTED AREAS.	\$3,710.00	3180
Total Labour	\$3,710.00	

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS	\$1,126.00	1,000
Total Spray Painting & Panel Beating	\$1,126.00	

Part 3 - Other Costs - Accident and Accident Repair Related Expense

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	\$200.00	X
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$240.00	X
TO CHECK WIRING AND SYSTEM FUNCTION	\$80.00	X
Total Other Costs	\$520.00	

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010148	GLASS	4001X01-GLASS5171	WINDSCREEN,FRONT:F OR MAN A22 BUS	1.00	\$5,031.80	10.00	\$4,528.62	Replace	/CRA
6010502	DOOR		GLASS,EXIT DOOR:FOR MAN A22 BUS	1.00	\$510.00	10.00	\$459.00	Replace	X R
			SMRT STICKER	1.00	\$200.00	0.00	\$200.00	Replace	/N/A
6009998	BODY LH	A01001-CW554	PANEL, SIDE:L4, FOR MAN A22 BUS	1.00 LH	\$517.50	100.00	\$0.00	Repair	X R
6009997	BODY LH	A01001-CW553	PANEL, SIDE:L3, FOR MAN A22 BUS	1.00 LH	\$244.30	10.00	\$219.87	Replace	/CR4
6009987	BODY RH	A01001-CW568	PANEL, SIDE:R6, FOR MAN A22 BUS	1.00 RH	\$1,776.80	100.00	\$0.00	Repair	X R
6009986	BODY RH	A01001-CW569	PANEL, SIDE:R5, FOR MAN A22 BUS	1.00 RM	\$353.70	10.00	\$318.33	Replace	/CR4
6010330			WHEEL ARCH TRIM	1.00	\$124.20	10.00	\$111.78	Replace	/CK4
4006315	CONSUMABLE	Aktivator - 100	ACTIVATOR	3.00	\$80.00	0.00	\$240.00	Replace	/N/A
6010303	VE	4001B05-LAM141	LAMP,INDICATOR,SIDE: LED (MAN BUS)	1.00	\$186.10	10.00	\$167.49	Replace	/CK4
6010163	GLASS	4001Y01-GLASS5150	GLASS,DRIVER WINDOW:FOR MAN A22 BUS	1.00	\$1,423.20	10.00	\$1,280.88	Replace	/BR
6010161	BODY RH	4001M01-ACCE467	MIRROR,VIEW:FRONT,R H, FOR MAN	1.00	\$1,244.90	10.00	\$1,120.41	Replace	/Jupa
6010050	Body	F01001-CW270	DOVE:REAR, FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	X R
6010175	GLASS	4001X01-GLASS5178	GLASS, SIDE:L6, FOR MAN A22 BUS	1.00 LH	\$543.40	10.00	\$489.06	Replace	/BR
6010174	GLASS	4001X01-GLASS5177	GLASS, SIDE:L5, FOR MAN A22 BUS	1.00 LH	\$957.40	10.00	\$861.66	Replace	/BR
6010173	GLASS	4001X01-GLASS5176	GLASS, SIDE:L4, FOR MAN A22 BUS	1.00 LH	\$1,060.90	10.00	\$954.81	Replace	/BR
			RUBBER PROFILE	1.00	\$150.00	0.00	\$150.00	Replace	/CR4
6010459	DOOR		GLASS,FRONT DOOR:FOR MAN A22 BUS	1.00	\$510.00	10.00	\$459.00	Replace	?
6010306	VE	81-25320-6111	FLASHER,AUX HEADLAMP,LH (MAN BUS)	1.00	\$904.40	10.00	\$813.96	Replace	?
6010304	VE	8-25101-6539	HEADLAMP,LH (MAN BUS)	1.00	\$1,603.60	10.00	\$1,443.24	Replace	?



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
80 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 83685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 14/01/2021

User ID : GohKK2

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6010153	Body	FD1001-CW254	COVER HEADLAMP FR LH FOR MAN A22 BUS	1.00	\$974.70	10.00	\$877.23	Replace	✓ CRU
6010073	Body	FD1001-CW252	DOVE FRONT FOR MAN A22 BUS	1.00	\$2,817.50	100.00	\$0.00	Repair	✓ R
4006313	CONSUMABLE	SIKAR Primer 206 G+P	PRIMER (SIKA 206 G+P)	3.00	\$80.00	0.00	\$240.00	Replace	✓ ME
4006314			SEALANT SIKAFLEX	37.00	\$37.00	0.00	\$1,369.00	Replace	✓ ME
Total					\$24,148.90		\$16,304.34		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

Repair dy - 7 days

L/S

After painting photo

Sun Pm (Hd)

14/01/2020.

TP without prejudice.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type:	Company
Owner ID:	292D
Vehicle Details	
Vehicle No.:	SMB1399D
Vehicle to be Exported:	No
Intended Deregistration Date:	15 Jan 2021
Vehicle Make:	MAN
Vehicle Model:	NL320F (A22)
Primary Colour:	Multicolor
Manufacturing Year:	2013
Engine No.:	50334631563452
Chassis No.:	WMAA22ZZ4D7001938
Maximum Power Output:	-
Open Market Value:	\$252,263.00
Original Registration Date:	01 Nov 2013
First Registration Date:	01 Nov 2013
Transfer Count:	0
Actual ARF Paid:	\$0.00
Intended PARF Rebate Details	
PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00
Intended COE Rebate Details	
COE Rebate Amount:	\$0.00
Total Rebate Amount:	\$0.00

The information contained herein is correct as at 15 Jan 2021

OK