

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

Consistent? : Yes or No

Consistent? : Yes or No

days Res.: Yes or No

% 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

Buyer Disassemble before POC sensor missing
WAC report motor: 97221
LTA as at 16-1-21 is \$46760
PRS no estimate

Submit DAR Report

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC DOHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

R/Bal.

L/Bal.

L/Bal.

D.O.A.

D.O.I.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

) S + RS, SI

) Photos

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$)

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

SLX824

Beer bumper sport	cracked
Beer bumper reflector o/s	mes
Beer bumper pdc sensor o/s	shock
Beer bumper reinforcement	Bent
Beer bumper top retainer	twisted
Beer bumper inner plate	cracked
Beer end panel	Repair
Beer bumper diffuser	Rebrand.

3 days.

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 456E

Vehicle Details

Vehicle No.: SLX82U
Vehicle to be Exported: No
Intended Deregistration Date: 16 Jan 2021
Vehicle Make: B.M.W.
Vehicle Model: 328I SEDAN AT D/AB DSC HID NAV
Primary Colour: Black
Manufacturing Year: 2013
Engine No.: B1620443N20B20A
Chassis No.: WBA3A56080NR04614
Maximum Power Output: 180.0 kW (241 bhp)
Open Market Value: \$43,487.00
Original Registration Date: 12 Jun 2013
First Registration Date: 12 Jun 2013
Transfer Count: 3
Actual ARF Paid: \$47,882.00 2394/

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 11 Jun 2023
PARF Rebate Amount: \$28,729.00

Intended COE Rebate Details

COE Expiry Date: 11 Jun 2023
COE Category: B - Car (1601cc & above)
COE Period(Years): 10
QP Paid: \$75,000.00
COE Rebate Amount: \$18,031.00
Total Rebate Amount: \$46,760.00

The information contained herein is correct as at 16 Jan 2021

OK