

ASS. REP. BY:

Steve

REF:

A/G

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / YP / RES / OD-RES / EVA / INV / MV

To inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vehicle _____

(Policy Condition)

Remarks: The veh had commenced its
repair at the time of inspection.

Est. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repair: _____ days Res.: Yes or No

Lum. Sum: _____ % 3 Val.: Yes or No

QA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date _____ Person Contacted: _____

Date / Time Action / Instruction

MV-75K

Veh No:

SKK 1888K

Yr Regn:

11/6/9

Type: (M/C) / M/Cyolo / Bus / Van / Lorry / Trd / Prime Mover /

Truck / Trailer or

Make:

KIA Shari

C.C.

998

Colour:

Grey

A/C: Insured / Std / Nil / N

Sp. Reading

24762

T/Radio: Insured / Std / Nil / N

Eng/No:

C/No:

KNA0681VK 629660

Gen. Cond: Good / Fair / Poor / Dampt

Steering: Worder / Jammed / Locked / Burnt or

Brake: Inter / Jammed / Locked / Burnt or

Mod: Nil / 9/Rin / STD Actin or

Tyre Size:

F:

185/65R15

R:

SS / DUN / BUNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUGI /

TOYO / YOKO or B

Kum ho

Front

Rear

R/Bal.

5

mm

R/Bal.

5

mm

L/Bal.

5

mm

L/Bal.

5

mm

D.O.A.

9/1/21

D.O.A.

15/1/21

Survey held at

Cyck & Carriye

Des. of Damages: Pri / Rear / O/S / W/S / U/C / Rooftop or

Rear RH

The U/C / Chassis frame / Body Structure affected due to collision

Date/Time, File, Date to?



: Prel. Report

: Final Report

Date/Time, File Return to?

25/1/21-Typist

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech. Inve (\$



: Weekend (\$



: Total

Days Of Repair: 4

Recovery No. of Trip: 1

Survey Fee:

Transportation:

8 + RS, \$

Photos

Others

TOTAL

3706 Formel: Merimen

ump Sum / L.P. / P \$1910.40



CYCLE & CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



ESTIMATE

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
NG KAI WEN (HUANG KAIWEN)	Cust No/Name LCV10120/NG KAI WEN (HUANG KAIWEN)
BLK 469C SENGKANG WEST WAY	Reg No/Reg Date SKK1888K / 11/06/201
#26-622	Date In/Mileage / 0
SINGAPORE 793469	Chassis No KNAD6811VK6296660
Contact No	Engine No G3LCKP029988
	Make/Model KIA/STONIC 1.0 A BET
	Colour/Trim ABT / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LCV10120	CRDVCH	15/01/2021/ 10:19	TLC	442 / CocoLu	27083

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
E PNT88000 REPAIR REAR DOOR RH, REAR BUMPER RH, RENEW REAR BUMPER	1.5 X 490			600 800.00
E PNT98000 SPRAY PAINT FOR REAR DOOR RH, REAR BUMPER				350 700.00
M SUNDRY TRANSFER REAR RIGHT RIM				? 30.00
B WHEELALIGNMENT To Conduct Computerize Full Wheel Alignment				120.00
A 90000001 CHECK WIRING & ELECTRICAL SYSTEM				30.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST				120 320.00
A 90000001 RENEW REAR UNDER CARRIAGE				640.00
M SUNDRY Sundry				20.00
M MOULDING ASSY-SIDE SILL, RH	1.00	248.00	00.00	248.00
M GARNISH-QTR SIDE RH	1.00	50.00	00.00	50.00
M GARNISH ASSY-RR DR SIDE, RH	1.00	92.00	00.00	92.00
M GARNISH ASSY-FR DR SIDE RH	1.00	82.00	00.00	82.00
M WHEEL ASSY-ALUMINIUM	1.00	659.00	00.00	659.00
M HUB ASSY-RR WHEEL	1.00	358.00	00.00	358.00
M COVER-RR BUMPER LWR	1.00	366.00	00.00	366.00

Estimate

Steve (LKK)

15/1/21, 11:30am

00- Nm AL, Excess - ?

P/P

By Bk sp
4 days

Confirm & accepted by the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis

Authorized signatory and company stamp

7% GST on **Nett 4515.00**

Total Payable 4,831.05

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	11/01/2021 09:24 (SGT)
Date of Accident	09/01/2021 12:15 (SGT)
Exact Location of Accident	510 Lorong 6 Toa Payoh, Toa Payoh, Singapore 319398
Additional Location Information	TOA PAYOH BLK 190 MULTI STOREY CARPARK
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKK1888K
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	NG KAI WEN
NRIC No	SXXXX360C
Email Address	CAROL.NG.KW@GMAIL.COM
Mobile Phone No	(Phone) +65-96622785
Alternative Phone No	+65-96622785

VEHICLE PARTICULARS

Manufacturer	Kia
Model	Stonic
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900104759
Cover Note Number	-

DRIVER

Name of Driver	NG KAI WEN
NRIC No	SXXXX360C
Date Of Birth	09/04/1987
Occupation	Outdoor

Of Driving Pass
ing experience
nder
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

16/09/2008
12 YEARS AND 4 MONTHS
Female
(Phone) +65-96622785
+65-96622785
CAROL.NG.KW@GMAIL.COM
BLK 469C SENGKANG WEST WAY #26-622
-
793469
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
INDOOR CARPARK
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
2
No
-
Yes
1
No
No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No
No
-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT
COLLISION-HEAD TO SIDE

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
Yes
No

DETAILS OF OTHER VEHICLE PROPERTY (1)

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode

SJP3315U
Honda
-
-
-
Private car
MRS GOH
(Phone) +65-92976041
-
-
-

Insurance Company Name -
Type Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any willful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "**Personal Information**") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "**Insurers**"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "**Purposes**")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

09/01/2021


Policyholder's Signature / Date & Time

09/01/2021

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan



A: SKK 688K

B: SJP 33154

Circumstances of the Accident

I was driving in the multi-storey carpark in Toa Payoh (Blk 190)
the red ~~vertical~~ Honda SJP3315U hit me from the driver side,
as she was trying to park into the parking lot,

Declaration

We declare the foregoing particulars are true in every respect.

 19/01/2021

Policyholder's Signature / Date &
Time

 19/01/2021

Driver's Signature (If driver is not the policyholder) / Date
& Time



Witnessed by Reporting Centre
Personnel

CERTIFICATE OF INSURANCE

KIA AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : NG KAI WEN (HUANG KAIWEN)
Period of Insurance : 11 Jun 2019 To 10 Jun 2021
Engine No. : G3LCKP029988
Chassis No. : KNAD6811VK6296660

Vehicle No. : SKK1888K
Policy No. : 1900104759
Endorsement No. :
Issued Date : 18 Jun 2019

ABOUT THE COVER

Make/Model : KIA Stonic

Engine Capacity/Tonnage : 998.00 CC

Driver Restriction : NA

Sum Insured : Market Value

Off Peak Car : No

First Year of Registration : 2019

Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

a) The Policyholder

b) Any other person who is driving on the Policyholder's order or with his/her permission.

This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.

This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered Inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189), Section 95 of the Road Transport Act, 1987 (Malaysia) and Road Transport (Amendment) Act 2019, are not to be included under these headings.

EXCESS

Section 1

Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2

Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

NG KAI WEN (HUANG KAIWEN) - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

1. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 800 Sin Ming Ave Singapore 575733 69328000

2. Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

3. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 241 Alexandra Road Singapore 159931 64278800

4. Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: MayBank

I/We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia), Road Transport (Amendment) Act 2019 and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504822245

CYCLE & CARRIAGE-JEDD

239 ALEXANDRA ROAD

SINGAPORE 159930

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
AUTHORISED REPRESENTATIVE

SSCNMD