

ASS. REC. BY:

REF: CS3/CTI21000735/Bqf3

Special Instruction:

Surveyor: LIM

ASSIGNMENT (Office)

From (Person): TAN KAH LEONG of CTI Date/Time: 15 Jan 2021 11:45

Estimated Cost: Bill to:

OD ☒ TP WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No: SMT 7556H Insured: SLW 4634G

at Workshop m/s King's Auto Repair & Service Pte Ltd Tel: 64578629

of BLK 176 SIN MING DRIVE, #02-10, 575721 Sin Ming

Policy No: DMPCSNW00009342000 Claim No: SNM21D200247

Sum Insured: Excess:

Make of Veh: D.O.A. 14/01/2021
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP"

H.O.D. Endorsement:

Date/Time: 15-01-21 12.55P.M Person Contacted: ALEX Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (☒) Estimate
	SMT 7556H- ☒
	SLW 4634G- ☒