

Days granted medical leave	NIL	Degree of Injury	NIL
----------------------------	-----	------------------	-----

Brief Details.

On the 12/01/2021 at about 1311hrs I parked my vehicle bearing, (SMX898X) at the multi storey carpark located at Blk 34A Bedok South Avenue 2, Lot 164. Everything was intact at that point of time. On the same day at about 1710hrs I returned back to my vehicle and discovered that there were slight scratches at the front left side of my vehicle. I then immediately made a check on my in-car camera and noticed that on the 12/01/2021 at about 1449hrs it could be seen that a vehicle bearing, (SLN7131T) was attempting to park into a parking lot opposite my vehicle.

While attempting to park into the lot the said vehicle brushed through the front left side of my vehicle and subsequently adjusted his vehicle before parking at the parking lot which was opposite left of my vehicle. I then made a search around my vehicle and did not notice any note left by the said driver. I am not sure if the vehicle is still parked at the said location. I would like to inform that due to the accident my vehicle sustained scratches at the front number plate, bumper and grille.

My in-car camera has captured the accident and I do have a footage of the accident.