

ASS. REC. BY:

REF:

A/G/ 210007351Kp

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

07/21

Person Contacted:

Vehicle: IN / OUT

CK

Date / Time

Action / Instruction

20/11 11:50h Cofm

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trlp:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$

☐

: Weekend (\$

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Veh No:

SKB 9566J

Yr Regn:

07/11

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or

Make:

Hyundai Elantra c.c. 1391

Colour

M. Gray

A/C: Insured / Std / NI / NA

Sp. Reading

128484

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

KM14D141CMEU 215363

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rlm / STD A/Rlm or

Tyre Size:

F:

225/45R17

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

3

mm

R/Bal.

3

mm

L/Bal.

3

mm

L/Bal.

3

mm

D.O.A.

7/1/21

D.O.I.

18/1/2021

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

FR N/S

The UIC / Chassis frame / Body Structure affected due to collision.