



Your Ref : 1426702540SG

Date: 22<sup>nd</sup> Jan 2021

Our Ref : CS/AIG21000757/Etf3e2

**M/s Aig Asia Pacific Insurance Pte Ltd**

78 Shenton Way #09-16

Aig Building

Singapore 079120

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMK 4652E  
ACCIDENT ON 13/01/2021**

Instruction was received to inspect the vehicle Reg. No. SMK 4652E. The inspection was conducted on 15/01/2021 at the premises of M/s Cycle & Carriage Kia Pte Ltd, 209 Pandan Gardens, Singapore 609339.

The following vehicle information was recorded:

Registration Number	: SMK 4652E
Make/Model	: Kia Cerato 1.6 (A) EX
Year of Registration	: 2019
Body Colour	: Blue
Chassis Number	: KNAF3416MK5032049
Engine Capacity	: 1591 cc

The vehicle sustained damages at the front o/s and rear o/s portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 73,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 31,962.00)
Nett Liability	<u>S\$ 41,038.00</u> =====

Vehicle Inspected By:



CHEN TSUE YEE  
Automotive Assessor



K.K.LAU  
MSc(Eng M), B Eng(Hons), Peng(UK),  
MASME(USA), B Bus(Aust), MBA(UK),  
IEng(UK), MIIE(mech), MinstAEA, MFIEA,  
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),  
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),  
Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.