	21000764/Qqf1.
<u>AS</u>	SSIGNMENT
From: Date:	Veh No: 505 3165 Yr Regn: 21/01/2016.
Estimated Cost:	Type: (M.Ca) / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD / TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No:	Make: Mercedes benz AlAI80 c.c 1595
at Workshop m/s	Colour Purple. A/C: Insured / Std / NI / NA
of	Sp.Reading 102884 T/Radio: Insured / Std / NI / NA
Insured:	Eng/No:
Policy No. 1900083554	C/No: WDC156 94 225166 236
Claims No. 1426702540SG	Gen. Cond: Good (Fair) Poor / Burnt
Sum Insured: Excess:	Steering: In order / Jammed / Leaked / Burnt or
(Client's Record)	Brake: Introde Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rin / STD A/Rim or
	Tyre Size: F: 235/50 R18
(Policy Condition)	R: 235/50 R18
	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	
Bal. or Market Value:	Front Rear R/Ral 6 mm
IDAC Accident Rport: Consistent? : Yes or No	17501,
GIA / PR Seen: Consistent? : Yes or No	L/Bal. 6 mm L/Bal. 6 mm
Est. Repairs: 6 days Res.: Yes or No	D.O.A. 13/01/2021 D.O.I. 18/01/2021.
Lum Sum: % 3 Val.: Yes or No	Survey held at Toh Painting
CA / REV / REP. / 24 HRS	Des. of Damages : Frt / Rea / O/S / N/3 / U/C / Rooftop or
Vehicle: IN / Date: Person Contacted:	The U/C / Chassis frame / Body Structure affected due to collision.
Date / Time Action / Instruction	
	Repair day 6 days
Mv. 80,000	
pv' 47,595	<u> </u>
NV 32,405	
Submit DAR; 6 repair days.	
Date/Time, File Pass to? : Preli. Report	Days Of Repair: 6
1)27/01 Typist : Final Report	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
Ad	d Fee: : Site Insp (\$)s+Rssi

: Interview (\$

: Tech. Invs (\$

Weellend (\$

MER-DAR

Report Format :

Lump Sum / LBJ: (%

Photos

Others

TOTAL

# SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process

2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date of Submission Date of Accident **Exact Location of Accident** Additional Location Information

Country/State of Loss

13/01/2021 18:38 (SGT) 13/01/2021 10:40 (SGT)

Singapore

Singapore

### **DETAILS OF OWN VEHICLE**

Vehicle Registration Number

**SDS316S** 

INSURED/POLICYHOLDER

Is company?

Name Of Registered Owner

NRIC No

**Email Address** Mobile Phone No

Alternative Phone No

KOH YAU LIONG

SXXXX134C

VICTORY@BRAINERGY.BIZ

(Phone) +65-96805395

+65-96805395

VEHICLE PARTICULARS

Manufacturer

Model

Variant

Exact purpose for which vehicle was being used at time of

your vehicle?

Mercedes

Gla 180

Are you claiming under your own insurance policy for repair to

Vehicle Category

No - Claiming third party

Private car

INSURANCE COMPANY

Name of Insurance Company

Type of Coverage Fleet Policy

Policy Number

Cover Note Number

GA545431/1

DRIVER

Name of Driver

NRIC No

Date Of Birth Occupation

Axa

Comprehensive

KOH YAU LIONG SXXXX134C 23/01/1956 Indoor



Date Of Driving Pass 17/05/1977 Driving experience 43 YEARS AND 8 MONTHS Gender Male Mobile Number (Phone) +65-96805395 Alt. Phone Number +65-96805395 Email Address VICTORY@BRAINERGY.BIZ Address 49 SUMMER PLACE Address complement Postcode 555739 Is the driver the policyholder? Yes If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? No Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident Collision - Head to Rear Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident 2 Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other material or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) No soliciting/offering accident claims assistance? DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACHED ATTACHMENT(S) Are accident photos available for attachment? Yes

## DETAILS OF OTHER VEHICLE PROPERTY 1

No

No

 Vehicle Registration Number
 SMK4652E

 Vehicle Manufacturer

 Vehicle Model

 Vehicle Variant

 Vehicle Colour

 Vehicle Category
 Private car

 Name of Driver

 Contact Number
 (Phone) +65-97258289

 Address

 Address complement

 Postcode

 Insurance Company Name

Was there any video captured by Car Camera?

Was there any audio recorded?

Nature Of Damage Details of property damaged in accident No. Of Passenger (Including Driver)

### DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number

Vehicle Manufacturer Vehicle Model

Vehicle Variant Vehicle Colour

Vehicle Category Name of Driver

Contact Number

Address

Address complement

Postcode

Insurance Company Name

Nature Of Damage

Details of property damaged in accident No. Of Passenger (Including Driver)

SKL8861K

-

.

Private car

(Phone) +65-94763328

\_

-

\_

-

# SKETCH PLAN

# **IMPORTANT NOTICE**

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- Information provided must be as <u>truthful and accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- S. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

ANG MOKIO AVE 1. 8 B CMK: 465: C - GKL 8861 CTE

### DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

ON 13/1/21 @ ABOUT 1040 HR, I WAS STATIONARY IN MY VEHICLE SOS 316S, AT TRAFFIC LIGHT ALONG CTE SLIP ROAD (EXIT 11) TO ANG MO KID AVENUE 1, BOUNDARY ROAD DIRECTION. I WAS WAITING FOR TRAFFIC LIGHT TO TURN GREEN. SUDDENLY I HEARD A LOUD BANG & REALIZED VEHICLE SMK 4652E COLLIPED ONTO MY VEHICLE'S LH REAR CORNER. 1 ALIGHTED FROM MY VEHICLE THEN PEALIZED VEHICLE SKL 8861K WAS INVOLVED AS WELL. NO PASSENGERS. NO INJURIES.

# > Back to OneMotoring

**Enquire PARF/COE Rebate for Registered Vehicle** 

Vehicle Owner Particulars	
Owner ID Type:	Singapore NRIC
Owner ID:	134C
Vehicle Details	
Vehicle No.:	SDS316S
Vehicle to be Exported:	No
Intended Deregistration Date:	20 Jan 2021
Vehicle Make:	MERCEDES BENZ
Vehicle Model:	GLA180 (R18 BI)
Primary Colour:	Purple
Manufacturing Year:	2015
Engine No.:	27091030753501
Chassis No.:	WDC1569422J166236
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$27,477.00
Original Registration Date:	21 Jan 2016
First Registration Date:	21 Jan 2016
Transfer Count:	0
Actual ARF Paid:	\$25,468.00
Intended PARF Rebate Details	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	20 Jan 2026
PARF Rebate Amount:	\$19,101.00
Intended COE Rebate Details	
COE Expiry Date:	20 Jan 2026
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$56,989.00
COE Rebate Amount:	\$28,494.00
Total Rebate Amount:	\$47,595.00


The information contained herein is correct as at 20 Jan 2021

Rear Portion

Rear	Portion							
NAC	INC	Item	-	Too		·	<u> </u>	_
1137		Rear Number Plate		CC	אנ	A	99	<u>U</u>
1138		Rear Number Plate Base		-		_	4	_
1139	993630	Rear Number Plate Garnish	_		_		1	_
1140	993637	Rear Number Plate Lamp		-	_	_	1	_
114	1 00000	CIRAR Durana		-		-,	1	_
1142	2   993085	Rear Bunner Unner Chi -12		CR		1	1	
1143	1 77301	INCAL Bumber Louver Co. L.c. 1		Cn		_	1	
1144	1 773034	Hicear Bumner Side		CR	4		4	
1145	AA3103	Rear Bumper Tow Cover		-	-	_	+	-
1146	99234	Rear Bumper Cline		1			1	_
1147		Rear Bunner Bracket		1/16	C	1	1	_
1148	993068	Rear Bumper Side Retainer		-	_		1	_
1149	993049			BI	7	_		
1150	992970	Rear Burney D					Γ	_
1151	993077	Rear Bumper Spanes					I	_
1.152	992999	Rear Bumper Damper	_	_				
1153	1 773040	I Kear Human - D		_			Ι	
1154	993036	I Kear D		-	4		L	
1155	7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	Kear Pumper Mauli		-	4		L	_
1156				Ne		1	$\perp$	_
1157	1773023	Kear Bumper Laurence	_	_	4		$\perp$	_
1158	1	INCVERSE SERVER I II		Shor	-	_	+	
1159	993327	Rear End Panel		3407	4	2	╀	-
1160	9933339	Rear End Pond To	-	-	+		+	-
1162				-	+		╁	-
1163	7,0000	Dool Compartment Inna T.		_	7		-	_
1164	1 222021	INCOLL'H Laillamn		CRI	1	T	$\vdash$	٦
1165	993859	Rear LH Taillamp Garnish			+	·	1-	٦
1166	995116	Rear LH Taillamp Panel Rear RH Taillamp		CRU	1	1		
1167		Rear RH Taillamp Garnish						٦
1168	993859	IKear RH Taille b	-		7			
1169	1 333334	IKear Apron Panel	-		4	_	<u> </u>	4
1170	1 337832	Bootlid	4		+		-	4
1171	991328	B'ootlid Emblem	7		+	-	-	┥
		Bootlid Handle	7		+	-	-	┨
1174	995250	Bootlid Moulding	7		+	-	_	┥
1175		Bootlid Reflector	7		+		_	٦
1176	993222	Bootlid Lamp LH	7		1			1
	005243	Bootlid Lamp RH Bootlid Lock	I		T		_	1
1178	990377	Bootlid Rubber	1		I		_	]
1179	990382	Bootlid Hinge	4		-	4	_	1
1180	993877	Bootlid Spoiler	+	-	╁	-		4
1181	994543	Tailgate	+	nn	+	$\exists$	-	4
1182	991328		_	Nec	1	+		┨
1183	994643	Tailgate Outer Handle	+		+	7		1
1184	994640	Tailgate Moulding	+		$\dagger$	7		1
1185	994545		T		T	1	_	1
	994048	Tailgate Reflector ;	T		T	7		1
1187	994549	Tailgate Lamp	C	RU	1	1	_	1
1189	004676	Tailgate Protector	1					1
1190	994677	Tailgate Wiper Arm	$\perp$			T		1
1191		Tailgate Wiper Blade	L	:		I	_	1
1192		Tailgate Wiper Nozzle	L		L	$\perp$		1
1193		Tailgate Wiper Motor Tailgate Glass	1		L	$\perp$	_	1
1194	994606	l'ailgate Glass Rubber	1		Ĺ	Ţ		1
1195	994604	Tailgate Glass Moulding	1	12	<u> </u>	1		l
1196	994607	Tailgate Glass Sealant	H	rec	_		_	
1197	994629	Failgate Lock	1	1160		+		
1198		Tailgate Rubber	0	0.1	-	+		
1199	994611	l'ailgate Hinge	۲	Ry	1	+		
1200	994594	l'ailgate Damper	-			+-		
1201	994613	Tailgate Inner Board				+	-	
			٠.	1	-	1	_	


<u></u>			Vehicle No: SDS 31	6\$			
1202		2	Item		C	ON	A
1203	1	20	Spare Tyre Board				
1204		65	Spare Tyre Panel Spare Tyre		L		
1205		26	Spare Tyre Lock Screw		L		
1206	9937	87	Spare Tyre Cover		<u> </u>	_	_
1207	9953	23	Triangle Breakdown Sign	-	-		├-
1208	99050	07 J	CD Changer Assy	_	-		-
1209		64	Antenna	_	_	_	_
1211		34	Centre Exhaust Pipe Assy		_		$\vdash$
1212		32	Centre Exhaust Mounting				
-		27	Rear Exhaust Pipe				
1214	99336	<del>;; </del>	Rear Exhaust Chrome Pipe Li Rear Exhaust Mounting	1	S	R	
1215	79335	8	Rear Exhaust Heat Shield	-		_	
1216	99522	23	Rear LH Chassis Member			_	
1217	99316	55 [	Rear RH Chassis Member	-	-	-	_
1218	99343	6	Rear LH Fender		CI	24	1
1220	99344	0	Rear LH Fender Protector Gurm	ı h	Ch	u	1
1221			Rear LH Fender Inner Panel Rear LH Fender Inner Trim	4	_		
1222	1 99341	5 1	Rear LH Fender Inner Garnish	+		-	$\dashv$
1223	1 99342	5   1	Rear LH Fender Inner Shield	+	-	$\dashv$	$\dashv$
1224	99362	1   1	Rear LH Mudflan	+	_	+	-
1225	1	3   F	Rear LH Wheel Rim				7
1227	99506	2   2	Rear LH Rim Cover Rear LH Tyre				
1228		6 R	Lear RH Fender	$\perp$	_	1	I
1229	993450	)   R	ear RH Fender Protector	+-	_	+	+
1230	993420	) R	ear RH Fender Inner Panel	+	_	+	+
1231 1232	793431	I IR	car RH Fender Inner Trim	土		$\perp$	+
1233	993425	TR	ear RH Fender Inner Garnish ear RH Fender Inner Shield	4	_	I	I
1234	993622	! IR	ear RH Mudflan	╁	_	+	4
1235	993934	HK	ear RH Wheel Rim	+	_	+	+
	994025	R	ear RH Rim Cover	$\top$	_	+	+
1238	995162	H	ear RH Tyre ear Fender Extension Panel LH		_		
1239	993471	R	car Fender Extension Panel RH	+		1	$\perp$
1240	<b>YY343</b> U	HR.	Car Fender Inner Ton C	+		+	+
	223013	IK	car Fender 1/4 Glace	┿	_	+	+
	993452	R	ear Fender 1/4 Glass Rubber		<u>.</u>	+	+
	222343	IK	ear Fender 1/4 Glass Scalant car Windscreen Glass	-	_	T	工
1243	993976	$\int \mathbf{R} d\mathbf{r}$	ear Windscreen Rubber	╀		+	+
1240	993961	R	ar Windscreen Moulding	1	_	+	十
1248	993933	K	ear Windscreen Sealant hird Brake Light		_	T	十
1249	993385	Ro	ar Fender Air Grille	F	_	F	T
1230	992167	Fu	el Lid	-		-	+
1251	992168	Fu	el Neck	-		+	+
1252	992179	Fu	el Tank	$\vdash$	_	-	+
	992184	Pu	el Tank Bracket		_		+
	992191	PU	el Tank Float				
11.517			ur LH Door	-	_	L	L
		1/6	41 - 11 100F	٦	(	<u> </u>	1
					-		+
					$\dashv$	_	+
		_	·	_		_	
				_		_	
			,		_		
					+		_
					+		_
					-		

No of Items: 19 Assessor: Sun Pm



Compare

### Used Mercedes-Benz GLA-Class Cars | Singapore Car Prices & Listing - sgCarMart



sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or stationwagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, financial services, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mercedes-Berz GLA-Class, used vehicles Singapore used Mercedes-Berz GLA-Class, used vehicles Singapore or even buy used Mercedes-Berz GLA-Class, used vehicles Singapore or even buy used Mercedes-Berz GLA-Class Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, real estate, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

#### Follow sgCarMart.com

About Us | Careers | Contact Us | Sitemap Terms of Service | Privacy Policy | Personal Data Protection Statement ©2004-2021 sgCarMart, Singapore. All rights reserved.