



SERVICE REQUESTS

MESSAGES

CLAIMS



Service Request Details

Claim	S1M030M0
Reference	CS3/ASM21000769/Gvf3e2 
Loss Date	13 January 2021
Report Date	14 Jan 2021 3:06:15 PM
Request Date	15 January 2021
Due Date	
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Services	Pre-Repair Survey

Actions

Next Step Wait for: Approve
invoice

[Add Invoice](#)

Vehicle Information

Incident SLV200G
Vehicle
Registration #

Make TPVD

Model UNKNOWN

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE, 575717, Singapore
65551188

Claim Handler

TAN Jun Hong

junhong.tan@axa.com.sg

Additional Instructions

1

Messages Invoices History Documents Assessment Metrics Notes

Document Type

Document SubType

+ Upload Documents

NAME	TYPE	SUB-TYPE	AUTHOR	DATE UPLOADED
 ASM-LKKInvoice-AC2100648.pdf	Invoice	Surveyor/ Assessor expense	LKK AUTO CONSULTANTS PTE LTD (TP)	29 January 2021
 LKKPreRepairInspection.pdf	Reports & Statement	Survey Report	LKK AUTO CONSULTANTS PTE LTD (TP)	29 January 2021
 IA.pdf	Forms / Claim Documents	Others	LKK AUTO CONSULTANTS PTE LTD (TP)	18 January 2021
 LKKPhotosIn4.pdf	Evidence	Photos	LKK AUTO CONSULTANTS PTE LTD (TP)	18 January 2021

NAME	TYPE	SUB-TYPE	AUTHOR	DATE
 SLV200G GIA Report.pdf	Reports & Statement	GIA Report	TAN Jun Hong	16 January 2021
 SHD3708G GIA Report.pdf	Letters and Correspondence	Third Party	TAN Jun Hong	16 January 2021
 SHD3708G INSD GIA.pdf	Reports & Statement	GIA Report	NIKAM Santosh Pandurang	14 January 2021
 EMAIL FROM SOLICITOR FOR TP REG.msg	Letters and Correspondence	Others	NIKAM Santosh Pandurang	14 January 2021