

ASS. REC. BY:

REF: CS3/ASM21000769/Gvf3

Special Instruction:

Surveyor: GQ ASSIGNMENT (Office)From (Person): Tan Jun Hong of AXA Date/Time: 15/1/2021 10:19 AM

Estimated Cost: _____ Bill to: _____

OD-☒TP/WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SLV 200G Insured: SHD 3708Gat Workshop m/s A-TEC Automotive Pte Ltd Tel: 63845206of 8 Kaki Bukit Avenue 4 #04 - 20 Premier SingaporePolicy No: _____ Claim No: S1M030M0

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 13-01-21
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP"

H.O.D. Endorsement: _____

Date/Time: 15-01-21 5.45P.M Person Contacted: PEGGY Vehicle ☒IN ☐OUT

Date/Time	Action/Instruction (☒) Estimate
	SLV 200G- ☒
	SHD 3708G- CC3/AXA12023233/H1v1f3u2 DOA :29/11/2012
18/1/21	Send IA via Smart Claim
18/1/21	Submit PRS, repair range \$5,000-\$6,000