



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving TPVD UNKNOWN UNKNOWN (PNK1981)

Date of Loss 13 January 2021

Time of Loss 9.45

Loss Description GBD518D (TP) rear-end SHB2292E (INSD)
PNK1981 (TP) self-skidded

Comment

Workshop Details

Total Rebate Amount

0

Nett Loss Amount

\$0.00

Assigned Workshop

LKK AUTO CONSULTANTS PTE LTD (TP)

Days of work
completion *

20



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration#	PNK1981	Purchase Date	<div>dd/mm/yyyy</div> <div></div>
Registration State	<div>SINGAPORE</div>	Registration Date *	<div>01/01/2018</div> <div></div>
Mileage	<div></div>	Age of Vehicle	3

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year		<div>2017</div>
Make	TPVD UNKNOWN	<div>HONDA</div>

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	TBC	<div></div>
Date of Birth		<div>dd/mm/yyyy</div> <div></div>

Model CATEGORY	UNKNOWN POLICY INFORMATION	PCX (A)
Type		<div>▼</div>
Type of Paint		
Chassis No		PMKKF2170JB100748
Engine No		HIDDEN
Engine Capacity		129
Sum Insured		0
Market Value		0

CATEGORY Age	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	
Education Qualification	Other	<div>▼</div>
Driving Experience	0	
Driver License #		
License Type		<div>▼</div>
License Issue Date		<div>dd/mm/yyyy</div> <div></div>
License Expiration Date		<div>dd/mm/yyyy</div> <div></div>

CATEGORY	FNOL INFORMATION	POST SURVEY
Address	SG, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>
Gender	Unknown	<input type="text" value="▼"/>
Marital status	Unknown	<input type="text" value="▼"/>
Identification #	TBC	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

18/01/2021



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

0

Young/Inexperienced/
Unnamed Driver
Excess

0

Condition of Vehicle at time of survey

General condition

Good



Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake
(Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good



Other Excess

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

Rear Tyre Size

Front left side

Rear left side

Front right side

Rear right side



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%	<input type="text"/>	Salvage%	<input type="text"/>
Discount%	<input type="text" value="10"/>	Settlement%	<input type="text" value="100"/>

Paint Labour/Material Ratio

Paint Labour Ratio	<input type="text" value="20"/>	Paint Material Ratio	<input type="text" value="80"/>
--------------------	---------------------------------	----------------------	---------------------------------

Cash Loss

YesNo

Part Supplied by AXA

YesNo

Save



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Parts










Add











Approve









Deny

Submit All

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		HEADLAMP ASSY	Cut	0	485	No		10			436.5	Reviewing
<input type="checkbox"/>		0	1		HEADLAMP GRILLE	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT HEADLAMP STAY	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT PLASTIC SHIELD COVER	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		KEY IGNITION COVER	Damaged	0	312	No		10			280.8	Reviewing
<input type="checkbox"/>		0	1		REAR SIGNAL LAMP RH	Serviceable	0	0	No		10			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		FRONT WING MIRROR RH	Cut	0	195	No		10			175.5	Reviewing
<input type="checkbox"/>		0	1		FRONT HANDLE BAR	Bent	0	295	No		10			265.5	Reviewing
<input type="checkbox"/>		0	1		FRONT HANDLE BALANCER RH	Dented	0	76	No		10			68.4	Reviewing
<input type="checkbox"/>		0	1		FRONT HANDLE GRIP	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT FENDER RH	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT FENDER INNER COVER	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		HEADLAMP COVER GUARD OUTER	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		HEADLAMP COVER GUARD INNER	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT LOWER SIDE COVER O/S	Cracked	0	496	No		10			446.4	Reviewing

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		LOWER SIDE COVER	Cracked	0	580	No		10			522	Reviewing
<input type="checkbox"/>		0	1		SIDE STAND	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FOOT REST PANEL RH	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR PILLION FOOT REST RH	Dented	0	80	No		10			72	Reviewing
<input type="checkbox"/>		0	1		REAR PILLION FOOT REST BRACKET RH	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		FRONT BRAKE HANDLE	Dented	0	165	No		10			148.5	Reviewing
<input type="checkbox"/>		0	1		FRONT STEP BRAKE	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR SIDE COVER RH UPPER	Cracked	0	155	No		10			139.5	Reviewing
<input type="checkbox"/>		0	1		REAR SIDE COVER RH LOWER	Cracked	0	155	No		10			139.5	Reviewing
<input type="checkbox"/>		0	1		REAR FENDER GUARD RH	Serviceable	0	0	No		10			0	Deny

	EDIT	SR NO	QUAN TITY	MATERIAL	PART NAME	CONDITION	LIST PRICE (WORKSHOP)	LIST PRICE (SURVEYOR)	SUPPLEMENTARY PARTS	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	ESTIMATED AMOUNT	ADJUSTED AMOUNT	ACTION (PARTS)
<input type="checkbox"/>		0	1		REAR WHEEL PROTECTOR	Dented	0	195	No		10			175.5	Reviewing
<input type="checkbox"/>		0	1		REAR WHEEL PROTECTOR BRACKET	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR FENDER EMBLEM - PCX	Necessary	0	60	No		10			54	Reviewing
<input type="checkbox"/>		0	1		REAR EXHAUST COVER BRACKET	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR EXHAUST COVER	Dented	0	218	No		10			196.2	Reviewing
<input type="checkbox"/>		0	1		REAR TOOLS BRACKET	Repair	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		REAR TOOLS HANDLE	Serviceable	0	0	No		10			0	Deny
<input type="checkbox"/>		0	1		ENGINE SIDE COVER	Serviceable	0	0	No		10			0	Deny

Labour







Add

Approve

Deny

Submit All

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
------	-------	-------------------------	-----------	------------------------	------------------------	-----------------------	-----------------------	-----------------	---------

	EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	ESTIMATE LABOUR AMOUNT	ADJUSTED LABOUR AMOUNT	ESTIMATE PAINT AMOUNT	ADJUSTED PAINT AMOUNT	ACTION (LABOUR)	COMMENT
<input type="checkbox"/>		0		STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	0	180	0	0	Reviewing	
<input type="checkbox"/>		0		SPRAY PAINTING ON ACCIDENT AREAS	0	0	0	0	Deny	
<input type="checkbox"/>		0		CONDUCT FULL WHEEL ALIGNMENT	0	0	0	0	Deny	
<input type="checkbox"/>		0		CHECK & REPAIR WIRING SYSTEM	0	15	0	0	Reviewing	
<input type="checkbox"/>		0		BALANCE FRONT WHEEL					Deny	
<input type="checkbox"/>		0		BALANCE REAR WHEEL					Deny	



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary







Add

Approve

Deny

Submit All

	EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	DAYS OF REPAIR : 4 DAYS	Reviewing		0		
<input type="checkbox"/>		0	REAR EXHAUST PIPE	Reviewing		120	DENTED	
<input type="checkbox"/>		0	TOP BOX	Reviewing		200	CUT	
<input type="checkbox"/>		0	REAR TOP BOX CARRIER	Deny		0	REPAIR	

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FRONT NO. PLATE	Deny	0	SERVICEABLE	
<input type="checkbox"/>		0	REAR NO. PLATE	Reviewing	18	BENT	
<input type="checkbox"/>		0	FRONT PLASTIC SHIELD STICKER - HONDA	Deny	0	NOT NECESSARY	



Assessment Details

General & Workshop Details		Vehicle & Driver Details	Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00		Adjusted Claim Amount		\$3,653.30	
CATEGORY		ESTIMATE		ADJUSTED			
Spare Parts		\$0.00		\$3,120.30			
Labour		\$0.00		\$195.00			
Miscellaneous		\$0.00		\$338.00			

Submit for Review



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Add

Approve

Deny

Submit All

EDIT	SR NO	NAME	ACTION	ESTIMATED AMOUNT	ADJUSTED AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		0	FINAL LUMP SUM	Reviewing	2000		



General & Workshop Details		Vehicle & Driver Details		Vehicle Condition	Taxes & Ratio	Parts & Labour	Miscellaneous	Summary
Estimated Claim Amount		\$0.00				Adjusted Claim Amount		\$2,000.00
CATEGORY		ESTIMATE		ADJUSTED				
Miscellaneous		\$0.00		\$2,000.00				
<div>Submit for Review</div>								