

ASS. REC. BY:

Steve

REP:

CS/AIG 21000784/EVO3

ASSURANCE

Form:

Date:

Estimated Cost:

CH / TR / W / R / RES / OD / RES / EVA / INV / MV

To Insured Vehicle Rec:

at Workshop info:

Insured:

Policy No:

Claim No:

Sum Insured:

Excess:

(Check / Personal)

Make of Vn:

(Policy Condition)

Remarks: The veh had commenced its repair at the time of inspection.



Ref. or checked Value:

IDAC Accident Report:

Consistent? : Yes or No

GLA / PR. Cons:

Consistent? : Yes or No

Est. Repair:

days

Res.: Yes or No

Loss Cost:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

File

Person Contacted:

Date / Time Action / Instruction

MV-94K

Veh No:

SLG 811Y

Yr Regn:

20/3/19

Type:

Motor / Bicyclo / Bus / Van / Lorry / Truck / Other

Truck / Trailer or

Make:

Mitsubishi Outlander

cc 1998

Colour:

Blue

Insured / Not Insured

Sp. No:

33997

Titled: Insured / Not Insured

Eng No:

GT 1W 060692

C/Nr:

Gen. Cond: Good / Fair / Poor / Damage

Steering: Locked / Jammed / Locked / Burnt or

Brake: Locked / Jammed / Locked / Burnt or

Mod: All / Other / STD Affix or

Tyre Size:

P:

275/55R18

R:

BS / DUN / EXNOVA / CY / PS / LIZAJ / MIC / OKTBU / PIR / SUEI

TOYO / YOKO or

17yo

Front

Rear

R/Sd.

4

mm

R/Sd.

4

mm

L/Sd.

4

mm

L/Sd.

4

mm

D.O.A.

15/1/21

D.O.I.

18/1/21

Survey held at

cycle & Carriage

Des. of Damages: Frl / Rear / O/S / W/S / UIC / Rooflap or

The UIC / Chassis frame / Body Structure affected due to collision

Ref. No. / File No. / Date

: Prel. Report

: Final Report

Days Of Repair:

Recovery No. of Trip:

Survey Fee:

Yanapattent

Add Fee:

: Site Insp (\$

: Interview (\$

: Tech. Insp (\$

: Weekend (\$

: S. & RS. \$

: Photos

: Others

TOTAL

App. / Form:

map 2000 / LB. / 1



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10755/LEE LAI WEI Reg No/Reg Date SLG811Y / 20/03/201 Date In/Mileage / 33207 Chassis No GF7W0600602 Engine No 4J11AC3741 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	16/01/2021/ 11:00	QUC	247 / DonBong	61959			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 RENEW ACCIDENT DAMAGED PARTS ON FRONT SUPPORT PANEL, FRONT BONNET, RH FRONT FENDER, FRONT BUMPER FACE, LH FRONT FENDER REPAIR RH FRONT DOOR, REPAIR LH FRONT DOOR					450 X 5			2250.00
E PNT88000 REMOVE AND INSTALL RADIATOR AND A/CON CONDENSER TO FACILITATE REPAIR WORK					(photo)			100.00
A 55900099 TOP UP AIR CON GAS AND CHECK A/CON SYSTEM								80.00
E PNT98000 PAINT WORK SPRAY FRONT SUPPORT PANEL, FRONT BONNET, RH FRONT DOOR, RH FRONT FENDER, LH FRONT DOOR, LH FRONT FENDER, FRONT BUMPER AND AFFECTED PORTION					2450			2800.00
M SUNDRY APPLY BODY SEALANT					40			120.00
A 54900099 CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM								30.00
M SUNDRY PERFORM RUST PREVENTION					40			120.00
A 10028901 TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST								120.00
M SUNDRY SUPPLY FRONT NUMBER PLATE WITH FRAME								50.00
M SUNDRY SUNDRIES					30			50.00
M PNL, HEADLAMP SUPT, UPR RH ✓ BT					1.00	58.00	23.00	44.66
M PANEL, HEADLAMP SUPPORT, UPR ✓ BT					1.00	182.00	23.00	140.14
M PNL, HEADLAMP SUPT, UPR LH ✓ BT					1.00	58.00	23.00	44.66
M PANEL, HEADLAMP SUPPORT, LWR ?					1.00	107.00	23.00	82.39
M CONDENSER ASSY, A/C REFRIGE ✓ BT					1.00	857.00	23.00	659.89
M HOSE, A/C COMPR DISCHARGE ?					1.00	191.00	23.00	147.07
M RADIATOR ASSY ✓ BR (photo)					1.00	1091.00	23.00	840.07

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10755/LEE LAI WEI Reg No/Reg Date SLG811Y / 20/03/201 Date In/Mileage / 33207 Chassis No GF7W0600602 Engine No 4J11AC3741 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	16/01/2021/ 11:00	QUC	247 / DonBong	61959			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LLC	4L	✓ nec		1.00	26.00	23.00	20.02
M	FAN, COOLING, LH		✓		1.00	78.00	23.00	60.06
M	FAN, COOLING, LH		✓		1.00	78.00	23.00	60.06
M	SHROUD, COOLING FAN		✓		1.00	258.00	23.00	198.66
M	MOTOR, COOLING FAN, LH(120W)		✓		1.00	479.00	23.00	368.83
M	MOTOR, COOLING FAN, LH(120W)		✓		1.00	479.00	23.00	368.83
M	COVER, HEADLAMP SUPT. PANEL		✓ CRU		1.00	50.00	23.00	38.50
M	COVER, FR BUMPER		✓		1.00	25.00	23.00	19.25
M	CLIP, RR BUMPER		✓ nec		10.00	3.00	23.00	23.10
M	GRILLE ASSY, RADIATOR		✓ BR		1.00	548.00	23.00	421.96
M	HEADLAMP ASSY, LH		✓ BR		1.00	1938.00	23.00	1492.26
M	HEADLAMP ASSY, RH		✓ BR		1.00	1938.00	23.00	1492.26
M	HOOD		✓ DO		1.00	975.00	23.00	750.75
M	HINGE, HOOD, LH		✓		1.00	68.00	23.00	52.36
M	HINGE, HOOD, RH		✓		1.00	68.00	23.00	52.36
M	INSULATOR, HOOD		✓ CRU		1.00	133.00	23.00	102.41
M	CLIP, HOOD INSULATOR		✓ nec		8.00	3.00	23.00	18.48
M	WEATHERSTRIP, HOOD		✓		1.00	40.00	23.00	30.80
M	WEATHERSTRIP, HOOD		✓		1.00	41.00	23.00	31.57
M	LATCH, HOOD		✓		1.00	76.00	23.00	58.52
M	EMGINE HOOD EMBLEM		✓ nec		1.00	80.00	23.00	61.60
M	BRACKET, FR BUMPER SIDE, LH		✓ BR		1.00	18.00	23.00	13.86
M	BRACKET, FR BUMPER SIDE, RH		✓ BR		1.00	18.00	23.00	13.86
M	FACE, FR BUMPER		✓ BR		1.00	859.00	23.00	661.43
M	COVER, FR BUMPER		✓ (Silver) CRU		1.00	359.00	23.00	276.43
M	EXTENSION, FR BUMPER		✓ (Black) BR		1.00	515.00	23.00	396.55
M	GARNISH, FR BUMPER, LH		✓		1.00	48.00	23.00	36.96
M	GARNISH, FR BUMPER, RH		✓ mis (fgy kp)		1.00	48.00	23.00	36.96
M	CLIP, ENG ROOM COVER		✓ nec		10.00	2.00	23.00	15.40
M	LH GARNISH, FR BUMPER SIDE		✓		1.00	48.00	23.00	36.96
M	RH GARNISH, FR BUMPER SIDE		✓		1.00	48.00	23.00	36.96
M	LH GARNISH, FR BUMPER SIDE		✓ BR		1.00	220.00	23.00	169.40
M	RH GARNISH, FR BUMPER SIDE		✓ BR		1.00	220.00	23.00	169.40

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #09-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV10755/LEE LAI WEI Reg No/Reg Date SLG811Y / 20/03/201 Date In/Mileage / 33207 Chassis No GF7W0600602 Engine No 4J11AC3741 Make/Model MIT/19MY OUTLANDER 2.0 MODERN(995) Colour/Trim D01 COSMIC BLUE MET/ BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	16/01/2021/ 11:00	QUC	247 / DonBong	61959			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
M	LH GARNISH,FR BUMPER SIDE	✓	BT		1.00	112.00	23.00	86.24
M	RH GARNISH,FR BUMPER SIDE	✓	BT		1.00	112.00	23.00	86.24
M	REINF,FR BUMPER SIDE,RH	✓	BT		1.00	69.00	23.00	53.13
M	REINFORCEMENT,FR BMR SIDE	✓	BT		1.00	22.00	23.00	16.94
M	REINF,FR BUMPER SIDE,LH	✓	BT		1.00	60.00	23.00	46.20
M	REINFORCEMENT,FR BUMPER	✓	BT		1.00	134.00	23.00	103.18
M	BAR,FR BUMPER GUARD	✓	BT		1.00	130.00	23.00	100.10
M	REINFORCEMENT,FR BUMPER	✓	BT		1.00	490.00	23.00	377.30
M	GARNISH,FR LICENSE PLATE	✓	CR4		1.00	23.00	23.00	17.71
M	FENDER,FR RH	✓	BT		1.00	688.00	23.00	529.76
M	FENDER,FR LH	✓	BT		1.00	688.00	23.00	529.76

Estimate

SURVEYOR NAME : Steve CLKK
 SURVEYOR SIGNATURE : 18/1/21, 12:30pm
 DATE : DD-NM AL
 REMARKS : EXCIS - ?

PIP
My BL SKY
9 dgs

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey

- Confirm & accepted by**
- Repairer's estimate subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Authorized signatory and company stamp

	Nett	17,212.25
7% GST on	17212.25	1204.86
Total Payable		18,417.11

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	15/01/2021 18:02 (SGT)
Date of Accident	15/01/2021 09:10 (SGT)
Exact Location of Accident	TPE, Singapore
Additional Location Information	KPE TUNNEL ENTRANCE TOWARDS MCE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLG811Y
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	LEE LAI WEI
NRIC No	SXXXX544E
Email Address	PAMELA.LAIWEI@GMAIL.COM
Mobile Phone No	(Phone) +65-93676333
Alternative Phone No	+65-93676333

VEHICLE PARTICULARS

Manufacturer	Mitsubishi
Model	Outlander
Variant	-
Exact purpose for which vehicle was being used at time of accident	-
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	AIG
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	1900067184
Cover Note Number	-

DRIVER

Name of Driver	LEE LAI WEI
NRIC No	SXXXX544E
Date Of Birth	30/04/1987
Occupation	Indoor

Of Driving Pass
Driving experience
Gender
Mobile Number
Alt. Phone Number
Email Address
Address
Address complement
Postcode
Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

18/08/2007
13 YEARS AND 5 MONTHS
Male
(Phone) +65-93676333
+65-93676333
PAMELA.LAIWEI@GMAIL.COM
BLK 890A TAMPINES AVENUE 1 #15-309
-
521890
Yes
-
No
-
-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident
Weather Conditions
Road Surface

Collision - Head to Rear
Clear
Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident?
Number of vehicles involved in the accident
Was anybody injured in the Accident?
Was any injured conveyed to hospital by ambulance?
Was any other material or property damaged?
Number of Passengers (Including Driver)
Has the driver been approached by unknown person(s)
soliciting/offering accident claims assistance?

No
4
No
-
Yes
1
No

DETAILS OF POLICE ACTION

Was the accident reported to the police?
Was notice of intended Prosecution given?
If yes, against whom?

No
No
-

CIRCUMSTANCES OF ACCIDENT

REFER TO ATTACHMENT

ATTACHMENT(S)

Are accident photos available for attachment?
Was there any video captured by Car Camera?
Was there any audio recorded?

Yes
Yes
No

DETAILS OF OTHER VEHICLE PROPERTY 1:

Vehicle Registration Number
Vehicle Manufacturer
Vehicle Model
Vehicle Variant
Vehicle Colour
Vehicle Category
Name of Driver
Contact Number
Address
Address complement
Postcode
Insurance Company Name

SMU9119T
Volkswagen
Touran
-
Blue
Private car
-
-
-
-
-

Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -

DETAILS OF OTHER VEHICLE PROPERTY 2:

Vehicle Registration Number SKA9944G
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver -
 Contact Number -
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -

DETAILS OF OTHER VEHICLE PROPERTY 3:

Vehicle Registration Number SJH3922J
 Vehicle Manufacturer -
 Vehicle Model -
 Vehicle Variant -
 Vehicle Colour -
 Vehicle Category Private car
 Name of Driver -
 Contact Number -
 Address -
 Address complement -
 Postcode -
 Insurance Company Name -
 Nature Of Damage -
 Details of property damaged in accident -
 No. Of Passenger (Including Driver) -

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")


- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan




Describe Circumstances of the Accident


The first car black Mercedes SJH2922T entered suddenly, causing the white Mercedes SKA 99446 to collide into it. The blue Volkswagen SMU 9119T was behind SKA 99446 but barely managed to brake in time to not knock into the white Mercedes. I was behind the SMU 9119T and noted the third car e-braking in front of me. I also attempted to e-brake but still hit the rear end of SMU 9119T.

Declaration

We declare the foregoing particulars are true in every respect.

 15/11/21
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time


Witnessed by Reporting Centre Personnel

CERTIFICATE OF INSURANCE

CYCLE & CARRIAGE AUTO PROTECTOR PRIVATE VEHICLE

Name of Policyholder : Lee Lai Wei
 Period of Insurance : 20 Mar 2019 To 19 Mar 2021
 Engine No. : 4J11AC3741
 Chassis No. : GF7W0600602

Vehicle No. : SLG811Y
 Policy No. : 1900067184
 Endorsement No. :
 Issued Date : 26 Mar 2019

ABOUT THE COVER

Make/Model : MITSUBISHI Outlander 2.0 Elegance/Sports
 Engine Capacity/Tonnage : 1,998.00 CC Sum Insured : Market Value First Year of Registration : 2019
 Driver Restriction : NA Off Peak Car : No Insuring with COE/PARF : Yes

Person or Classes of Persons Entitled to Drive* :

- a) The Policyholder
 b) Any other person who is driving on the Policyholder's order or with his/her permission.
 This Policy will indemnify the Policyholder or any authorised driver only if he/she meets the specified age condition.

You have to pay an additional sum of \$3,000 as "Young and/or Inexperienced Driver Excess" ("YIDR") if You are or Your Authorised Driver (named or unnamed) is under the age of 23 and/or has less than 2 years' driving experience.

Age Condition : All Age Condition

Limitation as to use* :

Use only for social, domestic and pleasure purposes and for the Policyholder's business.
 This Policy does not cover use for hire or reward, driving tuition, driving test, racing, pace-making, reliability trial or speed-testing, the carriage of goods other than samples in connection with any trade or business or use for any purpose in connection with Motor Trade.

Loss of Use 1500cc - 1600cc

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Cap. 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

EXCESS

Section 1
 Fire - \$0 Own Damage - \$600 Theft - \$0 Flood Cover - \$0

Section 2
 Property Damage - \$0

Windscreen : \$100

Named Driver and Excess (where applicable)

Lee Lai Wei - \$600 (Own Damage)

APPROVED REPORTING CENTRES/AUTHORISED REPAIRERS (FOR CLAIMS RELATED REPAIRS)

- 1 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 600 Sin Ming Ave Singapore 575733 69328000
- 2 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 20 Leng Kee Rd Singapore 159094 64708688
- 3 Cycle & Carriage Authorised Service Centre (For accident reporting & windscreen claim only) Add: 330 Ubi Rd 3 Singapore 408650 67461000
- 4 Cycle & Carriage Body & Paint Centre Add: 209 Pandan Gardens Singapore 609339 65684501

For other Approved Reporting Centres/AIG Authorised Repairers, please contact our 24-hour accident emergency hotline at +65 6338 6200. Alternatively, you may refer to AIG website www.aig.com.sg or AIG SG Mobile App. Simply search and download "AIG SG" from iTunes or Google Play.

IMPORTANT NOTES

Hire Purchase Company/Employer's Loan: United Overseas Bank Limited

We hereby certify that the policy to which this Certificate of Insurance relates is issued in accordance with the provisions of the Motor Vehicles (Third Party Risks and Compensation) Act (Cap. 189), Part IV of the Road Transport Act, 1987 (Malaysia) and Motor Vehicles (Third Party Risks) Rules, 1959 (Malaysia).

0504623050

FULCOMIP2 - CORPORATE
 22 UBI ROAD 4 FULCO BUILDING
 SINGAPORE 408617

Underwritten by AIG Asia Pacific Insurance Pte. Ltd.

AIG Asia Pacific Insurance Pte. Ltd.
 AUTHORISED REPRESENTATIVE

SSCNFY