PRS Filed By: GQ | REF: CS3/SMO20010487/Dqd3-1

PRS

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s BLUWEL AUTO

of

Insured:

Policy No.

Claims No. CMTD2002855/THE

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

	N/S	O/S

Bal. or Market Value:

IDAC Accident Rport: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 9 days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SKK 3185S Yr Regn: 28/06/2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover / Truck / Trailer or —

Make: TOYOTA PRIUS c.c 1497

Colour Orange A/C: Insured / Std / NI / NA

Sp.Reading 87294 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JTDKD3B3601046142 *

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Shorde / Jammed / Leaked / Burnt or

Brake: Shorde / Jammed / Leaked / Burnt or

Modi : Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/60R15

R: 185/60R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or CST

Front		Rear	
R/Bal.	6 mm	R/Bal.	6 mm
L/Bal.	6 mm	L/Bal.	6 mm
D.O.A.		D.O.I.	30-09-2020

Survey held at W/S 3:30pm

Des. of Damages : Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	$6000 - $7000
	GIA give later
	Submit LS $6000, 9 days (Red $9500, 61%)
	Note: MV:$26K(est); LTA:$20K(est); NV:$6000

Date/Time, File Pass to? : Preli. Report

1) 03/02 Typist : Final Report

Date/Time, File Return to?

2)

Days Of Repair: 9

Resurvey No. of Trip:

Add Fee: : Site Insp ($)

: Interview ($)

: Tech. Invs ($)

: Weekend ($)

Survey Fee:

Transportation:

S + RS. SI

Photos

Other

TOTAL

Report Format: TP

Lump Sum Limit: 6000