

ASS. REC. BY:

REF: CS3/SMO21000805/QKvf3

Special Instruction:

Surveyor: SUN PIN ASSIGNMENT (Office)From (Person): GRACE TEO of SMO Date/Time: 18/1/2021 11:52 AM

Estimated Cost: _____ Bill to: _____

OD-☒TP/WS/TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SJE 3338L Insured: SCY 652Bat Workshop m/s ENG SOON PAINTING Tel: 97272519of Block 4 Yew Tee Industrial Estate 393-J Woodlands Road Singapore 677978.Policy No: _____ Claim No: CMTD2100178/SYH

Sum Insured: _____ Excess: _____

Make of Veh: _____ D.O.A. 15-January-2021
(Client's Record)

CA / REV / REP. / REV 24 HRS "WP"

H.O.D. Endorsement: _____

Date/Time: 18-01-21 1.09P.M Person Contacted: MR TEO Vehicle ☒IN ☐OUT

Date/Time	Action/Instruction (☒) Estimate
	SJE 3338L- ☒
	SCY 652B- NA/MGA08012228/Aw1 DOA :15/04/2008
20/1/21	Submit PRS, repair range \$2000-\$3000 (3 days)