

ASS. REC. BY:

REF:

CS/U0121000806/R1/f3

8302

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

☒ TP/WS/TP RES/OD RES/EVA/INV/MVTo Inspect Vehicle No: SLZ 2892Aat Workshop m/s MOTOR IMAGEof 25, LENTH KOK RDInsured: UOI

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: TBA 500

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 79K

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / ☒ REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SLZ 2892A Yr Regn: 2018 / APRType: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: SUZUKI FORESTER 2.0I c.c. 1985Colour: GREY A/C: Insured / Std / NI / NASp. Reading: 063489 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JF1SJ5KCSJG107854Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: Nil / ☒ S/Rim / STD A/Rim orTyre Size: F: 225/60R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / ☒ MIO / OHTSU / PIR / SUMI /
TOYO / YOKO or .

Front

Rear

R/Bal. 6 mm R/Bal. 6 mmL/Bal. 6 mm L/Bal. 6 mmD.O.A. 13/01/2021D.O.I. 22/01/2021Survey held at MOTOR IMAGEDes. of Damages: ☒ Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	Repair limit = 42K
	Finalised amount is \$ 9047.56 BEFORE excess / 5 days of repair
	RED: 6592.44; 42%

Date/Time, File Pass to?

☐ : Prel. Report
☐ : Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. SI

Photos

Others

TOTAL

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Rep. Format: _____

Lump Sum / L.S.F. (\$) _____

MAGE ENTERPRISES PTE. LTD.
LENG KEE ROAD
SINGAPORE 159097

ESTIMATE : ACCIDENT/BODY REPAIRS
WORKSHOP : LENG KEE
CONTACT NO :
REFERENCE : INS/IC/LHI/0005/2021
DATE : 16-JAN-2021

UNITED OVERSEAS INSURANCE LIMITED
3 ANSON ROAD
#28-01 SPRINGLEAF TOWER
S(079909)
TEL : 62227733(16 LINES)
FAX : 2242718
UPDATED 16JUN2005

OWNER'S NAME : WONG KOK WAH
ADDRESS : APT BLK 20 JALAN MEMBINA
#15-42
S(164020)
TELEPHONE NO : 98386487

TYPE OF CLAIM : COMPREHENSIVE CLAIM
POLICY NO : 1
VEHICLE NO : SLZ2892A
MODEL CODE : SJ5EK7C
MODEL/YEAR : FORESTER 2.0I-L AWD CVT
ENGINE NO : FB20YD36834
CHASSIS NO : JF1SJ5KC5JG107854
MILEAGE : 1 KM
DATE IN : 16/01/2021
LIABILITY : 0.00
EXCESS CLAUSE : 0.00
ESTIMATE BY : JEFF TEH TENG CHUEN
ACCIDENT DATE : 16/01/2021

Print Date : 16/01/2021
Print Time : 18:52:46

Veh No: 14 Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

ED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SLZ2892A

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	SPG	TO SUPPLY & INSTALL FRONT SPORTY GRILLE	50.00	30
2	ZZ/001	TO REPAIR AND REPLACE FRONT BUMPER, FRONT BONNET, FRONT BOTH SIDE FENDER, ENERGY ABSORBER, FRONT	2800.00	1120 @560
3	ZZ/002	UNDERSPOILER AND FRONT SUPPORT PANEL		
4	ZZ/003	TO RESPRAY FRONT BONNET, FRONT BUMPER, FRONT BOTH SIDE FENDER, FRONT BUMPER BEAM AND FRONT SUPPORT	3520.00	840 @40
5	ZZ/004	PANEL		
6	ZZ/005	TO CONDUCT FRONT LIGHTING SYSTEM TEST	100.00	80
7	ZZ/006	TO CONDUCT FRONT HEADLAMP WASHER TEST	100.00	60
8	ZZ/007	SUNDRIES	50.00	20
9	ZZ/008	TO SUPPLY AND REPLACE FRONT LICENSE PLATE WITH CASING	55.00	64 ✓
TOTAL LABOUR CHARGES			6675.00	

ENTERPRISES PTE. LTD.

ROAD

59097

LIST FOR ACCIDENT VEHICLE REGN NO SLZ2892A

DAMAGED PARTS & PRICES

S/NO	PARTS DESCRIPTION	PARTS NUMBER	NETT	LIST	S/NETT	S/LIST REMARKS
1	RAD PNL COMPL RPR ?	53029SG0019P	360.00			
2	FRT FENDER RH X	57120SG0209P	270.00			
3	FRT FENDER LH X	57120SG0309P	270.00			
4	HOOD F CPL bl ✓	57229SG0009P	882.00			
5	BRKT CORNER F RH u ✓	57707SG000	36.00			
6	BRKT CORNER F LH u ✓	57707SG010	36.00			
7	BUMPER COVER FRT (FOR HL/W) de ✓	57709SG011	594.00			
8	BACK BEAM CPL F ?	57711SG0009P	288.00			
9	ENERGY ABSOR F ?	57722SG020	126.00			
10	COVER HOOK F SP de ?	57731SG070	5.40			
11	COVER FOG F SP RH de ?	57731SG080	43.20			
12	COVER FOG F SP LH X	57731SG090	43.20			
13	COVER SD F SP RH ms ✓	57731SG120	12.60			
14	COVER SD F SP LH X	57731SG130	12.60			
15	LAMP ASSY HEAD EOF RIGHT SIDE ?	84002SG222	2380.00			
16	LAMP ASSY HEAD EOF LH ca ✓	84002SG232	2380.00			
17	FOG LAMP ASSY F *2 ?	84501AJ060	544.00			
18	BRKT F FOG ASSY RH ?	84927SG020	19.80			
19	BRKT F FOG ASSY LH ?	84927SG030	19.80			
20	NOZZLE H L WASHERRH de ca ✓	(SUPP) 86636SG361	79.20			
21	NOZZLE H L WASHERLH ?	86636SG371	79.20			
22	NOZZLE COVER ASSYRH ms ✓	86636SG380EN	54.00			
23	NOZZLE COVER ASSYLH ms ✓	86636SG390EN	54.00			
24	BRKT GRILLE LWR NA cut ✓	91165SG000	21.60			
25	ORNAMENT F ms ✓	93013SG050	68.40			

Truck / Trailer or

ad Cost:

FOR ACCIDENT VEHICLE REGN NO SLZ2892A

PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
6 FRONT GRILLE <i>scr</i>	J1010SG101	1200.00			
27 FORESTER 2.0I-S KIT FRONT UNDER SPOILER (TCS) <i>cr</i>	TCS-FJ8-FL-002	1396.00			
SUB TOTAL		11275.00	0.00	0.00	0.00
LESS DISCOUNT (NETT-20 %)		2255.00	0.00	0.00	0.00
GRAND TOTAL		9020.00	0.00	0.00	0.00
OVERALL TOTAL		9020.00			

LEGEND: REMARKS(OK) = APPROVED, REMARKS(X) = NOT APPROVED

Truck / Trailer or
Type: motor

Cost:

ERPRISES PTE. LTD.

0AD

9097

OF ESTIMATE FOR VEHICLE REGN NO SLZ2892A

LABOUR CHARGES	6620.00
AL SPARE PARTS CHARGES	9020.00

GRAND TOTAL	15640.00 *

* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	Rasul - 4p 90010068
SURVEYED DATE	:	22/01/2021 @ 1120
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00 5 days
LIABILITY	:	0.00
REMARKS	:	EXCESS: TBA

REMARKS
Resurvey before paint

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Type: M.Car / M.Cycle / Bus / Van / Light Truck / Trailer or

Truck / Trailer or

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	13/01/2021 15:56 (SGT)
Date of Accident	13/01/2021 07:25 (SGT)
Exact Location of Accident	AYE, Singapore
Additional Location Information	TOWARDS TUAS
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLZ2982A
-----------------------------	----------

INSURED/POLICYHOLDER

Is company?	No
Name Of Registered Owner	WONG KOK WAH
NRIC No	SXXXX830Z
Email Address	kwwong3580@yahoo.com.sg
Mobile Phone No	(Phone) +65-98386487
Alternative Phone No	+65-98386487

VEHICLE PARTICULARS

Manufacturer	Subaru
Model	Forester
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Private car

INSURANCE COMPANY

Name of Insurance Company	United Overseas Insurance
Type of Coverage	Comprehensive
Fleet Policy	No
Policy Number	DHOM110167641901
Cover Note Number	-

DRIVER

Name of Driver	WONG KOK WAH
NRIC No	SXXXX830Z

Driving Pass
Experience

03/08/1977
43 YEARS AND 5 MONTHS
Male
(Phone) +65-98386487
+65-98386487
kwwong3580@yahoo.com.sg
BLK 20 JALAN MEMBINA #15-42

Number
Phone Number
Address
Address complement
Postcode

164020
Yes
-
No
-
-

Is the driver the policyholder?
If No, Relationship of the Driver with the Insured
Does Driver Own Other Vehicles?
Vehicle Registration Number of Other Vehicle Owned by Driver
Insurance Company of Other Vehicle Owned by Driver

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident Collision - Head to Rear
Weather Conditions Clear
Road Surface Dry

OTHER INFORMATION

Was any foreign vehicle involved in the accident? No
Number of vehicles involved in the accident 2
Was anybody injured in the Accident? No
Was any injured conveyed to hospital by ambulance? -
Was any other material or property damaged? Yes
Number of Passengers (Including Driver) 1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? No

DETAILS OF POLICE ACTION

Was the accident reported to the police? No
Was notice of intended Prosecution given? No
If yes, against whom? -

CIRCUMSTANCES OF ACCIDENT

ON 13TH JAN 2021 AT ABOUT 07:25 HRS I WAS TRAVELLING ALONG AYE TOWARDS JURONG AND AFTER AYE SPEED CAMERA. I WAS TRAVELLING BEHIND 3RD PARTY VEHICLE ALONG LANE 1. I SAW THE 3RD PARTY VEHICLE BRAKE LIGHT LIGHTED AND UNABLE TO STOP OR BRAKE ON TIME. I REAR ENDED THE 3RD PARTY VAN BEHIND. BOTH OF US CHANGE PARTICULAR, TELEPHONE AND TOOK PICTURES OF THE INCIDENT, BOTH OF US MOVED ON OUR JOURNEY.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No
Was there any audio recorded? No

DETAILS OF OTHER VEHICLE PROPERTY

Vehicle Registration Number GBE8118S
Vehicle Manufacturer Mercedes
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Commercial vehicle
Name of Driver LI ZHENG HUA
Passport No/FIN FXXXXX017X

TOYOTA PRIMS SQR H.B. HUN c.c. 1718


Make:

NS/ITP RES/OD RES/EVA/INV/INV


SKETCH PLAN


IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that:
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

 13/1/21
Policyholder's Signature / Date &
Time 1:50 pm
Sketch Plan

Driver's Signature (If driver is not the policyholder) / Date
& Time

 13/1/2021
Witnessed by Reporting Centre
Personnel




Describe Circumstances of the Accident


On 13th Jan 2021 I was travelling along A16 towards Tursay and after
my speed camera. I was travelling behind the 3rd party
vehicle along lane 1. I saw the 3rd party vehicle brake light lit and
unable to stop or brake in time. I rear ended the 3rd party van
behind.
Both of us exchanged particulars, telephone and took pictures of the incident.
Both of us noted on our journey.

Declaration

We declare the foregoing particulars are true in every respect.

 13/1/21
Policyholder's Signature / Date &
Time 1510 hrs

Driver's Signature (if driver is not the policyholder) / Date
& Time

 13/01/2021
Witnessed by Reporting Centre
Personnel

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Singapore NRIC
Owner ID:	830Z
Vehicle No.:	SLZ2892A
Vehicle to be Exported:	No
Intended Deregistration Date:	25 Jan 2021
Vehicle Make:	SUBARU
Vehicle Model:	FORESTER 2.0i-L CVT AWD 5R
Primary Colour:	Grey
Manufacturing Year:	2018
Engine No.:	FB20YD36834
Chassis No.:	JF15J5KC5JG107854
Maximum Power Output:	110.0 kW (147 bhp)
Open Market Value:	\$13,612.00
Original Registration Date:	27 Apr 2018
First Registration Date:	27 Apr 2018
Transfer Count:	0
Actual ARF Paid:	\$13,612.00
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	26 Apr 2028
PARF Rebate Amount:	\$10,209.00
COE Expiry Date:	26 Apr 2028
COE Category:	B - Car above 1600cc or 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$37,010.00
COE Rebate Amount:	\$26,842.00
Total Rebate Amount:	\$37,051.00

The information contained herein is correct as at 25 Jan 2021

OK

carmart.com/used_cars/info.php?ID=954173&DL=2397

Subaru Forester 2.0i-L Sunroof

Overview

Financial

Accessories

Similar

Research

Photos

Map



STARISE AUTOMOBILE

Member of



Accredited by



Price	\$80,800		
Depreciation ⓘ	\$10,110 /yr View models with similar depre	Reg Date	22-May-2018 (7yrs 3mths 26days COE left)
Mileage	39,596 km (14.8k /yr)	Manufactured ⓘ	2018
Road Tax ⓘ	\$1,208 /yr	Transmission	Auto
Dereg Value ⓘ	\$37,506 as of today (change)	OMV ⓘ	\$13,584
COE ⓘ	\$38,389	ARF ⓘ	\$13,584
Engine Cap	1,995 cc	Power	110.0 kW (147 bhp)
Curb Weight ⓘ	1,591 kg	No. of Owners ⓘ	1
Type of Vehicle	SUV		

Features

Responsive 2.0L Boxer Engine At 148BHP, AWD, SI-Drive, Linear Tronic CVT Gearbox, Paddle Shifters, Dual Zone Aircon, Rain Sensing, Cruise Control View specs of the Subaru Forester (2013-2019)