

COMFORTDELGRO ENGINEERING PTE LTD
REPAIR ESTIMATE

ALG CPT / JN
Date: 18.01.2021
Time: 11:58:45
Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305448710
REGN NO : SHIA2253Z
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 06.08.2019
DATE/TIME IN : 18.01.2021 08:55
ACCIDENT DATE : 17.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-3813-G	IONIQVC EMBLEM-BLUE DRIVE	1	26.60	20.00	21.28	na	
0002	04-01-0104-0574-G	IONIQVC PANEL-FENDER LH#	1	588.80	20.00	471.04	Ry	
0003	04-01-0104-2534-G	IONIQV2&3 COVER-FR BUMPER	1	430.90	20.00	344.72	de	803.90
0004	03-01-0104-2061-G	IONIQV1&3 CAP ASSY-WHEEL	1	346.40	20.00	277.12	ant	643.12

SUB-TOTAL : 1,114.16

JOB NATURE

0000	PB	PANEL BEATING	800.00	525	
0001	SP	SPRAYPAINT CHARGE	600.00	500	
0002	20-00	TUFF COAT ON AFFECTED PARTS.	50.00	X nm	1055
0003	17-01	CHECK ALL LIGHTING	50.00	30	workable
SUB-TOTAL : 1,500.00					81698.12

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanphir 1749 5745 "2 days" *
"wp" 18/1/21 C 5pm
p/p Resurvey before paint
Tanphir C/LK Auto con