



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924		Ref: CS/AGI21000814/Aqd3n2 Date: 29/03/2021	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SMC 1237H	Veh. Inspected	SJA 4895J
Policy No.		Coverage (\$)	0.00
Claim No.	C10008680/KY	Excess (\$)	0.00
Assign From	IVY RATILLA	Assign Date	18/01/2021
2. Vehicle Particulars & Condition			
Make & Model	SUZUKI SWIFT	c.c	1490
Engine No.	HIDDEN	Year of Reg.	2007
Chassis No.	JSAEZC21500407234	Colour	RED
Odometer	243226 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/55 R15	FIRENZA	6 mm
L/H Front Tyre	195/55 R15	FIRENZA	6 mm
R/H Rear Tyre	195/55 R15	FIRENZA	6 mm
L/H Rear Tyre	195/55 R15	FIRENZA	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	12/01/2021	Inspection Date	18/01/2021
Survey held at	CAS GARAGE PTE LTD NO. 1 KAKI BUKIT AVE 6, #02-22 AUTOBAY 417883 KAKI BUKIT		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	