

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305448714 Via Fax : EMAIL
Date : 18-1-21 Your Insured : SJZ 1972A
Time of Fax : _____ Date of Acc : 16-1-21

Attn: Motor Claims Department ALG

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH

A6293B

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties-involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

♦ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811
♦ <u>Jumani Bin Masudin</u>	<u>Tel: 6214 8315 or HP: 9635 5305</u>
♦ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546
♦ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006

} **jumanibm@cdge.com.sg**
Fax no. 6546 8156

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

COMFORTDELGRO ENGINEERING

member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 609286

20 Ulu Pandan Singapore 340499

24 Senoko Loop Singapore 758156

7 Sungai Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 768732

Date/Time: 18.01.2021 13:41

Page: 1

Team: ARC Repair TP(CLS0)1

JOB CARD

Sales Order:

JC NO.: 305448714

FORMER COMFORT TRANSPORTATION PTE LTD MS 7010045 FORMER NO. 383 SIN MING DRIVE ADDRESS Singapore SINGAPORE 575717 65508755 (R) (O) (P)	REGN NO. SHA6393B MAKE: HYUNDAI MODEL IONIQ(G3) YR OF MANUF. 16.01.2020 CHASSIS CODE KMHC851CVLU188182	MILEAGE FUEL E.....1/2.....F DATE/TIME IN 18.01.2021 10:45 TARGET DATE COMPLETION DATE/TIME:
--	---	--

OUNT CARD NO.

JOB DESCRIPTION


Accident Date: 16.01.2021
NATURE: 3P 16.01.2021

S/NO

LABOR CODE

DESCRIPTION

FRONT



RECEIVED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Redemption Slip

Exit Pass

No.: **SHA6393B**

JU AIG

Vehicle No.:

SHA6393B

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305448714
REGN NO : SHA6393B
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 16.01.2020
DATE/TIME IN : 18.01.2021 10:45
ACCIDENT DATE : 16.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 28-01-0103-0003-A	(I40)FRT DOOR LOGO SONATA	1	N	75.00	0.00	75.00
0002 28-01-9999-2023-A	APP LOGO REAR DOOR L/R CT	1	N	80.00	0.00	80.00
0003 04-01-0104-0592-G	IONIQVC PANEL ASSY-FRONT	1		1,797.20	20.00	1,437.76
0004 04-01-0104-0595-G	IONIQVC PANEL ASSY-REAR D	1		1,789.90	20.00	1,431.92

SUB-TOTAL : 3,024.68

JOB NATURE

0000 PB	PANEL BEATING	400.00
0001 SP	SPRAYPAINT CHARGE - ROCKER PANEL	800.00
0002 L	TRANSFER DOOR PART	240.00

SUB-TOTAL : 1,440.00

TOTAL : 4,464.68

MVA NAME & SIGNATURE
DATE :

AUTHORISED : YES / NO
SURVEYOR NAME & SIGNATURE
DATE :