

COMFORTDELGRO ENGINEERING

ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969

Our Ref : 305498774
Date : 18-1-21
Time of Fax : _____
Via Fax : email
Your Insured : SHUA 10314
Date of Acc : 16-1-21

Attn: Motor Claims Department all

Dear Sirs

SURVEY OF CLIENT'S DAMAGED VEHICLE REG NO. SH D 44505

Our client has engaged us to repair the above vehicle and submit claims against the other party/parties involved in the accident.

In accordance to the motor claims framework, we hereby request your presence at 59 Loyang Drive, Singapore 508969 to survey our client's damaged vehicle.

Enclosed, please find:

- i) Our initial estimate of repairs of the damaged vehicle;
- ii) Accident report made by our client.

I would appreciate it if you could call us to arrange for the survey of the vehicle:

◆ Lim Kwok Eng	Tel: 6214 8355 or HP: 9824 0811	} jumanibm@cdge.com.sg Fax no. 6546 8156
◆ <u>Jumani Bin Masudin</u>	Tel: 6214 8315 or HP: 9635 5305	
◆ Lim Tien Siong	Tel: 6214 8398 or HP: 9635 8546	
◆ Chiang Liat Choon	Tel: 6214 8314 or HP: 9296 6006	

→ If we do not hear from you within the next 48 hours, we shall deem that you have waived your rights to survey our client's vehicle and we shall proceed to engage independent surveyor without further reference to you. We henceforth reserve our rights to claim for Loss of Use and Loss of Rental during any delayed period of this survey arrangement.

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a Motor Surveyor appointed by the Insurance company.

Thank you.

Yours faithfully

For Vice President
Taxi Accident Repair

member of COMFORTDELGRO

Date/Time: 18.01.2021 15:34

Page : 1

Team: ARC Repair TP(CLSO)1

JOB CARD

Sales Order: 4054699

JC NO.: 305448774

FORMER AS FORMER NO RESS (R) (P)	COMFORT TRANSPORTATION PTE LTD 7010045 383 SIN MING DRIVE Singapore SINGAPORE 575717 65508755	REGN NO: SHD4450S MAKE: HYUNDAI MODEL: IONIQ(G3) YR OF MANU: 25.10.2019 CHASSIS CODE: KMHC851CVLU187367	MILEAGE FUEL E.....1/2.....F DATE/TIME IN: 17.01.2021 10:00 TARGET DATE COMPLETION DATE/TIME:
---	--	--	---

COUNT CARD NO.


JOB DESCRIPTION

Accident Date: 16.01.2021

NATURE: 3P 16.01.2021

S/NO	LABOR CODE
000040	PB
000050	SP
000060	20-00

DESCRIPTION
 PANEL BEATING
 SPRAYPAINT CHARGE
 TUFF COAT ON AFFECTED PARTS



WORKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

pledgement Slip

Exit Pass

No.:

SHD4450S

Vehicle No.:

SHD4450S

f Service Advisor

Signature/Date

Name of Service Advisor

Date

turned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

Date: 18.01.2021

REPAIR ESTIMATE

Time: 15:29:29

Page: 1

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305448774
REGN NO : SHD4450S
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G3)
DATE OF REGN : 25.10.2019
DATE/TIME IN : 17.01.2021 10:00
ACCIDENT DATE : 16.01.2021

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0104-0573-G	IONIQVC PANEL-FENDER RH#	1	588.80	20.00	471.04
0002 04-01-0104-2534-G	IONIQV2&3 COVER-FR BUMPER	1	430.90	20.00	344.72
0003 04-01-0104-3913-G	IONIQVC EMBLEM-BLUE DRIVE	1	26.60	20.00	21.28

SUB-TOTAL : 837.04

JOB NATURE

0000 PB	PANEL BEATING	800.00
0001 SP	SPRAYPAINT CHARGE	600.00
0002 20-00	TUFF COAT ON AFFECTED PARTS.	50.00

SUB-TOTAL : 1,450.00

TOTAL : 2,287.04

AUTHORISED : YES / NO

MVA NAME & SIGNATURE

SURVEYOR NAME & SIGNATURE

DATE :

DATE :